

**VINÇOTTE vzw**

Certified inspection body | External service for technical inspections at the workplace

Registered Office : Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium

VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC : GEBABEBB

Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium • phone: +32 2 674 57 11 • brussels@vincotte.be

Original



040 - INSP

Our References

Report n° : AUD/10/14446048/00/EN

Contract Ref. : 0001011189/3000

Your References

Ref.: Brief ref. : WBE/ADB dd 04/11/09 04112009

Intervention data

Area : AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit : 25.04.2023

Performed by : DE MAEYER STEIN (5907)

AED Rent nv

Bedrijvenpark De Veert, 12
2830 Willebroek
BELGIUM

**Periodical report concerning your
Common lifting equipment and similar equipment.**

Conclusions founded in this report:

- 12 The material was not available during inspection, or could only be partly inspected, without an additional inspection we cannot ensure the safe use of the material
- 19 The material can be used

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

Important note

Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.

When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.

Please also ensure you that other regulations are not applicable for you.

Ing. J. WINDEY
General Manager

If you wish to make a complaint or comment on our services, please contact us on www.vincotte.be, section Contact.

BASIS AND CONTENTS OF OUR INSPECTIONS

1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection. The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

3. INSPECTION PROGRAMS (non exhaustive listing)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories, lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.

Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.

Our electrical inspection department is available for carrying out the measurements.

Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.

Inspections marked "" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.

- Remarks: these result in the obligation to remedy the situation as soon as possible.

- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.

This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.

Please also make sure there are no other applicable regulations.

We are at your disposal if you require any further information.

DESCRIPTION OF THE DEVICES

FINDINGS

MOBILE ELEVATING WORK PLATFORMS

ELECTRIC LIFT ALP

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-041572

Make : ALP LIFT

Client number of the equipment : 008

Type : PH1300 EU1

Year of manufacture : 2004

Maximum load : 135KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORMS

Serial number : 24-041573

Make : ALP LIFT

Client number of the equipment : 009

Type : PH1300 EU1

Year of manufacture : 2004

Maximum load : 135KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-051631

Make : ALP LIFT

Client number of the equipment : 010

Type : PHC940 EU1

Year of manufacture : 2005

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-051632

Make : ALP LIFT

Client number of the equipment : 011

Type : PHC940 EU1

Year of manufacture : 2005

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-061737

Make : ALP LIFT

Client number of the equipment : 013

Type : PHC940 EU1

Year of manufacture : 2006

Maximum load : 140KG

(see next page)

DESCRIPTION OF THE DEVICES

Number of persons : 1

FINDINGS

*** Conditions and operation inspection (07.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (04.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-061738
Make : ALP LIFT
Client number of the equipment : 014
Type : PHC940 EU1
Year of manufacture : 2006
Maximum load : 140KG
Number of persons : 1

*** Conditions and operation inspection (07.2023)**

*** Mechanism and structure inspection (04.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-061741
Make : ALP LIFT
Client number of the equipment : 016
Type : PHC1300 EU1
Year of manufacture : 2006
Maximum load : 135KG
Number of persons : 1

*** Conditions and operation inspection (07.2023)**

*** Mechanism and structure inspection (04.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-071800
Make : ALP LIFT
Client number of the equipment : 017
Type : PHC940 EU1
Year of manufacture : 2007
Maximum load : 140KG
Number of persons : 1

*** Conditions and operation inspection (07.2023)**

Not inspected: not presented.

*** Mechanism and structure inspection (04.2024)**

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-081861
Make : ALP LIFT
Client number of the equipment : 019
Type : PHC940 EU1
Year of manufacture : 2008
Maximum load : 140KG

(see next page)

DESCRIPTION OF THE DEVICES

Number of persons : 1

FINDINGS

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-071849

Make : ALP LIFT

Client number of the equipment : 020

Type : PHC940 EU1

Year of manufacture : 2007

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-081858

Make : ALP LIFT

Client number of the equipment : 021

Type : PHC940 EU1

Year of manufacture : 2008

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-081864

Make : ALP LIFT

Client number of the equipment : 023

Type : PHC1200 EU1

Year of manufacture : 2008

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM

Serial number : 24-091963

Make : ALP LIFT

Client number of the equipment : 024

Type : PHC1200 EU1

Year of manufacture : 2009

Maximum load : 140KG

Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

(see next page)

DESCRIPTION OF THE DEVICES

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-091964
Make : ALP LIFT
Client number of the equipment : 025
Type : PHC1200 EU1
Year of manufacture : 2009
Maximum load : 140KG
Number of persons : 1

FINDINGS

** Conditions and operation inspection (07.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-091958
Make : ALP LIFT
Client number of the equipment : 026
Type : PHC940 EU1
Year of manufacture : 2009
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-091959
Make : ALP LIFT
Client number of the equipment : 027
Type : PHC940 EU1
Year of manufacture : 2009
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-091960
Make : ALP LIFT
Client number of the equipment : 028
Type : PHC940 EU1
Year of manufacture : 2009
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-091961
Make : ALP LIFT
Client number of the equipment : 029

(see next page)

DESCRIPTION OF THE DEVICES

Type : PHC940 EU1
Year of manufacture : 2009
Maximum load : 140KG
Number of persons : 1

FINDINGS

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-112030
Make : ALP LIFT
Client number of the equipment : 030
Type : PHC940 EU1
Year of manufacture : 2011
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-112031
Make : ALP LIFT
Client number of the equipment : 031
Type : PHC940 EU1
Year of manufacture : 2011
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-112032
Make : ALP LIFT
Client number of the equipment : 032
Type : PHC940 EU1
Year of manufacture : 2011
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-122090
Make : ALP LIFT
Client number of the equipment : 033
Type : PHC940
Year of manufacture : 2012
Maximum load : 140KG
Number of persons : 1

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Mobile elevating work platform other than articulated arm

(see next page)

DESCRIPTION OF THE DEVICES

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-122091
Make : ALP LIFT
Client number of the equipment : 034
Type : PHC940
Year of manufacture : 2012
Maximum load : 140KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-122093
Make : ALP LIFT
Client number of the equipment : 035
Type : PHC1200 EU1
Year of manufacture : 2016
Maximum load : 135KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 24-96839
Make : ALP LIFT
Client number of the equipment : 036
Type : PHC940 EU1
Maximum load : 140KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 9925
Make : ALP LIFT
Client number of the equipment : 037
Type : PHC940 EU1
Year of manufacture : 2016
Maximum load : 140KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 9925
Make : ALP LIFT
Client number of the equipment : 038
Type : PHC940 EU1
Year of manufacture : 2016
Maximum load : 140KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 9923

FINDINGS

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (04.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

DESCRIPTION OF THE DEVICES

Make : ALP LIFT
Client number of the equipment : 039
Type : PHC1200 EU1
Year of manufacture : 2016
Maximum load : 135KG
Number of persons : 1

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : 9924
Make : ALP LIFT
Client number of the equipment : 040
Type : PHC1200 EU1
Year of manufacture : 2016
Maximum load : 135KG
Number of persons : 1

SELF-DRIVE ELECTRIC LIFT ALP AMWP9.5

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : R06121H09
Make : ALP LIFT
Client number of the equipment : 006
Type : AMWP9.5
Year of manufacture : 2021
Maximum load : 125

Mobile elevating work platform other than articulated arm

Nature : MOBILE ELEVATING WORK PLATFORM
Serial number : R06121H10
Make : ALP LIFT
Client number of the equipment : 007
Type : AMWP9.5
Year of manufacture : 2021
Maximum load : 125

FINDINGS

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

Note: The positive test of load and/or moment sensing systems was executed on the date next mentioned. In accordance with the note GTO/TN/H/H/002, recognized by the FPS Employment, Labour and Social Dialogue, the load and/or moment sensing systems has to be retested the latest within one year. Date of test: 18/01/2023

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

** Conditions and operation inspection (07.2023)*

Note: The positive test of load and/or moment sensing systems was executed on the date next mentioned. In accordance with the note GTO/TN/H/H/002, recognized by the FPS Employment, Labour and Social Dialogue, the load and/or moment sensing systems has to be retested the latest within one year. Date of test: 18/01/2023

** Mechanism and structure inspection (04.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Total of the equipment inspected

19	10411001	Mobile work platf.no artic.arm
19	10411002	Mobile work platf.no artic.arm

Cond. & Oper.Insp. or Prev.
Mechanism&structure inspection

Total of the equipment not inspected



Report n° : AUD/10/14446048/00/EN
Contract Ref. : 0001011189/3000

12	10411001	Mobile work platf.no artic.arm
12	10411002	Mobile work platf.no artic.arm

Cond. & Oper.Insp. or Prev.
Mechanism&structure inspection