

**VINÇOTTE vzw**

Certified inspection body | External service for technical inspections at the workplace

Registered Office : Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium

VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC : GEBABEBB

Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium • phone: +32 2 674 57 11 • brussels@vincotte.be

Original



040 - INSP

Our References

Report n° : AUD/10/14530016/00/EN

Contract Ref. : 0001011189/38000

Your References

Ref.: Brief ref. : WBE/ADB dd 04/11/09 04112009

Intervention data

Area : AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit : 19.07.2023

Performed by : DE MAEYER STEIN (5907)

AED Rent nv

Bedrijvenpark De Veert, 12
2830 Willebroek
BELGIUM

**Periodical report concerning your
Common lifting equipment and similar equipment.**

Conclusions founded in this report:

- 150 The material was not available during inspection, or could only be partly inspected, without an additional inspection we cannot ensure the safe use of the material
- 50 The material can be used

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

Important note

Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.

When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.

Please also ensure you that other regulations are not applicable for you.

Ing. J. WINDEY
General Manager



If you wish to make a complaint or comment on our services, please contact us on www.vincotte.be, section Contact.

BASIS AND CONTENTS OF OUR INSPECTIONS

1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection.

The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

3. INSPECTION PROGRAMS (non exhaustive listing)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories, lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.

Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.

Our electrical inspection department is available for carrying out the measurements.

Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.

Inspections marked "" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.

- Remarks: these result in the obligation to remedy the situation as soon as possible.

- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.

This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.

Please also make sure there are no other applicable regulations.

We are at your disposal if you require any further information.

DESCRIPTION OF THE DEVICES

FINDINGS

ELECTRIC HOISTS CHAINMASTER 1250KG D8+

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M00089
Make : CHAINMASTER
Client number of the equipment : 001
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14416
Make : CHAINMASTER
Client number of the equipment : 002
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14417
Make : CHAINMASTER
Client number of the equipment : 003
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14418
Make : CHAINMASTER
Client number of the equipment : 004
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14419
Make : CHAINMASTER
Client number of the equipment : 005
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M14420
Make : CHAINMASTER
Client number of the equipment : 006
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14421
Make : CHAINMASTER
Client number of the equipment : 007
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14422
Make : CHAINMASTER
Client number of the equipment : 008
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14423
Make : CHAINMASTER
Client number of the equipment : 009
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14424
Make : CHAINMASTER
Client number of the equipment : 010
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14425

(see next page)

Make : CHAINMASTER
Client number of the equipment : 011
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14426
Make : CHAINMASTER
Client number of the equipment : 012
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14427
Make : CHAINMASTER
Client number of the equipment : 013
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14428
Make : CHAINMASTER
Client number of the equipment : 014
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14429
Make : CHAINMASTER
Client number of the equipment : 015
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M14430
Make : CHAINMASTER
Client number of the equipment : 016
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14431
Make : CHAINMASTER
Client number of the equipment : 017
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14635
Make : CHAINMASTER
Client number of the equipment : 018
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14636
Make : CHAINMASTER
Client number of the equipment : 019
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14637
Make : CHAINMASTER
Client number of the equipment : 020
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)



Nature : MOTOR-DRIVEN HOIST
Serial number : M14638
Make : CHAINMASTER
Client number of the equipment : 021
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14639
Make : CHAINMASTER
Client number of the equipment : 022
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14640
Make : CHAINMASTER
Client number of the equipment : 023
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14641
Make : CHAINMASTER
Client number of the equipment : 024
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14642

(see next page)

Make : CHAINMASTER
Client number of the equipment : 025
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14636
Make : CHAINMASTER
Client number of the equipment : 026
Type : SB6.1/17P
Year of manufacture : 43
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14644
Make : CHAINMASTER
Client number of the equipment : 027
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14645
Make : CHAINMASTER
Client number of the equipment : 028
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14646
Make : CHAINMASTER
Client number of the equipment : 029
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14647

(see next page)

Make : CHAINMASTER
Client number of the equipment : 030
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14648
Make : CHAINMASTER
Client number of the equipment : 031
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14649
Make : CHAINMASTER
Client number of the equipment : 032
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14650
Make : CHAINMASTER
Client number of the equipment : 033
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M14651
Make : CHAINMASTER
Client number of the equipment : 034
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M14652

Make : CHAINMASTER

Client number of the equipment : 035

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M14653

Make : CHAINMASTER

Client number of the equipment : 036

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M14654

Make : CHAINMASTER

Client number of the equipment : 037

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18941

Make : CHAINMASTER

Client number of the equipment : 038

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18942

Make : CHAINMASTER

Client number of the equipment : 039

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18943
Make : CHAINMASTER
Client number of the equipment : 040
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18944
Make : CHAINMASTER
Client number of the equipment : 041
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18945
Make : CHAINMASTER
Client number of the equipment : 042
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18946
Make : CHAINMASTER
Client number of the equipment : 043
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18947
Make : CHAINMASTER
Client number of the equipment : 044
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18948
Make : CHAINMASTER
Client number of the equipment : 045
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18949
Make : CHAINMASTER
Client number of the equipment : 046
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18950
Make : CHAINMASTER
Client number of the equipment : 047
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18951
Make : CHAINMASTER
Client number of the equipment : 048
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18952
Make : CHAINMASTER
Client number of the equipment : 049
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18953
Make : CHAINMASTER
Client number of the equipment : 050
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18954
Make : CHAINMASTER
Client number of the equipment : 051
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18955
Make : CHAINMASTER
Client number of the equipment : 052
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18956
Make : CHAINMASTER
Client number of the equipment : 053
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18957

(see next page)

Make : CHAINMASTER
Client number of the equipment : 054
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18958
Make : CHAINMASTER
Client number of the equipment : 055
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18959
Make : CHAINMASTER
Client number of the equipment : 056
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18960
Make : CHAINMASTER
Client number of the equipment : 057
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18961
Make : CHAINMASTER
Client number of the equipment : 058
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18962
Make : CHAINMASTER
Client number of the equipment : 059
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18963
Make : CHAINMASTER
Client number of the equipment : 060
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18964
Make : CHAINMASTER
Client number of the equipment : 061
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18965
Make : CHAINMASTER
Client number of the equipment : 062
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18966
Make : CHAINMASTER
Client number of the equipment : 063
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18967
Make : CHAINMASTER
Client number of the equipment : 064
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18968
Make : CHAINMASTER
Client number of the equipment : 065
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18969
Make : CHAINMASTER
Client number of the equipment : 066
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18970
Make : CHAINMASTER
Client number of the equipment : 067
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18971
Make : CHAINMASTER
Client number of the equipment : 068
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18972
Make : CHAINMASTER
Client number of the equipment : 069
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18973
Make : CHAINMASTER
Client number of the equipment : 070
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18974
Make : CHAINMASTER
Client number of the equipment : 071
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18975
Make : CHAINMASTER
Client number of the equipment : 072
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18976

Make : CHAINMASTER

Client number of the equipment : 073

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18977

Make : CHAINMASTER

Client number of the equipment : 074

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18978

Make : CHAINMASTER

Client number of the equipment : 075

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M18979

Make : CHAINMASTER

Client number of the equipment : 076

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18980
Make : CHAINMASTER
Client number of the equipment : 077
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18981
Make : CHAINMASTER
Client number of the equipment : 078
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18982
Make : CHAINMASTER
Client number of the equipment : 079
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18983
Make : CHAINMASTER
Client number of the equipment : 080
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18984
Make : CHAINMASTER
Client number of the equipment : 081
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18985

(see next page)

Make : CHAINMASTER
Client number of the equipment : 082
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18986
Make : CHAINMASTER
Client number of the equipment : 083
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18987
Make : CHAINMASTER
Client number of the equipment : 084
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18988
Make : CHAINMASTER
Client number of the equipment : 085
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18989
Make : CHAINMASTER
Client number of the equipment : 086
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Nature : MOTOR-DRIVEN HOIST
Serial number : M18990
Make : CHAINMASTER
Client number of the equipment : 087
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18991
Make : CHAINMASTER
Client number of the equipment : 088
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18992
Make : CHAINMASTER
Client number of the equipment : 089
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18993
Make : CHAINMASTER
Client number of the equipment : 090
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18994
Make : CHAINMASTER
Client number of the equipment : 091
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18995
Make : CHAINMASTER
Client number of the equipment : 092
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18996
Make : CHAINMASTER
Client number of the equipment : 093
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18997
Make : CHAINMASTER
Client number of the equipment : 094
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18998

(see next page)

Make : CHAINMASTER
Client number of the equipment : 095
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M18999
Make : CHAINMASTER
Client number of the equipment : 096
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M19000
Make : CHAINMASTER
Client number of the equipment : 097
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M19001
Make : CHAINMASTER
Client number of the equipment : 098
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M23573
Make : CHAINMASTER
Client number of the equipment : 099
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M23574
Make : CHAINMASTER
Client number of the equipment : 100
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28286
Make : CHAINMASTER
Client number of the equipment : 101
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28287
Make : CHAINMASTER
Client number of the equipment : 102
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28288
Make : CHAINMASTER
Client number of the equipment : 103
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28289

Make : CHAINMASTER

Client number of the equipment : 104

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28290

Make : CHAINMASTER

Client number of the equipment : 105

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28291

Make : CHAINMASTER

Client number of the equipment : 106

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28292

Make : CHAINMASTER

Client number of the equipment : 107

Type : SB6.1/17P

Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28293
Make : CHAINMASTER
Client number of the equipment : 108
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28294
Make : CHAINMASTER
Client number of the equipment : 109
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28295
Make : CHAINMASTER
Client number of the equipment : 110
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28296

(see next page)



Make : CHAINMASTER
Client number of the equipment : 111
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28297
Make : CHAINMASTER
Client number of the equipment : 112
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28298
Make : CHAINMASTER
Client number of the equipment : 113
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28299
Make : CHAINMASTER
Client number of the equipment : 114
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28300

(see next page)



Make : CHAINMASTER
Client number of the equipment : 115
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28301
Make : CHAINMASTER
Client number of the equipment : 116
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28302
Make : CHAINMASTER
Client number of the equipment : 117
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28303
Make : CHAINMASTER
Client number of the equipment : 118
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28304
Make : CHAINMASTER
Client number of the equipment : 119
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28305
Make : CHAINMASTER
Client number of the equipment : 120
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28306
Make : CHAINMASTER
Client number of the equipment : 121
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28307
Make : CHAINMASTER
Client number of the equipment : 122
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28308

(see next page)



Make : CHAINMASTER
Client number of the equipment : 123
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28309
Make : CHAINMASTER
Client number of the equipment : 124
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28310
Make : CHAINMASTER
Client number of the equipment : 125
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28311
Make : CHAINMASTER
Client number of the equipment : 126
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28312

(see next page)

Make : CHAINMASTER
Client number of the equipment : 127
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28313
Make : CHAINMASTER
Client number of the equipment : 128
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28314
Make : CHAINMASTER
Client number of the equipment : 129
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28315
Make : CHAINMASTER
Client number of the equipment : 130
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28316
Make : CHAINMASTER
Client number of the equipment : 131
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28317

Make : CHAINMASTER

Client number of the equipment : 132

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28318

Make : CHAINMASTER

Client number of the equipment : 133

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28319

Make : CHAINMASTER

Client number of the equipment : 134

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28320

Make : CHAINMASTER

Client number of the equipment : 135

Type : SB6.1/17P

Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28321
Make : CHAINMASTER
Client number of the equipment : 136
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28322
Make : CHAINMASTER
Client number of the equipment : 137
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28323
Make : CHAINMASTER
Client number of the equipment : 138
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28324
Make : CHAINMASTER
Client number of the equipment : 139
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28325
Make : CHAINMASTER
Client number of the equipment : 140
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28326
Make : CHAINMASTER
Client number of the equipment : 141
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28327
Make : CHAINMASTER
Client number of the equipment : 142
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28328

(see next page)



Make : CHAINMASTER
Client number of the equipment : 143
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28329
Make : CHAINMASTER
Client number of the equipment : 144
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28330
Make : CHAINMASTER
Client number of the equipment : 145
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28331
Make : CHAINMASTER
Client number of the equipment : 146
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28332

(see next page)



Make : CHAINMASTER
Client number of the equipment : 147
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28333
Make : CHAINMASTER
Client number of the equipment : 148
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28334
Make : CHAINMASTER
Client number of the equipment : 149
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28335
Make : CHAINMASTER
Client number of the equipment : 150
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28336

(see next page)

Make : CHAINMASTER
Client number of the equipment : 151
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28337
Make : CHAINMASTER
Client number of the equipment : 152
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28338
Make : CHAINMASTER
Client number of the equipment : 153
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28339
Make : CHAINMASTER
Client number of the equipment : 154
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28340
Make : CHAINMASTER
Client number of the equipment : 155
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28341
Make : CHAINMASTER
Client number of the equipment : 156
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28342
Make : CHAINMASTER
Client number of the equipment : 157
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28343
Make : CHAINMASTER
Client number of the equipment : 158
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28344

(see next page)



Make : CHAINMASTER
Client number of the equipment : 159
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28345
Make : CHAINMASTER
Client number of the equipment : 160
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28346
Make : CHAINMASTER
Client number of the equipment : 161
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28347
Make : CHAINMASTER
Client number of the equipment : 162
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28348

(see next page)



Make : CHAINMASTER
Client number of the equipment : 163
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28349
Make : CHAINMASTER
Client number of the equipment : 164
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28350
Make : CHAINMASTER
Client number of the equipment : 165
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28351
Make : CHAINMASTER
Client number of the equipment : 166
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28352

(see next page)

Make : CHAINMASTER
Client number of the equipment : 167
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28353
Make : CHAINMASTER
Client number of the equipment : 168
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28354
Make : CHAINMASTER
Client number of the equipment : 169
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28355
Make : CHAINMASTER
Client number of the equipment : 170
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28356

(see next page)



Make : CHAINMASTER
Client number of the equipment : 171
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28357
Make : CHAINMASTER
Client number of the equipment : 172
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28358
Make : CHAINMASTER
Client number of the equipment : 173
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28359
Make : CHAINMASTER
Client number of the equipment : 174
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28360

(see next page)



Make : CHAINMASTER
Client number of the equipment : 175
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28361
Make : CHAINMASTER
Client number of the equipment : 176
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28362
Make : CHAINMASTER
Client number of the equipment : 177
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28363
Make : CHAINMASTER
Client number of the equipment : 178
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*
Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28364

(see next page)

Make : CHAINMASTER
Client number of the equipment : 179
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28365
Make : CHAINMASTER
Client number of the equipment : 180
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28366
Make : CHAINMASTER
Client number of the equipment : 181
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28367
Make : CHAINMASTER
Client number of the equipment : 182
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28368
Make : CHAINMASTER
Client number of the equipment : 183
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28369
Make : CHAINMASTER
Client number of the equipment : 184
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28370
Make : CHAINMASTER
Client number of the equipment : 185
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28371
Make : CHAINMASTER
Client number of the equipment : 186
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28372

(see next page)

Make : CHAINMASTER
Client number of the equipment : 187
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28373
Make : CHAINMASTER
Client number of the equipment : 188
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28374
Make : CHAINMASTER
Client number of the equipment : 189
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28375
Make : CHAINMASTER
Client number of the equipment : 190
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28376
Make : CHAINMASTER
Client number of the equipment : 191
Type : SB6.1/17P
Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

** Mechanism and structure inspection (08.2024)*

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28377

Make : CHAINMASTER

Client number of the equipment : 192

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28378

Make : CHAINMASTER

Client number of the equipment : 193

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28379

Make : CHAINMASTER

Client number of the equipment : 194

Type : SB6.1/17P

Year of manufacture : 2022

Maximum load : 1250KG

** Conditions and operation inspection (11.2023)*

Not inspected: not presented.

** Mechanism and structure inspection (08.2024)*

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST

Serial number : M28380

Make : CHAINMASTER

Client number of the equipment : 195

Type : SB6.1/17P

Year of manufacture : 2022

(see next page)

Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28381
Make : CHAINMASTER
Client number of the equipment : 196
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28382
Make : CHAINMASTER
Client number of the equipment : 197
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28382
Make : CHAINMASTER
Client number of the equipment : 198
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28384

(see next page)



Make : CHAINMASTER
Client number of the equipment : 199
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**
Not inspected: not presented.

*** Mechanism and structure inspection (08.2024)**
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST
Serial number : M28385
Make : CHAINMASTER
Client number of the equipment : 200
Type : SB6.1/17P
Year of manufacture : 2022
Maximum load : 1250KG

*** Conditions and operation inspection (11.2023)**

*** Mechanism and structure inspection (08.2024)**

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Total of the equipment inspected

50	10396001	Motor-driven hoist
50	10396002	Motor-driven hoist

Cond. & Oper.Insp. or Prev.
Mechanism&structure inspection

Total of the equipment not inspected

150	10396001	Motor-driven hoist
150	10396002	Motor-driven hoist

Cond. & Oper.Insp. or Prev.
Mechanism&structure inspection