

#### VINÇOTTE vzw

Certified inspection body I External service for technical inspections at the workplace Registered Office: Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC: GEBABEBB

Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium • phone: +32 2 674 57 11 • brussels@vincotte.be



Our References

Report n°: AUD/10/14446054/00/EN Contract Ref.: 0001011189/6000

Your References

Ref.: Brief ref.: WBE/ADB dd 04/11/09 04112009

Intervention data

Area: AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit: 25.04.2023

Performed by: DE MAEYER STEIN (5907)

Periodical report concerning your Common lifting equipment and similar equipment.

AED Rent nv

2830 Willebroek

**BELGIUM** 

Bedrijvenpark De Veert, 12

# Conclusions founded in this report:

- 140 The material was not available during inspection, or could only be partly inspected, without an additional inspection we cannot ensure the safe use of the material
- 95 The material can be used

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

# Important note

Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.

When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.

Please also ensure you that other regulations are not applicable for you.

Ing. J. WIMDEY General Manager

If you wish to make a complaint or comment on our services, please contact us on www.vincotte.be, section Contact.

Date of issue: 02/05/2023 Page: 1/54



Contract Ref.: 0001011189/6000

## BASIS AND CONTENTS OF OUR INSPECTIONS

#### 1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

#### 2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection. The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

## 3. INSPECTION PROGRAMS (non exhaustive lisiting)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories,lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.

Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.

Our electrical inspection department is available for carrying out the measurements.

Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

## 4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.

Inspections marked "\*" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.
- Remarks: these result in the obligation to remedy the situation as soon as possible.
- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.

This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.

Please also make sure there are no other applicable regulations.

We are at you disposal if you require any further information.

Date of issue: 02/05/2023 Page: 2/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

#### **FINDINGS**

# **MANUAL HOISTS 1000KG**

## **MANUAL HOISTS 1000KG - VERLINDE**

Manual hoist

Nature: MANUAL HOIST

Serial number: CHA 33605-10274

Make: VERLINDE

Client number of the equipment: 250

Type: PHD

Year of manufacture: 2006 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

Serial number: CHA 06143-10141

Make: VERLINDE

Client number of the equipment: 252

Type: PHD

Year of manufacture: 2006 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0602 0295

Make: VERLINDE

Client number of the equipment: 297

Type: VHR3-1000/10 Year of manufacture: 2007 Maximum load: 1000KG

Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0602 0222

Make: VERLINDE

Client number of the equipment: 341

Type: VHR3-1000/10 Year of manufacture: 2006 Maximum load: 1000KG

Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

(see next page)

Date of issue: 02/05/2023 Page: 3/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Nature: MANUAL HOIST Serial number: MHV 0602 0260

Make: VERLINDE

Client number of the equipment: 342

Type: VHR3-1000/10 Year of manufacture: 2006 Maximum load: 1000KG

# **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0602 0224

Make: VERLINDE

Client number of the equipment: 353

Type: VHR3-1000/10 Year of manufacture: 2006 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0602 0277

Make: VERLINDE

Client number of the equipment: 356

Type: VHR3-1000/10 Year of manufacture: 2006 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0706 367

Make: VERLINDE

Client number of the equipment: 376

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG

- Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 4/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: MHV 0706 350

Make: VERLINDE

Client number of the equipment: 379

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : MHV 0709 194

Make: VERLINDE

Client number of the equipment: 419

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG \* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : MHV 0706 315

Make: VERLINDE

Client number of the equipment: 428

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG \* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : MHV 0706 332

Make: VERLINDE

Client number of the equipment: 449

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : MHV 0706 385

Make: VERLINDE

Client number of the equipment: 461

Type: VHR3-1000/10

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 02/05/2023 Page: 5/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2007 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0709 195

Make: VERLINDE

Client number of the equipment: 483

Type: VHR3-1000/10 Year of manufacture: 2007 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: MHV 0709 197

Make: VERLINDE

Client number of the equipment: 485

Type: VHR3-1000/10 Year of manufacture: 2007 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.

Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: MHV 081 360

Make: VERLINDE

Client number of the equipment: 528

Type: VHR3-1000/10 Year of manufacture: 2008 Maximum load: 1000KG

- Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Manual hoist

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 6/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number : 47711 Make : VERLINDE

Client number of the equipment: 554

Type: VHR3-1000/10 Year of manufacture: 2011 Maximum load: 1000KG

# \* Condition

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 47754 Make : VERLINDE

Client number of the equipment: 559

Type: VHR3-1000/10
Year of manufacture: 2011
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 89425-58916

Make: VERLINDE

Client number of the equipment: 567

Type: VHR3-10/1000 Year of manufacture: 2012 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- Manual hoist
- Nature : MANUAL HOIST Serial number : 89425-58920

Make: VERLINDE

Client number of the equipment: 569

Type: VHR3-10/1000 Year of manufacture: 2012 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 19142105991

Make: VERLINDE

Client number of the equipment: 575

Type: VHR3-10/1000

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 02/05/2023 Page: 7/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2014 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 19142105935

Make: VERLINDE

Client number of the equipment: 578

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 19142105967

Make: VERLINDE

Client number of the equipment: 583

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 24052127525

Make: VERLINDE

Client number of the equipment: 597

Type: VHR3-10/1000 Year of manufacture: 2015 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 8/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 24052127526

Make: VERLINDE

Client number of the equipment: 598

Type: VHR3-10/1000 Year of manufacture: 2015 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 24052127559

Make: VERLINDE

Client number of the equipment: 609

Type: VHR3-10/1000 Year of manufacture: 2015 Maximum load: 1000KG

/ear of manufacture : 2015 the

Manual hoist

Nature: MANUAL HOIST Serial number: 24052127575

Make: VERLINDE

Client number of the equipment: 616

Type : VHR3-10/1000 Year of manufacture : 2015 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 24052127587

Make: VERLINDE

Client number of the equipment: 623

Type: VHR3-10/1000 Year of manufacture: 2015 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 19142105932

Make: VERLINDE

Client number of the equipment: 631

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist (see next page)

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 9/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 19142105949

Make: VERLINDE

Client number of the equipment: 635

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 19142105950

Make: VERLINDE

Client number of the equipment: 636

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 19142105953

Make: VERLINDE

Client number of the equipment: 638

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 19142105966

Make: VERLINDE

Client number of the equipment: 641

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist (see

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 10/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 19142105993

Make: VERLINDE

Client number of the equipment: 645

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 19142106002

Make: VERLINDE

Client number of the equipment: 650

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 19142106014

Make: VERLINDE

Client number of the equipment: 652

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 19142106029

Make: VERLINDE

Client number of the equipment: 654

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
  Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 11/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 19410106530

Make: VERLINDE

Client number of the equipment: 664

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Manual hoist

Nature : MANUAL HOIST Serial number : 19410106537

Make: VERLINDE

Client number of the equipment: 669

Type: VHR3-10/1000 Year of manufacture: 2014 Maximum load: 1000KG

#### Manual hoist

Nature : MANUAL HOIST Serial number : 27895137002

Make: VERLINDE

Client number of the equipment: 677

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 27895137010

Make: VERLINDE

Client number of the equipment: 681

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
  Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Manual hoist

Nature : MANUAL HOIST Serial number : 27895137011

Make: VERLINDE

Client number of the equipment: 682

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 12/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 27895137012

Make: VERLINDE

Client number of the equipment: 683

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 27895137033

Make: VERLINDE

Client number of the equipment: 690

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 27895137037

Make: VERLINDE

Client number of the equipment: 694

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Manual hoist

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 13/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 27895137040

Make: VERLINDE

Client number of the equipment: 696

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145143

Make: VERLINDE

Client number of the equipment: 701

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **Manual hoist**

Nature : MANUAL HOIST Serial number : 32351145147

Make: VERLINDE

Client number of the equipment: 706

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

## Manual hoist

Nature : MANUAL HOIST Serial number : 32351145157

Make: VERLINDE

Client number of the equipment: 707

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

# Manual hoist

Nature: MANUAL HOIST Serial number: 32351145137

Make: VERLINDE

Client number of the equipment: 708

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

## **FINDINGS**

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist (see next page)

Date of issue: 02/05/2023 Page: 14/54



Not inspected: not presented.

Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Nature : MANUAL HOIST Serial number : 32351145146

Make: VERLINDE

Client number of the equipment: 709

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

# \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

**FINDINGS** 

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145135

Make: VERLINDE

Client number of the equipment: 710

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

# \* Conditions and operation inspection (07.2023)

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145149

Make: VERLINDE

Client number of the equipment: 712

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 32351145163

Make: VERLINDE

Client number of the equipment: 713

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist (see next page)

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 15/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 32351145164

Make: VERLINDE

Client number of the equipment: 714

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145143

Make: VERLINDE

Client number of the equipment: 715

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145139

Make: VERLINDE

Client number of the equipment: 716

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 32351145133

Make: VERLINDE

Client number of the equipment: 717

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

## Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 16/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 32351145142

Make: VERLINDE

Client number of the equipment: 718

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145117

Make: VERLINDE

Client number of the equipment: 722

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145115

Make: VERLINDE

Client number of the equipment: 723

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 32351145108

Make: VERLINDE

Client number of the equipment: 726

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 17/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number : 32351145111

Make: VERLINDE

Client number of the equipment: 727

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 32351145110

Make: VERLINDE

Client number of the equipment: 728

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 32351145170

Make: VERLINDE

Client number of the equipment: 729

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 32351145168

Make: VERLINDE

Client number of the equipment: 730

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

## Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145167

Make: VERLINDE

Client number of the equipment: 731

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 18/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145122

Make: VERLINDE

Client number of the equipment: 734

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145173

Make: VERLINDE

Client number of the equipment: 735

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 32351145172

Make: VERLINDE

Client number of the equipment: 737

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 19/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 33417146558

Make: VERLINDE

Client number of the equipment: 741

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 33417146568

Make: VERLINDE

Client number of the equipment: 744

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 33417146573

Make: VERLINDE

Client number of the equipment: 751

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 33417146543

Make: VERLINDE

Client number of the equipment: 754

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature : MANUAL HOIST Serial number : 33417146540

Make: VERLINDE

Client number of the equipment: 756

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 20/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2016 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

abnormalities were found when inspecting

Manual hoist

Nature : MANUAL HOIST Serial number : 33417146560

Make: VERLINDE

Client number of the equipment: 758

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

**Manual hoist** 

Nature : MANUAL HOIST Serial number : 32351145148

Make: VERLINDE

Client number of the equipment: 762

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 32351145159

Make: VERLINDE

Client number of the equipment: 764

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145118

Make: VERLINDE

Client number of the equipment: 767

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 21/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2016 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145127

Make: VERLINDE

Client number of the equipment: 768

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 32351145154

Make: VERLINDE

Client number of the equipment: 770

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 32351145151

Make: VERLINDE

Client number of the equipment: 771

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Manual hoist

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 22/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 32351145128

Make: VERLINDE

Client number of the equipment: 773

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

# **FINDINGS**

\* Conditions and operation inspection (07.2023)

Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145125

Make: VERLINDE

Client number of the equipment: 774

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 32351145134

Make: VERLINDE

Client number of the equipment: 775

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

## **Manual hoist**

Nature: MANUAL HOIST Serial number: 32351145126

Make: VERLINDE

Client number of the equipment: 776

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 23136125637

Make: VERLINDE

Client number of the equipment: 777

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 23/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 23186125643

Make: VERLINDE

Client number of the equipment: 778

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 23186125649

Make: VERLINDE

Client number of the equipment: 779

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 23186125680

Make: VERLINDE

Client number of the equipment: 782

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 23186125530

Make: VERLINDE

Client number of the equipment: 784

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Nature: MANUAL HOIST

Manual hoist

Date of issue: 02/05/2023 Page: 24/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number : 23186125611

Make: VERLINDE

Client number of the equipment: 785

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 23186125632

Make: VERLINDE

Client number of the equipment: 789

Type: VHR3 1000/10
Year of manufacture: 2016
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 23186125635

Make: VERLINDE

Client number of the equipment: 791

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 23186125683

Make: VERLINDE

Client number of the equipment: 795

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 25/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 23186125689

Make: VERLINDE

Client number of the equipment: 796

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature : MANUAL HOIST Serial number : 23186125693

Make: VERLINDE

Client number of the equipment: 797

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: 23186125694

Make: VERLINDE

Client number of the equipment: 798

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 23186125692

Make: VERLINDE

Client number of the equipment: 800

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
  Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist (s

Nature : MANUAL HOIST Serial number : 23186125697

Make: VERLINDE

Client number of the equipment: 801

Type: VHR3 1000/10

(see next page)

Date of issue: 02/05/2023 Page: 26/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2016 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 23186125701

Make: VERLINDE

Client number of the equipment: 802

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 23186125703

Make: VERLINDE

Client number of the equipment: 803

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 23186125705

Make: VERLINDE

Client number of the equipment: 804

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Manual hoist

Nature: MANUAL HOIST

Date of issue: 02/05/2023 Page: 27/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 23186125706

Make: VERLINDE

Client number of the equipment: 805

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### \* Meci

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

**FINDINGS** 

The material can be used, no abnormalities were found when inspecting the material

## Manual hoist

Nature : MANUAL HOIST Serial number : 23186125707

Make: VERLINDE

Client number of the equipment: 806

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 23186125709

Make: VERLINDE

Client number of the equipment: 807

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

## Manual hoist

Nature: MANUAL HOIST Serial number: 23186125716

Make: VERLINDE

Client number of the equipment: 811

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 23186125716

Make: VERLINDE

Client number of the equipment: 812

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 28/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 23186125717

Make: VERLINDE

Client number of the equipment: 813

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 23136125800

Make: VERLINDE

Client number of the equipment: 814

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 25064132199

Make: VERLINDE

Client number of the equipment: 816

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 25064132484

Make: VERLINDE

Client number of the equipment: 817

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

## Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 29/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Serial number: 27895137031

Make: VERLINDE

Client number of the equipment: 821

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 27895137039

Make: VERLINDE

Client number of the equipment: 822

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: 27895137055

Make: VERLINDE

Client number of the equipment: 823

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 231361257598

Make: VERLINDE

Client number of the equipment: 825

Type: VHR3 1000/10 Year of manufacture: 2016 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature: MANUAL HOIST Serial number: 38896157809

Make: VERLINDE

Client number of the equipment: 828

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

(see next page)

Date of issue: 02/05/2023 Page: 30/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Nature : MANUAL HOIST Serial number : 38896157815

Make: VERLINDE

Client number of the equipment: 829

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### Manual hoist

Nature : MANUAL HOIST Serial number : 38896157818

Make: VERLINDE

Client number of the equipment: 830

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### Manual hoist

Nature: MANUAL HOIST Serial number: 38896157839

Make: VERLINDE

Client number of the equipment: 831

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

## Manual hoist

Nature: MANUAL HOIST Serial number: 38896157842

Make: VERLINDE

Client number of the equipment: 833

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

## Manual hoist

Nature: MANUAL HOIST Serial number: 38896157843

Make: VERLINDE

Client number of the equipment: 834

Type: VHR3 1000/10

#### **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

#### Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 02/05/2023 Page: 31/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2018 Maximum load : 1000KG

## **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### Manual hoist

Nature : MANUAL HOIST Serial number : 38896157845

Make: VERLINDE

Client number of the equipment: 835

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### **Manual hoist**

Nature : MANUAL HOIST Serial number : 38896157846

Make: VERLINDE

Client number of the equipment: 836

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

Not inspected: not presented.

- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.
- \_\_\_\_

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature: MANUAL HOIST Serial number: 38896157847

Make: VERLINDE

Client number of the equipment: 837

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Manual hoist

Nature: MANUAL HOIST Serial number: 38896157872

Make: VERLINDE

Client number of the equipment: 842

Type: VHR3 1000/10

(see next page)

Date of issue: 02/05/2023 Page: 32/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2018 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 38896157874

Make: VERLINDE

Client number of the equipment: 844

Type: VHR3 1000/10
Year of manufacture: 2018
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature : MANUAL HOIST Serial number : 38896157875

Make: VERLINDE

Client number of the equipment: 845

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

Nature : MANUAL HOIST Serial number : 41687165264

Make: VERLINDE

Client number of the equipment: 847

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 33/54



Contract Ref.: 0001011189/6000

# **DESCRIPTION OF THE DEVICES**

Serial number: 41687165276

Make: VERLINDE

Client number of the equipment: 849

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Nature: MANUAL HOIST Serial number: 41687165288

#### **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no

Conclusion

The material can be used, no

abnormalities were found when inspecting the material

#### Manual hoist

Manual hoist

Make: VERLINDE

Type: VHR3 1000/10

Year of manufacture: 2018 Maximum load: 1000KG

Nature: MANUAL HOIST Serial number: 41687165289

Make: VERLINDE

Client number of the equipment: 852

Client number of the equipment: 851

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

abnormalities were found when inspecting the material

Conclusion

## Manual hoist

Nature: MANUAL HOIST Serial number: 41687165291

Make: VERLINDE

Client number of the equipment: 854

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### **Manual hoist**

Nature: MANUAL HOIST Serial number: 41687165292

Make: VERLINDE

Client number of the equipment: 855

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

## Manual hoist

Nature: MANUAL HOIST Serial number: 41687165296

Make: VERLINDE

Client number of the equipment: 858

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Manual hoist

(see next page)

Date of issue: 02/05/2023 Page: 34/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Nature : MANUAL HOIST Serial number : 41687165297

Make: VERLINDE

Client number of the equipment: 859

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

# Manual hoist

Nature : MANUAL HOIST Serial number : 41687165298

Make: VERLINDE

Client number of the equipment: 860

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### **Manual hoist**

Nature : MANUAL HOIST Serial number : 41687165299

Make: VERLINDE

Client number of the equipment: 861

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

## Manual hoist

Nature : MANUAL HOIST Serial number : 41687165300

Make: VERLINDE

Client number of the equipment: 862

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

# **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Manual hoist

Nature : MANUAL HOIST Serial number : 41687165304

Make: VERLINDE

Client number of the equipment: 863

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 35/54



Contract Ref.: 0001011189/6000

## **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2018 Maximum load: 1000KG

## **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### Manual hoist

Nature: MANUAL HOIST Serial number: 41687165305

Make: VERLINDE

Client number of the equipment: 864

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 41687165306

Make: VERLINDE

Client number of the equipment: 865

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no

Conclusion

abnormalities were found when inspecting the material

## **Manual hoist**

Nature: MANUAL HOIST Serial number: 41687165311

Make: VERLINDE

Client number of the equipment: 866

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Manual hoist

Nature: MANUAL HOIST Serial number: 41687165317

Make: VERLINDE

Client number of the equipment: 867

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 36/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Serial number: 41687165327

Make: VERLINDE

Client number of the equipment: 868

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165328

Make: VERLINDE

Client number of the equipment: 869

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023) \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

**Manual hoist** 

Nature: MANUAL HOIST Serial number: 41687165329

Make: VERLINDE

Client number of the equipment: 870

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165331

Make: VERLINDE

Client number of the equipment: 872

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165333

Make: VERLINDE

Client number of the equipment: 873

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

**Manual hoist** 

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 37/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Serial number: 41687165335

Make: VERLINDE

Client number of the equipment: 875

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165336

Make: VERLINDE

Client number of the equipment: 876

Type: VHR3 1000/10
Year of manufacture: 2018
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- Manual hoist
- Nature: MANUAL HOIST Serial number: 38896157849

Make: VERLINDE

Client number of the equipment: 877

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 38896157850

Make: VERLINDE

Client number of the equipment: 879

Type: VHR3 1000/10
Year of manufacture: 2018
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 38896157852

Make: VERLINDE

Client number of the equipment: 880

Type: VHR3 1000/10

(see next page)

Date of issue: 02/05/2023 Page: 38/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Maximum load: 1000KG **Manual hoist** 

Manual hoist

Make: VERLINDE

Type: VHR3 1000/10

Nature: MANUAL HOIST Serial number: 39879160047

Nature: MANUAL HOIST Serial number: 38896160052

Year of manufacture: 2018

Make: VERLINDE

Client number of the equipment: 882

Client number of the equipment: 881

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Manual hoist

Nature: MANUAL HOIST Serial number: 38896160054

Make: VERLINDE

Client number of the equipment: 883

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature: MANUAL HOIST Serial number: 39879160056

Make: VERLINDE

Client number of the equipment: 884

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 39/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Year of manufacture : 2018 Maximum load : 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

abnormalities were found when inspecting

#### Manual hoist

Nature : MANUAL HOIST Serial number : 38896160059

Make: VERLINDE

Client number of the equipment: 885

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

# \* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

Conclusion

the material

# Manual hoist

Nature : MANUAL HOIST Serial number : 38896160060

Make: VERLINDE

Client number of the equipment: 886

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG abnormalities were found when inspecting the material

### Manual hoist

Nature: MANUAL HOIST Serial number: 38896160066

Make: VERLINDE

Client number of the equipment: 888

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG \* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 38896160067

Make: VERLINDE

Client number of the equipment: 889

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Manual hoist

(see next page)

Date of issue: 02/05/2023 Page: 40/54



Not inspected: not presented.

Not inspected: not presented.

Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Nature: MANUAL HOIST Serial number: 38896160068

Make: VERLINDE

Client number of the equipment: 890

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

# Conclusion

**FINDINGS** 

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 39879160078

Make: VERLINDE

Client number of the equipment: 894

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Conditions and operation inspection (07.2023)

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 39879160081

Make: VERLINDE

Client number of the equipment: 897

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Manual hoist

Nature: MANUAL HOIST Serial number: 39896160082

Make: VERLINDE

Client number of the equipment: 898

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

### Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 41/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Serial number: 39879160083

Make: VERLINDE

Client number of the equipment: 899

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Nature: MANUAL HOIST Serial number: 39879160084

#### **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

#### Manual hoist

Manual hoist

Make: VERLINDE

Type: VHR3 1000/10

Year of manufacture: 2018 Maximum load: 1000KG

Nature: MANUAL HOIST Serial number: 39879160087

Make: VERLINDE

Client number of the equipment: 901

Client number of the equipment: 900

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

### Manual hoist

Nature: MANUAL HOIST Serial number: 39879160089

Make: VERLINDE

Client number of the equipment: 902

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### **Manual hoist**

Nature: MANUAL HOIST Serial number: 39879160091

Make: VERLINDE

Client number of the equipment: 904

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 42/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Serial number: 39879160093

Make: VERLINDE

Client number of the equipment: 906

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Nature: MANUAL HOIST Serial number: 39879160095

#### **FINDINGS**

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Maximum load : 1000KG Manual hoist

Manual hoist

Make: VERLINDE

Type: VHR3 1000/10

Year of manufacture: 2018

Nature : MANUAL HOIST Serial number : 39879160096

Make: VERLINDE

Client number of the equipment: 908

Client number of the equipment: 907

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: 39879160097

Make: VERLINDE

Client number of the equipment: 909

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Manual hoist

Nature: MANUAL HOIST Serial number: 38896157876

Make: VERLINDE

Client number of the equipment: 910

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST

(see next page)

Date of issue: 02/05/2023 Page: 43/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Serial number: 41687165251

Make: VERLINDE

Client number of the equipment: 911

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 41687165255

Make: VERLINDE

Client number of the equipment: 912

Type: VHR3 1000/10
Year of manufacture: 2018
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature : MANUAL HOIST Serial number : 41687165303

Make: VERLINDE

Client number of the equipment: 914

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : 38896157 Make : VERLINDE

Client number of the equipment: 915

Type: VHR3 1000/10
Year of manufacture: 2018
Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature : MANUAL HOIST Serial number : 41687165310

Make: VERLINDE

Client number of the equipment: 917

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 44/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Maximum load: 1000KG **Manual hoist** 

Manual hoist

Make: VERLINDE

Type: VHR3 1000/10

Nature: MANUAL HOIST Serial number: 41687165313

Nature: MANUAL HOIST Serial number: 41687165319

Year of manufacture: 2018

Make: VERLINDE

Client number of the equipment: 921

Client number of the equipment: 918

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Manual hoist

Nature: MANUAL HOIST Serial number: 41687165320

Make: VERLINDE

Client number of the equipment: 922

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

#### Manual hoist

Nature: MANUAL HOIST Serial number: 41687165324

Make: VERLINDE

Client number of the equipment: 923

Type: VHR3 1000/10

Date of issue: 02/05/2023 Page: 45/54



Contract Ref.: 0001011189/6000

### **DESCRIPTION OF THE DEVICES**

Year of manufacture: 2018 Maximum load: 1000KG

#### **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165325

Make: VERLINDE

Client number of the equipment: 924

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Manual hoist

Nature: MANUAL HOIST Serial number: 41687165356

Make: VERLINDE

Client number of the equipment: 926

Type: VHR3 1000/10 Year of manufacture: 2018 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# **MANUAL HOISTS 1000KG - YALE**

Manual hoist

Nature: MANUAL HOIST Serial number: S19022091X

Make: YALE

Client number of the equipment: 001

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

- **Manual hoist**
- Nature: MANUAL HOIST Serial number: S19022092X

Make: YALE

Client number of the equipment: 002

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Manual hoist (see next page)

Date of issue: 02/05/2023 Page: 46/54



Contract Ref.: 0001011189/6000

Nature: MANUAL HOIST Serial number: S19022093X

Make: YALE

Client number of the equipment: 003

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no

Conclusion

Manual hoist Nature: MANUAL HOIST Serial number: S19022094X

Make: YALE

Client number of the equipment: 004

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

The material can be used, no abnormalities were found when inspecting the material

**Manual hoist** Nature: MANUAL HOIST Serial number: S19022097X

Make: YALE

Client number of the equipment: 005

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022098X

Make: YALE

Client number of the equipment: 006

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022099X

Make: YALE

Client number of the equipment: 007

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022100X

Make: YALE

Client number of the equipment: 008

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist Nature: MANUAL HOIST Serial number: S19022101X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 47/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 009

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist

Nature : MANUAL HOIST Serial number : S19022102X

Make: YALE

Client number of the equipment: 010

Year of manufacture : 2020 Maximum load : 1000KG

Type: VSE III

Manual hoist
Nature: MANUAL HOIST
Serial number: \$19022105X

Make: YALE

Client number of the equipment: 011

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022106X

Make: YALE

Client number of the equipment: 012

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022107X

Make: YALE

Client number of the equipment: 013

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022108X

Make: YALE

Client number of the equipment: 014

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

**Manual hoist** 

Nature : MANUAL HOIST Serial number : S19022109X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 48/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 015

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist

Nature : MANUAL HOIST Serial number : S19022110X

Make: YALE

Client number of the equipment: 016

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022111X

Make: YALE

Client number of the equipment: 017

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022112X

Make: YALE

Client number of the equipment: 018

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022113X

Make: YALE

Client number of the equipment: 019

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022114X

Make: YALE

Client number of the equipment: 020

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022115X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 49/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 021

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist

Nature: MANUAL HOIST Serial number: S19022118X

Make: YALE

Client number of the equipment: 022

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022119X

Make: YALE

Client number of the equipment: 023

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022120X

Make: YALE

Client number of the equipment: 024

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022124X

Make: YALE

Client number of the equipment: 025

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022125X

Make: YALE

Client number of the equipment: 026

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022126X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 50/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 027

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist

Nature: MANUAL HOIST Serial number: S19022128X

Make: YALE

Client number of the equipment: 028

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022129X

Make: YALE

Client number of the equipment: 029

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022131X

Make: YALE

Client number of the equipment: 030

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022133X

Make: YALE

Client number of the equipment: 031

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022135X

Make: YALE

Client number of the equipment: 032

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022136X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 51/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 033

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist

Nature : MANUAL HOIST Serial number : S19022138X

Make: YALE

Client number of the equipment: 034

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG The material can be used, no abnormalities were found when inspecting the material

Manual hoist

Nature : MANUAL HOIST Serial number : S19022141X

Make: YALE

Client number of the equipment: 035

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022146X

Make: YALE

Client number of the equipment: 036

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022147X

Make: YALE

Client number of the equipment: 037

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist

Nature : MANUAL HOIST Serial number : S19022149X

Make: YALE

Client number of the equipment: 038

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist
Nature: MANUAL HOIST
Serial number: \$19022150X

Make: YALE

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 02/05/2023 Page: 52/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 039

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023) \* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023) \* Mechanism and structure inspection (04.2024)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conclusion

the material

Conclusion

the material

the material

Conclusion

Manual hoist

Nature: MANUAL HOIST Serial number: S19022151X

Make: YALE

Client number of the equipment: 040

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

The material can be used, no abnormalities were found when inspecting the material

abnormalities were found when inspecting

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022152X

Make: YALE

Client number of the equipment: 041

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

Manual hoist

Nature: MANUAL HOIST Serial number: S19022153X

Make: YALE

Client number of the equipment: 042

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022154X

Make: YALE

Client number of the equipment: 043

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

**Manual hoist** 

Nature: MANUAL HOIST Serial number: S19022155X

Make: YALE

Client number of the equipment: 044

Type: VSE III

Year of manufacture: 2020 Maximum load: 1000KG

the material

Manual hoist (see next page)

Nature: MANUAL HOIST Serial number: S19022156X

Make: YALE

Date of issue: 02/05/2023 Page: 53/54



Contract Ref.: 0001011189/6000

Client number of the equipment: 045

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Manual hoist\* Conditions and operation inspection (07.2023)Nature: MANUAL HOIST\* Mechanism and structure inspection (04.2024)

Make : YALE

Client number of the equipment: 046

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Serial number: S19022160X

The material can be used, no abnormalities were found when inspecting

Manual hoist Nature : MANUAL HOIST Serial number : S19022161X

Make: YALE

Client number of the equipment: 047

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG

Manual hoist
Nature: MANUAL HOIST
Serial number: \$19022164X

Make: YALE

Client number of the equipment: 048

Type: VSE III

Year of manufacture : 2020 Maximum load : 1000KG the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

# Total of the equipment inspected

95 10398001 Manual hoist Cond. & Oper.Insp. or Prev. 95 10398002 Manual hoist Mechanism&structure inspection

### Total of the equipment not inspected

140 10398001 Manual hoist Cond. & Oper.Insp. or Prev.
 140 10398002 Manual hoist Mechanism&structure inspection

Date of issue: 02/05/2023 Page: 54/54