

VINÇOTTE vzw

Certified inspection body I External service for technical inspections at the workplace Registered Office : Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium

VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC : GEBABEBB

Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium • phone: +32 2 674 57 11 • brussels@vincotte.be



Our References

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

Your References

Ref.: Brief ref.: WBE/ADB dd 04/11/09 04112009

Intervention data

Area: AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit: 27.04.2023

Performed by: DE MAEYER STEIN (5907)

> Periodical report concerning your Lifting accessories and similar equipment.

AED Rent nv

2830 Willebroek

BELGIUM

Bedrijvenpark De Veert, 12

Conclusions founded in this report:

The material was not available during inspection, or could only be partly inspected, without an additional inspection we cannot ensure the safe use of the material

1865 The material can be used

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

Important note

Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.

When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.

Please also ensure you that other regulations are not applicable for you.

Ing. J. WINDEY General Manager

If you wish to make a complaint or comment on our services, please contact us on www.vincotte.be, section Contact.

16/05/2023 Page: 1/1083 Date of issue:



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

BASIS AND CONTENTS OF OUR INSPECTIONS

1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection.

The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

3. INSPECTION PROGRAMS (non exhaustive lisiting)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories,lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.

Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.

Our electrical inspection department is available for carrying out the measurements.

Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.

Inspections marked "*" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.
- Remarks: these result in the obligation to remedy the situation as soon as possible.
- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.

This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.

Please also make sure there are no other applicable regulations.

We are at you disposal if you require any further information.

Date of issue: 16/05/2023 Page: 2/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

SLINGS SPANSET

SOFT STEELS 2000KG - 0.5M

Sling (cable/synthetic)

Nature : SLING Serial number : A001 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A002 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A003 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A005 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A006 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

FINDINGS

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 3/1083



DESCRIPTION OF THE DEVICES

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A007 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A008 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A009 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A010 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M

Sling (cable/synthetic)

Nature: SLING Serial number: A011 * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: Page: 4/1083 16/05/2023



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A013 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A014 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A015 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A016 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A018 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 5/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A019 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A020 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A021 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A022 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A023 Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 6/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A024 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A025 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A026 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A027 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A028 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 7/1083



DESCRIPTION OF THE DEVICES Length: 0,5M	FINDINGS * Conditions and operation inspection (07.2023) Conclusion
	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A029 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic) Nature: SLING Serial number: A030 Make: BENECA Year of manufacture: 2009	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The
Maximum load : 2000KG Length : 0,5M	material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A031 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A032 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A033 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 8/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A034 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A035 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A036 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A037 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A038 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A039 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A040 Make : BENECA

Year of manufacture: 2009

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 9/1083



DESCRIPTION OF THE DEVICES Maximum load : 2000KG	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Length: 0,5M	Conclusion
	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A041 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number: A042 Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Serial number : A043 Make : BENECA Year of manufacture : 2009 Maximum load : 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 0,5M Sling (cable/synthetic) Nature: SLING Serial number: A044 Make: BENECA	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting
Year of manufacture : 2009 Maximum load : 2000KG Length : 0,5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : A045	Not inspected: not presented. Conclusion
Make: BENECA Year of manufacture: 2009 Maximum load: 2000KG Length: 0,5M	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page : 10/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A046 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A047 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING Serial number : A048 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A049 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A050 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A138 (see next page)

Date of issue: 16/05/2023 Page: 11/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A254 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A293 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25401 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25402

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25403

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 12/1083



Serial number : 18/25409

Year of manufacture : 2018 Maximum load : 2000KG

Make : BENECA

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 0,5M	* Conditions and operation inspection (07.2023)
	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/25404 Make: BENECA Year of manufacture: 2018	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting
Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic) Nature: SLING Serial number: 18/25405	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no
Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic)	abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023)
Nature: SLING Serial number: 18/25406 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 0,5M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/25407 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/25408 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 0,5M Sling (cable/synthetic) Nature: SLING	(see next page)

Date of issue: 16/05/2023 Page: 13/1083



DESCRIPTION OF THE DEVICES

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25410

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25411

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25412

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25413

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25414

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/25415

Make: BENECA

Year of manufacture: 2018

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 14/1083



Maximum load: 2000KG

Sling (cable/synthetic)

Length: 0,5M

Nature: SLING

Date of issue:

16/05/2023

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Maximum load: 2000KG * Conditions and operation inspection (07.2023) Length: 0,5M Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/25416 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/25417 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/25418 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 0,5M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 18/25419 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Lenath: 0.5M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/25420 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 0,5M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/25421 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018

the material

(see next page)

Page: 15/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/25422

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25423

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25424

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25425

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25426

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25427

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25428

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 16/1083



DESCRIPTION OF THE DEVICES Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no
	abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25430	The material can be used, no
Make: BENECA	•
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25431	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 0,5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature: SLING	Conclusion
Serial number : 18/25432	
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25433	The material can be used, no
Make: BENECA	•
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25434	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 0,5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature: SLING	Conclusion
Serial number : 18/25435	
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	(see next page)
Nature : SLING	

Date of issue: 16/05/2023 Page: 17/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/25436

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25437

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25438

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25439

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25440

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25441

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25442

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 18/1083



DESCRIPTION OF THE DEVICES

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25443

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25444

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25445

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25446

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 18/25447

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25448

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 19/1083



Nature : SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 0,5M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25449	The material can be used, no
Make : BENECA	·
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25450	The material can be used, no
Make : BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25451 Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25452	
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25453	The material can be used, no
Make : BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25454	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	tile material
Length: 0,5M	(
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 20/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/25455

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25457

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25459

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25460

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25462

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25463

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25464

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 21/1083



DESCRIPTION OF THE DEVICES Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25465	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018 Maximum load : 2000KG	the material
Length: 0,5M	ino matorial
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25466	The meterial can be used no
Make: BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25468 Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25469	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 0,5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25470	
Make: BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic) Nature: SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number: 18/25471	Conclusion
Make : BENECA	
Year of manufacture : 2018	The material cannot be used anymore. The
Maximum load : 2000KG	material was not available during
Length: 0,5M	inspection, or could only be partially
	inspected, an additional inspection is
	required before re-service
Sling (cable/synthetic)	(see next nage)
omig (capie/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 22/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/25473

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25474

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25475

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25477

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25478

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25479

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25480

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 23/1083



Nature : SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 0,5M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25488	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG Length : 0,5M	tilo matorial
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25497	
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25498	The material can be used, no
Make : BENECA	•
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25499	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 0,5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25506	
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/25507	The material can be used, no
Make : BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	
Maximum load : 2000KG	the material
Length: 0,5M	
Sling (cable/synthetic)	(see next page)
DISTRICT : ST INII -	

Date of issue: 16/05/2023 Page: 24/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/25508

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic) Nature: SLING

Serial number: 18/25509

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25510

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING Serial number: 18/25511

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25512

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25513

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 0,5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25514

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 25/1083



DESCRIPTION OF THE DEVICES

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25516

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/25517

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

m load : 2000KG the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/25518

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

The material cannot be used anymore. The

abnormalities were found when inspecting

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/25519

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/25520

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : 04-001 (see next page)

Date of issue: 16/05/2023 Page: 26/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 06-004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-003 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-005 Make : BENECA

Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-008 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 27/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 07-009 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-010 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-011 Make : BENECA

Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-014 Make : BENECA

Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-015 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 28/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 07-017 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-018 Make : BENECA

Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-020 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-021 Make : BENECA

Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-023 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 29/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: 07-027 Make: BENECA Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 07-030 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 07-033 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 07-034 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 07-035 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 30/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 07-041 Make : BENECA Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 07-042 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 09-003 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 09-004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 09-006 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 31/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: 09-007 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 09-008 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 09-009 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 09-021 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 09-033 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 32/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 09-039 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 10-004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 10-008 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 0,5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 001 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 002 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 003

(see next page)

Date of issue: 16/05/2023 Page: 33/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 004

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 005

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 006

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature : SLING Not inspected: not presented.

Serial number : 2011 007 Conclusion

Year of manufacture: 2011

Maximum land : 2000KC

Maximum load : 2000KG

Length: 0.5M

Make: BENECA

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 008

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG (see next page)

Date of issue: 16/05/2023 Page: 34/1083



DESCRIPTION OF THE DEVICES Length: 0.5M	* Conditions and operation inspection (07.2023) Conclusion
	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : 2011 009 Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : 2011 010 Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 2011 011 Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 2011 014	Conclusion
Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 2011 015	Conclusion
Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	The material cannot be used anymore. The material was not available during inspection, or could only be partially
Lengur : 0.5M	inspection, or could only be partially inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page : 35/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 016

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 018

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 019

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 020

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 021

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 022

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 023

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 36/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 024

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 025

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 026

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 027

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 028

(see next page)

Date of issue: 16/05/2023 Page: 37/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 029

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 030

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 031

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 032

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 033

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 38/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: 2011 034

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 035

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 036

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 037 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 038 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 039

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 39/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 040 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 041

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 042

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 043

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 044

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 40/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 045

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 046

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 047

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 048

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 049

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 050

(see next page)

Date of issue: 16/05/2023 Page: 41/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 051

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 052

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 053

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 054

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 056

(see next page)

Date of issue: 16/05/2023 Page: 42/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 057

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 058

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 059

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 061

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 062

(see next page)

Date of issue: 16/05/2023 Page: 43/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 064

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 065

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 066

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 067

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 068

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 44/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 069

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 070

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 071

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 072

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 45/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 073

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 074

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 075

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 076

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 077

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 078

(see next page)

Date of issue: 16/05/2023 Page: 46/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 079

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 080

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

The material can be used, no

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 081

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 082

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 083

(see next page)

Date of issue: 16/05/2023 Page: 47/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 084

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 085

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 087

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 088

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 089

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 48/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 090

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 091

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 092

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 093

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 094

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 095

(see next page)

Date of issue: 16/05/2023 Page: 49/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 097

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 098

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 099

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 100

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 50/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 102

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 103

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 104

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 105

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 106

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 107

(see next page)

Date of issue: 16/05/2023 Page: 51/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 108

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 109

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 110

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 111

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 52/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 113

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 114

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 115

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 116

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 117

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 118

(see next page)

Date of issue: 16/05/2023 Page: 53/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 119

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 120

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 121

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 122

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 54/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 123

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 125

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 126

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 127

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 128

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 129

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 55/1083



DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 2011 130 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 0.5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 2011 131 Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG Length : 0.5M	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 2011 132 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 0.5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 2011 133 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 0.5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 2011 134 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 0.5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 2011 135 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 0.5M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material (see next page)

Date of issue: 16/05/2023 Page: 56/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 136

Make : BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 137

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 138

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 139

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 140

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 141

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or sould only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

required before re-service

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 57/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 142

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 144

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 146

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 147

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 148

(see next page)

Date of issue: 16/05/2023 Page: 58/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 149

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 150

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING Serial number : A12-003

Make : BENECA Year of manufacture : 2011 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A12-013 Make : BENECA

Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A12-015

Make: BENECA

Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 59/1083



Not inspected: not presented.

Nature: SLING

Serial number: A12-016 Make: BENECA

DESCRIPTION OF THE DEVICES

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A12-022 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING Serial number: A12-029

Make: BENECA

Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 001 Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 002

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

inspection, or could only be partially Length: 0.5M inspected, an additional inspection is

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 003

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

FINDINGS

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

required before re-service

Date of issue: 16/05/2023 Page: 60/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 004

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 005

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 006

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature : SLING

Serial number : A 13 050 007

Not inspected: not presented.

Conclusion

Serial number : A 13 050 007

Make : BENECA

Conclusion

Year of manufacture : 2013

Maximum load : 2000KG

Length: 0.5M

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 008

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 61/1083



DESCRIPTION OF THE DEVICES Length: 0.5M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion
	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : A 13 050 009 Make : BENECA Year of manufacture : 2013 Maximum load : 2000KG Length : 0.5M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number: A 13 050 010 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 0.5M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : A 13 050 011 Make : BENECA Year of manufacture : 2013 Maximum load : 2000KG Length : 0.5M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : A 13 050 012 Make : BENECA Year of manufacture : 2013 Maximum load : 2000KG Length : 0.5M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : A 13 050 013	Conclusion
Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 0.5M	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Page : 62/1083 Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 014

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 015

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 016

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 017

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 018

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 019

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 63/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 020

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 021

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic) * Cond

Nature : SLING

Serial number: A 13 050 022

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 023

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 024

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 025

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 64/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 026

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 027

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 028

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Serial number : A 13 050 029

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 030

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 031

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 65/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 032

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 033

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 034

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 035

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 036

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 038

Date of issue: 16/05/2023 Page: 66/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 039

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

Conclusion

the material

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

abnormalities were found when inspecting

required before re-service

The material can be used, no

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 040

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 041

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 042

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: A 13 050 043

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 044

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 67/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 045

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 046

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 047

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 048

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 049

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 050

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 68/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 051

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 052

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 053

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 054

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 055

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 69/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 056

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 057

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 058

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 059

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 060

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 061

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 70/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

equired belove

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 062

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 063

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 064

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 065

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 066

(see next page)

Date of issue: 16/05/2023 Page: 71/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 067

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 068

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 069

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 070

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Nature : SLING

Serial number: A 13 050 071

Date of issue: 16/05/2023 Page: 72/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 072

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 073

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 074

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 075

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 076

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 077

Date of issue: 16/05/2023 Page: 73/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 078

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 079

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 080

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 081

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 082

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 083

Make: BENECA

Year of manufacture: 2013

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 74/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 084

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 085

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 086

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 087

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 088

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 089

(see next page)

Date of issue: 16/05/2023 Page: 75/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 090

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

inspected, an additional inspection is

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 091

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 092

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 093

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 094

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 76/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 095

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 096

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 097

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 098

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 099

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 77/1083



Nature : SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Nature: SLING Serial number: A 13 050 100 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting
Length: 0.5M	the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number: A 13 050 101	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2013	the material
Maximum load : 2000KG	the material
Length: 0.5M	* Conditions and energtion inspection (07 2022)
Sling (cable/synthetic) Nature: SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : A 13 050 102	
Make : BENECA	The material can be used, no
Year of manufacture : 2013	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0.5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : A 13 050 103	
Make : BENECA	The material can be used, no
Year of manufacture : 2013	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0.5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : A 13 050 104	The material can be used, no
Make: BENECA	•
Year of manufacture : 2013	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 0.5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : A 13 050 105	The material can be used, no
Make : BENECA	abnormalities were found when inspecting
Year of manufacture : 2013	
Maximum load : 2000KG	the material
Length: 0.5M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : A 13 050 106	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2013	the material
Maximum load : 2000KG	the material
Length: 0.5M	(and novit name)
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 78/1083



DESCRIPTION OF THE DEVICES

Serial number: A 13 050 107

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

abnormalities were found when inspecting

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 108

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 109

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 110

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 111

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 112

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 79/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 113

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 114

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 115

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 116

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 117

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 80/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 118

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 119

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 120

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 121

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 122

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 123

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 81/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 124

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 125

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 126

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

the material

The material can be used, no

* Conditions and operation inspection (07.2023)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 127

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 128

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 129

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 82/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 130

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 131

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 132

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 133

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 134

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 135

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 136

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 83/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 137

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 138

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 139

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 140

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 141

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 84/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 142

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The meterial can be

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 143

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 144

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 145

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 146

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 85/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 147

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 148

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 149

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 150

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 151

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 0.5M

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023

Page: 86/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 152

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 050 153

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 154

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Serial number : A 13 050 155

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 156

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 157

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 87/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 050 158

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 159

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 160

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Serial number : A 13 050 161

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 162

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 163

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 88/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 164

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 165

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 166

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 167

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 168

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 169

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 170

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 89/1083



DESCRIPTION OF THE DEVICES

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 171

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 172

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 173

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 174

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 175

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 90/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 176

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 177

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 178

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Serial number : A 13 050 179

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 180

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 181

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 91/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 182

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 183

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 184

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 185

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 186

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 187

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 92/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 188

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 189

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 190

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 191

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 192

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 93/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 050 193

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 194

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 050 195

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 050 196

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 197

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 050 198

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 94/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 199

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 050 200

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 0.5M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

SOFT STEELS 2000KG - 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 003

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 004

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 005

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 95/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 006

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 007

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 008

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 009

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 012

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 013

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 96/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 014

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 015

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 018

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 021

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 022

Make : BENECA

(see next page)

Date of issue: 16/05/2023 Page: 97/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 024

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 026

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 027

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 033

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 034

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 98/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 037 Make : BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 040

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 041

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 042

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 043

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 045

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 99/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 046

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 048

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 049

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG Length : 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 050

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 052

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 100/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 054

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 055

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Nature: SLING

Serial number: 2011 056

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

The material cannot be used anymore. The material was not available during

abnormalities were found when inspecting

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 057

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 058

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 059

(see next page)

Date of issue: 16/05/2023 Page: 101/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 060

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 061

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 062

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 063

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 065

(see next page)

Date of issue: 16/05/2023 Page: 102/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 066

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 067

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 068

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 069

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 103/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: 2011 070

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 071

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 072

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 073

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 074

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 104/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 075

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 076

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

The material can be used, no

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 077

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 078

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 080

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 081

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 105/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 082

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 083

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 084

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 085

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 086

(see next page)

Date of issue: 16/05/2023 Page: 106/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 087

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 089

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 091

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 092

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 107/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 093

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 094

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 095

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 096

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 097

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 098

Make : BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 108/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 099

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 100

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 101 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 102

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 109/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 104

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 105

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 106

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 107

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 108

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 109

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 111

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 110/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 112

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 113

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 114 Make : BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 115

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 116

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 111/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 117

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Condition

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 119

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 120

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 121

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 123

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 125

(see next page)

Date of issue: 16/05/2023 Page: 112/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 127

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 129

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially

abnormalities were found when inspecting

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 131

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 132

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 133

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 113/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 134

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 135

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 136

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 138

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 139

Year of manufacture: 2011 Maximum load: 2000KG

Make: BENECA

Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 114/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 140

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 141

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 142

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 143

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 144

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 146

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 115/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 147

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 148

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 149

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 150

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 151

(see next page)

Date of issue: 16/05/2023 Page: 116/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 152

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 153

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: 2011 154

Make: BENECA

Nature: SLING

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 155

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 157 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 117/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 160

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 161

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 163

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 164

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 166

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 118/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 167

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 168

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 169

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 170

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 171

(see next page)

Date of issue: 16/05/2023 Page: 119/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 172

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 173

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 174

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 175

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 177

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 120/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 178

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 179

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 180

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 182

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 183

(see next page)

Date of issue: 16/05/2023 Page: 121/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 184

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 185

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 186

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 187

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 188

(see next page)

Date of issue: 16/05/2023 Page: 122/1083



DESCRIPTION OF THE DEVICES Make: BENECA Year of manufacture: 2011

Length: 1M

Maximum load: 2000KG

Nature: SLING Serial number: 2011 190 Make: BENECA

Sling (cable/synthetic)

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 191 Make: BENECA

Year of manufacture: 2011

Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Serial number: 2011 192

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 193

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Serial number: 2011 194

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 123/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 196

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 197

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 198

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 199

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 201

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 202

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 204

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 124/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 205

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 206

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 209

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 211

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 212

(see next page)

Date of issue: 16/05/2023 Page: 125/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 213

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 215

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 216

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 218

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 219

(see next page)

Date of issue: 16/05/2023 Page: 126/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 220

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 222

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 223

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 224

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 226

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 227

Date of issue: 16/05/2023 Page: 127/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 230

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 231

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 232

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 233

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 234

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 128/1083



DESCRIPTION OF THE DEVICES FINDINGS Year of manufacture: 2011 * Conditions and operation inspection (07.2023) Not inspected: not presented. Maximum load: 2000KG Length: 1M Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 2011 235 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2011 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Make: BENECA Conclusion Client number of the equipment: 11 236 The material cannot be used anymore. The Year of manufacture: 2011 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 2011 237 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2011 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 2011 238

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 239 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 129/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 240

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 241

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 242

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 244

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 245

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 130/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 246

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 247

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 248

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: 2011 249

Make: BENECA

Nature: SLING

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 250

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 251

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 131/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 252

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 253

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 254

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 255

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 256

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 257

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection or could only be partially

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

required before re-service

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 132/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 258

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 259

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: 2011 260

Make: BENECA

Nature: SLING

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 261

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 262

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 133/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 263

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 264

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 265

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 266

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 267

(see next page)

Date of issue: 16/05/2023 Page: 134/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 268

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 269

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 270

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 271

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 135/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 272

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 273

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 274

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 275

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 276

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 278

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 136/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 280

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 282

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 283

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 285

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 286

(see next page)

Date of issue: 16/05/2023 Page: 137/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 287

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 288

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 291

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 293

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 138/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 294

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 295

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 296

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 297

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 298

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 299

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 139/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 300

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 307

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 392

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0046 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Serial number : A0071 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 140/1083



DESCRIPTION OF THE DEVICES Length: 1M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A0082 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 1M Sling (cable/synthetic) Nature: SLING Serial number: A0119 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A0124 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 1M Sling (cable/synthetic) Nature: SLING Serial number: A0138 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A0151 Make: BENECA Year of manufacture: 2011 Maximum load: 2000KG Length: 1M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service (see next page)

Date of issue: 16/05/2023 Page : 141/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0176 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0183 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0198 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0239 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0242 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 142/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0249 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A0252 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A0253 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A0254 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A0293 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG Length : 1M

Sling (cable/synthetic)

Nature: SLING

Date of issue:

Serial number : A 13 100 001

16/05/2023

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Page: 143/1083

(see next page)



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 002

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic) * Conditions and oper

Nature: SLING

Serial number: A 13 100 003

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 004

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Serial number: A 13 100 005

Year of manufacture: 2013

Maximum load: 2000KG

Length: 1M

Nature: SLING

Make: BENECA

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 006

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 144/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 007

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 008

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 009

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 010

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 011

Make: BENECA

Maximum load: 2000KG

Length: 1M

Year of manufacture: 2013

Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 145/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 012

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 013

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 014

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 015

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 016

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 017

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 146/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 018

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 019

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 020

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 021

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 022

(see next page)

Date of issue: 16/05/2023 Page: 147/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 024

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 025

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

Serial number : A 13 100 026

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 027

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 028

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

(see next page)

Date of issue: 16/05/2023 Page: 148/1083



DESCRIPTION OF THE DEVICES

Serial number : A 13 100 029

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 030

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 031

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 032

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 033

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 149/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 034

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 035

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 036

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 037

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 038

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 039

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 150/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 040

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 041

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 042

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 043

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 044

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 151/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 045

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 046

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 047

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 048

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 049

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 152/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 050

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 051

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 052

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 053

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 054

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 153/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 055

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 056

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 057

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 100 058

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 059

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 060

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 061

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 154/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 062

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 063

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 064

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 065

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 066

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 155/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 067

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 068

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 069

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 070

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 071

(see next page)

Date of issue: 16/05/2023 Page: 156/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 072

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 073

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 074

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 075

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 077

(see next page)

Date of issue: 16/05/2023 Page: 157/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 078

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 079

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 080

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 081

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 082

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 158/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 083

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 084

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 085

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 086

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 087

(see next page)

Date of issue: 16/05/2023 Page: 159/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 088

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 089

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 090

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 091

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 092

(see next page)

Date of issue: 16/05/2023 Page: 160/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 093

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 094

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 095

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 096

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 097

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 098

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 161/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 099

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 100

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 101

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 102

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 104

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 162/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 105

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 107

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 108

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 109

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 110

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 163/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 111

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 112

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 113

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 114

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 115

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 164/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 116

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 117

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 118

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 119

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 120

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 121

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 165/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 122

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 123

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 124

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 125

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 126

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 166/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 127

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 128

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 129

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 130

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 131

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 132

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 167/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 133

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 134

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 135

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 136

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 137

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 168/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 138

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 139

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 140

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 141

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 142

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 143

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 169/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 144

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 145

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 146

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 147

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 170/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 148

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 149

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 150

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 151

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 152

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 153

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 171/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 154

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 155

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 156

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 157

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 158

(see next page)

Date of issue: 16/05/2023 Page: 172/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 159

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 160

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 161

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 162

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 173/1083



Not inspected: not presented.

FINDINGS

Conclusion

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 163

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 164

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conclusion Make: BENECA The material cannot be used anymore. The

> material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 165

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 167

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 168

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 174/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 169

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 170

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 171

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 172

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 173

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 174

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 175/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 175

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 176

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 177

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 100 178

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 179

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 180

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 176/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 100 182

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 183

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 184

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 185

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 186

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 187

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

(see next page)

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Date of issue: 16/05/2023 Page: 177/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 188

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

The material can be used, no

abnormalities were found when inspecting

the material

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 189

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 190

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 191

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 192

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 178/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 193

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 194

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 195

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 196

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 197

(see next page)

Date of issue: 16/05/2023 Page: 179/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 198

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 199

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 200

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 202

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 180/1083



DESCRIPTION OF THE DEVICES
Nature: SLING

Serial number : A 13 100 203

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 204

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 205

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 206

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 207

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 208

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 181/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 209

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 210

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 211

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 212

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 213

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 214

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 182/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 215

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 216

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 217

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 218

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 183/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 100 219

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 220

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 221

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 222

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 223

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 224

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 184/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 225

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 226

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 227

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 228

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 229

(see next page)

Date of issue: 16/05/2023 Page: 185/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 230

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 231

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 232

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 233

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 234

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 186/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 235

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 236

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 237

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 238

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 239

Date of issue: 16/05/2023 Page: 187/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 240

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 241

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 242

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 243

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 244

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 188/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 245

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 246

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 247

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 248

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 189/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 100 249

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 250

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 251

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 252

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 253

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 254

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 190/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 255

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 256

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 257

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 258

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 259

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 260

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 261

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 191/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 262

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 263

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 264

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)
Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 265

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 266

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 192/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 1M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 100 267 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: A 13 100 268 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 100 269 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Make: BENECA Conclusion Client number of the equipment: A 13 100 270 The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Make: BENECA Conclusion

Client number of the equipment: A 13 100 271

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 193/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 272

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 273

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 274

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 275

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number : A 13 100 276

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 194/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 277

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 278

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 279

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 281

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 282

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 283

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Lenath: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic) Nature: SLING

Date of issue: 16/05/2023

Page: 195/1083



DESCRIPTION OF THE DEVICES

Serial number: A 13 100 284

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 285

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 286

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 287

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 288

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 289

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 196/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 290

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 291

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 292

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 293

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 294

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 197/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 295

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 296

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 297

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 298

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 299

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 300

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 198/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 301

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 302

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 303

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 304

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 305

(see next page)

Date of issue: 16/05/2023 Page: 199/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 306

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 307

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 308

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 309

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 200/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : A 13 100 310

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 314

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 315

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 316

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 318

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: A 13 100 319

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 201/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 320

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 321

Year of manufacture: 2013 Maximum load: 2000KG Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 322

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 323

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 324

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 325

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 202/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 326

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 327

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 328

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 329

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 330

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 331

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 203/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 332

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 333

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 334

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 335

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 336

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 337

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 204/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 338

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 339

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 340

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 341

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 342

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 343

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 344

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 205/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 345

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 346

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number : A 13 100 347

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 348

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: A 13 100 349

Make: BENECA

Nature: SLING

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 206/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 350

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 351

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 352

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 353

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 207/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 354

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 355

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 356

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 357

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 358

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 359

(see next page)

Date of issue: 16/05/2023 Page: 208/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 360

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 361

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 362

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 363

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 364

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 365

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 209/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 366

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 367

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 368

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 369

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 370

(see next page)

Date of issue: 16/05/2023 Page: 210/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 371

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 372

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 373

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 374

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: A 13 100 375

Senai number . A 13 100 3/5

Make : BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 211/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 100 376

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 377

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 378

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 380

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 381

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 382

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 212/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 383

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 384

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 385

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 386

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 387

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 213/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 388

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 389

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 390

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 391

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 392

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 393

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)
Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 214/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 100 394

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 395

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 396

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 397

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 398

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number: A 13 100 399

Make: BENECA

Nature: SLING

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 215/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 400

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 401

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 402

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 403

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 404

Year of manufacture : 2013 Maximum load : 2000KG Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 216/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 405

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 406

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 407

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 408

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 217/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 409

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 410

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 411

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 412

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 413

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 218/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 414

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 415

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 416

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 417

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 418

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 219/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 419

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 420

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 421

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 422

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 423

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 424

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Date of issue: 16/05/2023 Page: 220/1083



DESCRIPTION OF THE DEVICES

Serial number: A 13 100 425

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 426

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 427

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 428

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 429

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 430

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 431

(see next page)

Date of issue: 16/05/2023 Page: 221/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 432

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 433

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 434

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 435

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 436

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 222/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : A 13 100 437

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 439

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 440

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 441

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 442

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 443

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 223/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 444

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 445

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 446

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 447

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 448

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 224/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 449

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 450

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 451

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 452

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 453

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 225/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 454

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 455

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 456

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 457

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 458

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 226/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 459

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Length: 1M

Client number of the equipment: A 13 100 460

Year of manufacture: 2013 Maximum load: 2000KG

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 461

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 462

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 463

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 464

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 227/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 465

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 466

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 467

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 468

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 469

(see next page)

Date of issue: 16/05/2023 Page: 228/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 470

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 471

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 472

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 100 473

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 229/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 100 474

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 475

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 476

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 477

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 100 478

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 479

Date of issue: 16/05/2023 Page: 230/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 480

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 481

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 482

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 483

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 484

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 231/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 100 485

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 486

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 487

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 488

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 100 489

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 490

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 232/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 491

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 492

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 493

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 494

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 495

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 100 496

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 233/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 497

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 498

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 100 499

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 100 500

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A13 100 524

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 001

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 234/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 002

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 003

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 004

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 005

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 235/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 006

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 007

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)
Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 008

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 009

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 011

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 012

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 236/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 013

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 014

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 015

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

the material

Sling (cable/synthetic) Nature: SLING

Serial number: A 14 100 016

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 017

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 018

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 237/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 100 019

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 020

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 021

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 022

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 023

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 024

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 238/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 025

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 026

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 027

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 028

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 029

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 239/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 030

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 031

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 032

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 033

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 034

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 240/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 035

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 036

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 037

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 038

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 039

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 241/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 040

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 041

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 042

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 043

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 044

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 045

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 242/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 046

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 047

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 100 048

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 049

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 050

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 243/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 051

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 052

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 053

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 054

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 055

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 244/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 100 056

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 057

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 058

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

abnormalities were found when inspecting the material

The material can be used, no

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 059

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 060

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 061

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 245/1083



DESCRIPTION OF THE DEVICES

Serial number: A 14 100 062

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 063

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 064

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 065

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 066

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 246/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 067

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 068

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 069

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 070

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 071

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 072

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 247/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 073

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 074

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 075

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 076

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 248/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 100 077

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 078

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 079

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 080

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 081

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 082

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

(see next page)

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Date of issue: 16/05/2023 Page: 249/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 083

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 084

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 085

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 086

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 088

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 250/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 100 089

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 090

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 091

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 092

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 093

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 251/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 100 094

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 095

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 096

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 100 097

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 098

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 252/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 100 099

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 100

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 101

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 102

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 103

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 253/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 104

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 105

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 106

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 107

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 108

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 109

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 254/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 110

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 111

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 100 112

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 113

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 255/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 100 114

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 115

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 116

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 117

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 118

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 256/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 100 119

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 120

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 121

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 122

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 123

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 124

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 257/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 125

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 126

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 127

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 128

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 129

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 258/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 130

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 131

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 132

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 133

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 134

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 135

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 259/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 136

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 137

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

_

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 138

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature : SLING Not inspected: not presented.

Client number of the equipment: A 14 100 139

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Make: BENECA

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 140

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 260/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 141

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 142

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 143

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 144

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 145

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1M

Nature: SLING

Serial number: A 14 100 146

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 261/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 147

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 148

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 149

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 150

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 151

Year of manufacture : 2014 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 262/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 152

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 153

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 154

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 155

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 156

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 263/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 157

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 158

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 159

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 160

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 161

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 162

Year of manufacture: 2014

* Conditions and operation inspection (07.2023) Conclusion

abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 264/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 163

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 164

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 165

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 166

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 167

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 265/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 168

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 169

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 100 170

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 171

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 172

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 173

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 266/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 174

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 175

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 176

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 177

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 178

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 267/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 179

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Condition

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 180

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

the material

The material can be used, no

* Conditions and operation inspection (07.2023) Conclusion

Conclusion

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 181

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

The material can be used, no abnormalities were found when inspecting the material

abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 182

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 183

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 100 184

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 268/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 185

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 100 186

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 187

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 188

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 189

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 269/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 190

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 191

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 100 192

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 193

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 194

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 270/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 100 195

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 196

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 197

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 100 198

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 199

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 200

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 271/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 100 466

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : RDB73156

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB73502

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/26440

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 272/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/26441 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26442

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

Conclusion

the material

the material

Conclusion

The material cannot be used anymore. The material was not available during

abnormalities were found when inspecting

abnormalities were found when inspecting

abnormalities were found when inspecting

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26443

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 18/26444

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 18/26445

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26446 Make: BENECA

Year of manufacture: 2018

Maximum load: 2000KG

Length: 1M

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 273/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/26447

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26448

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26449

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/26450

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26451

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26453

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 274/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/26454

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26457

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26458

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26459

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26460

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26461

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Lenath: 1M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Nature: SLING

Date of issue: 16/05/2023 Page: 275/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/26462

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26463

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26464

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26465

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG Length : 1M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26466

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26467 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M
Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 276/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/26468

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26469

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26470

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26471 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26472

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26473

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 277/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) Nature: SLING

Serial number: 18/26474

Make: BENECA Year of manufacture: 2018

Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26475

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26476 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26477

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: 18/26478

Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG

Lenath: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 278/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/26479

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26487

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26496

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26618

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26621 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26622

(see next page)

Date of issue: 16/05/2023 Page: 279/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26623

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26624

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26625

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26626

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26627

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 280/1083



Nature : SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 1M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26628	The material can be used, no
Make : BENECA Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 18/26629	Conclusion
Make: BENECA	The material cannot be used anymore. The
Year of manufacture : 2018	material was not available during
Maximum load : 2000KG Length : 1M	inspection, or could only be partially
Lengur. Twi	inspected, an additional inspection is
	required before re-service
	<u> </u>
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26630 Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26631 Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26632	The material can be used, no
Make : BENECA Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	(see next page)
Noture : CLINC	

Date of issue: 16/05/2023 Page: 281/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/26633

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26634

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26635

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26636

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1M

Nature: SLING

Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Conclusion

the material

Conclusion

Serial number: 18/26637 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018

the material Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26638

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26639

(see next page)

Date of issue: 16/05/2023 Page: 282/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26640

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26678

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26681 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26682

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26683

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 283/1083



DESCRIPTION OF THE DEVICES

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26684

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26686

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26687

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26688

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26689

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 284/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 1M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/26690 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/26691 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Serial number: 18/26692 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/26693 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/26694 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M

Sling (cable/synthetic)

Nature : SLING

(see next page)

inspected, an additional inspection is

required before re-service

Date of issue: 16/05/2023 Page: 285/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/26695

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26696

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26697

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26698

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26699

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/26700

(see next page)

Date of issue: 16/05/2023 Page: 286/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26781

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Conclusion

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26782

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26783

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26784

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26786

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

The material can be used, no

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26787

Make: BENECA

Year of manufacture: 2018

Date of issue: 16/05/2023 Page: 287/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The
	material carnot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 18/26788	Conclusion
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 18/26789	Conclusion
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 18/26790	Conclusion
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Nature : SLING	
Serial number : 18/26791 Make : BENECA	Conclusion
Year of manufacture : 2018	The material cannot be used anymore. The
Maximum load : 2000KG	material was not available during
Length: 1M	inspection, or could only be partially
	inspected, an additional inspection is
	required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Not inspected: not presented.
Serial number : 18/26792	Conclusion
Make: BENECA	The material cannot be used anymore. The
Year of manufacture : 2018	material was not available during
Maximum load : 2000KG Length : 1M	inspection, or could only be partially
Longur. IIVI	inspected, an additional inspection is
	required before re-service
	roquired before re-service

Date of issue: 16/05/2023 Page: 288/1083

(see next page)



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/26793

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26794

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/26795

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)
Nature: SLING

Serial number : 18/26796

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26797

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26798

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 289/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/26799

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26800

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26801

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : 18/26802

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26803

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26804 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Condition

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26805

(see next page)

Date of issue: 16/05/2023 Page: 290/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26806

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

The material can be used, no

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26807

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26808

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

· · ·

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26809

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26810

(see next page)

Date of issue: 16/05/2023 Page: 291/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/26811 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/26812 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/26813 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/26814 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/26815 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
OP t LLt d d	

Date of issue: 16/05/2023 Page: 292/1083

(see next page)



DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 18/26816 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023)
Nature: SLING Serial number: 18/26817 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/26818 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/26819 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/26820 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/26821 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service (see next page)
Jilly (cable/syllthetic)	(see next page)

Date of issue: 16/05/2023 Page: 293/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 18/26822 Conclusion Make: BENECA The material can be used, no Year of manufacture: 2018 abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/26823 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/26824 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 18/26825 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/26826 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018

Sling (cable/synthetic)

Maximum load: 2000KG

Nature: SLING

Length: 1M

Serial number : 18/26827

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 294/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/26828

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26829

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26830

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 18/26831

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26832

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 295/1083



DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 18/26833	
Make: BENECA	Conclusion
Year of manufacture : 2018	The material cannot be used anymore. The
Maximum load : 2000KG	material was not available during
Length: 1M	<u> </u>
	inspection, or could only be partially
	inspected, an additional inspection is
	required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26834	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2018	the material
Maximum load : 2000KG	the material
Length: 1M	* Conditions and answeller inspection (07 2022)
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 18/26835	Conclusion
Make : BENECA	
Year of manufacture : 2018	The material cannot be used anymore. The
Maximum load : 2000KG	material was not available during
Length: 1M	inspection, or could only be partially
	inspected, an additional inspection is
	required before re-service
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/26836	The material can be used, no
Make: BENECA	•
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 18/26837	Conclusion
Make : BENECA	The material can be used, no
Year of manufacture : 2018	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Not inspected: not presented.
Serial number : 18/26838	Conclusion
Make: BENECA	The material cannot be used anymore. The
Year of manufacture : 2018	material was not available during
Maximum load : 2000KG	inspection, or could only be partially
Length: 1M	inspection, or could only be partially

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 296/1083

inspected, an additional inspection is

required before re-service

(see next page)



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/26839

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26840

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

The material can be used, no

The material can be used, no

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26921

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26922 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26923

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26924

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Lenath: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Date of issue: 16/05/2023 Page: 297/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/26925

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26926

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26927

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26928

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26929

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26930

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 298/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/26931

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26932

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/26933

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number : 18/26934

Make : BENECA

Nature: SLING

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/26935

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26936

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 299/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/26937

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26938

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/26939

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Serial number : 18/26940

Make : BENECA

Nature: SLING

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27001

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27002

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 300/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/27003

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27004

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27005

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27006

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27007

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

required before re-service

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27008

(see next page)

Date of issue: 16/05/2023 Page: 301/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27009

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27010

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27011

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27012

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27013

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 302/1083



Maximum load: 2000KG

Sling (cable/synthetic)

Date of issue:

16/05/2023

Length: 1M

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 1M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/27014 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 18/27015 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/27016 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/27017 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Not inspected: not presented. Nature: SLING Serial number: 18/27018 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018

material was not available during

required before re-service

(see next page)

inspection, or could only be partially

inspected, an additional inspection is

Page: 303/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 18/27019 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/27020 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023) Not inspected: not presented.
Nature: SLING Serial number: 18/27021 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/27022 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/27023 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/27024 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 304/1083

(see next page)



DESCRIPTION OF THE DEVICES
Nature: SLING
Serial number: 18/27025

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/27027

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/27028

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/27029

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/27030

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27031

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 305/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 18/27032 Conclusion Make: BENECA The material can be used, no Year of manufacture: 2018 abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/27033 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/27034 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 18/27035 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/27036 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/27037 Conclusion

Sling (cable/synthetic)

Year of manufacture: 2018

Maximum load: 2000KG

Make: BENECA

Length: 1M

(see next page)

The material cannot be used anymore. The

material was not available during

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

Date of issue: 16/05/2023 Page: 306/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/27038

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27039

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27040

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

Sling (cable/synthetic)

Nature : SLING Serial number : 28.100 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

SOFT STEELS 2000KG - 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0001 Make : BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 307/1083



DESCRIPTION OF THE DEVICES

Serial number : A0002 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0010 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0011 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0013 Make : BENECA

Sling (cable/synthetic)

Year of manufacture: 2014

Maximum load: 2000KG

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Nature : SLING Serial number : A0014

Make: BENECA

Length: 1M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0015 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 308/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0016 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0017 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0018 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0019 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0020 (see next page)

Date of issue: 16/05/2023 Page: 309/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0021 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A0022

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0024 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0025 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 310/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0026 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0027 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0028 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0029 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0030 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0031

Date of issue:

16/05/2023

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

rectinopostos. Not procen

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

Page: 311/1083

required before re-service

(see next page)



DESCRIPTION OF THE DEVICES

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0032 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0033 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0034 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0035 Make : BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0036 Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 312/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0037 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0038 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0039 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0040 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 313/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : a0041 Make : BENECA

Client number of the equipment: 041

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0042 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0043 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0044 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0045 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M
Sling (cable/synthetic)

Nature : SLING Serial number : A0046

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 314/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0047 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0048 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0050 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0051 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0053 (see next page)

Date of issue: 16/05/2023 Page: 315/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0054 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0055 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0056 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0057 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 316/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0058 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0059 Make: BENECA Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0060 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0061 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0062 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0063 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 317/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0064 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0065 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0066 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0067 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0068 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0071 **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 318/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0072 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0073 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0074 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0075 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0076 (see next page)

Date of issue: 16/05/2023 Page: 319/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0077 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0078 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0079 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0080 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 320/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0081 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0082 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0083 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0084 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0085 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 321/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0086 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0087 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0088 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0089 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0090 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0091 **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 322/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0092 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0093 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0094 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0095 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 323/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0096 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0097 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0098 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0099 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0100 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 324/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0101 Make : BENECA Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0102 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0103 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0104 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0105 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature : SLING Serial number : A0106 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 325/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0107 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0108 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0109 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0110 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0111 Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 326/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0113 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0114 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0115 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0116 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0117 (see next page)

Date of issue: 16/05/2023 Page: 327/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0118 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0119 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0120 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0121 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0122 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 328/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0124 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0125 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0126 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0127 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0128 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 329/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0129 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0130 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0131 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0132 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 330/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0133 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0134 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0135 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0136 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0137 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 331/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0138 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0139 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0140 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0141 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0142 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0143 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 332/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0144 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0145 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0146 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0148 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 333/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0149 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0150 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0151 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0152 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0153 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0154 **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 334/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0155 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0157 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0158 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0159 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

Nature : SLING Serial number : A0160 * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 335/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0161 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0162 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0163 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0164 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0165 (see next page)

Date of issue: 16/05/2023 Page: 336/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0166 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0167 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0168 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0169 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 337/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0170 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0171 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0172 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0174 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0175 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 338/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 176

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 177

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 178

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 179

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 180

Year of manufacture : 2009 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

Page: 339/1083

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0181 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0182 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 183

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 184

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 185

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0186 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M
Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 340/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 187

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 188

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 189

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 190

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 191

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 341/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0192 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0193 Make : BENECA

Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0194 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 195

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0196 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 342/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 197

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 198

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 199

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0200 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0201 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0202 (see next page)

Date of issue: 16/05/2023 Page: 343/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0203 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0204 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0205 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 206

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0207 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 344/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 208

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0209 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0210 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0211 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 212

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 345/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 213

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 214

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0215 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0216 Make : BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 217

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 346/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 218

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 219

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 220

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 221

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0222 Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 347/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0223 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0224 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 225

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 226

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0227 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 228

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 348/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 229

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 230

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0231 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 232

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 233

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 349/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 234

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 235

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0236 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0237 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0238 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 239

Year of manufacture: 2009 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 350/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 240

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0241 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 242

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 243

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 351/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 244

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Serial number: A0245 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 246

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 247

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 249

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 352/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 250

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 251

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 252

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0253 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0254 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 353/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A0255

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0256 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

inspected, an additional inspection is

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 257

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 258

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 259

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0260 (see next page)

Date of issue: 16/05/2023 Page: 354/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0261 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Serial number: A0262 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Serial number: A0263 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 264

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 265

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 355/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 266

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0267 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0268 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 269

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 270

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 356/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 271

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 272

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 273

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 274

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 275

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 357/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 276

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0277 Make : BENECA Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 278

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 279

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 280

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 358/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0281 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 282

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 283

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 284

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 285

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 286

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 359/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 287

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0288 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0289 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 291

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 360/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 292

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 293

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 294

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 295

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 296

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 361/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0297 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0298 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0299 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A0300 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 1,6M

Nature: SLING

Sling (cable/synthetic)

Serial number : 2011 001

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 003

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 362/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 004

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 005

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 006

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 007

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 008

(see next page)

Date of issue: 16/05/2023 Page: 363/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 009

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 010

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 011

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 012

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 013

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 364/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 014

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 015

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 016

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 017

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 018

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 019

(see next page)

Date of issue: 16/05/2023 Page: 365/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 020

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 021

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 022

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 023

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 024

(see next page)

Date of issue: 16/05/2023 Page: 366/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 025

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 026

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 027

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 028

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 367/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 029

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 030

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 031

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 032

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 033

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 368/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 034 Make : BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 036

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 037

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 038

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number: 2011 039

Serial number : 2011 039

Make : BENECA

Nature: SLING

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 369/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 2011 040

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 041

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 042

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 043

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 044

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 370/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 2011 045

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 046

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 047

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 049

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 050

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 371/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 2011 051

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 053

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 054

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 056

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 057

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 372/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 2011 058

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 059

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 060 Make : BENECA

Vear of manufactur

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 061

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 062

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 063

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 373/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 064

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 065

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 066

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 068

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number: 2011 069

Make: BENECA

Nature: SLING

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 374/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 070

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 071

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 072

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 073

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 074

Make : BENECA

(see next page)

Date of issue: 16/05/2023 Page: 375/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 075

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 076

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 077 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 078

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 376/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 2011 079

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 080

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 081

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 082

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 083

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 377/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 2011 084

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 085

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 086

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Nature: SLING Make: BENECA

Sling (cable/synthetic)

Client number of the equipment: 2011 087

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 088 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 378/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 089

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 090

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 091

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 092

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 093

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 094

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 379/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 095

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 096

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 097

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 098

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 380/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 2011 099

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 100

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 101

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 103

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 104

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 381/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 2011 105

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 106

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 107

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number : 2011 108 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Nature: SLING

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 109

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 382/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 2011 110

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 111

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 112 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 113

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 114

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 383/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 115

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 116

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 117

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 118

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Conclusion

Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 119

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 121

Year of manufacture : 2011 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 384/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 120

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 122

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 123

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 124 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 385/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 125

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 126

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 127

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 128 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 129

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 130

(see next page)

Date of issue: 16/05/2023 Page: 386/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 131

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 132

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 133

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 134

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 135

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Date of issue: 16/05/2023 Page: 387/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 137

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 138

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 139

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 140 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 141

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 388/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 142

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 143

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 144

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 145

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 146

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Date of issue: 16/05/2023 Page: 389/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 147

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 148

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 149

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 150

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 151 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG Length : 1,6M

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Date of issue: 16/05/2023 Page: 390/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 152

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 153

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 154

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 155

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 156

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 391/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 157

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 158

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 159

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 160

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 161

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 162

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 392/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 163

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 164

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 165 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 166

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 167

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 393/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 168

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Ttot mopooto

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 169

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

The material can be used, no abnormalities were found when i

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 170

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 171

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 172

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 394/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 173

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 174

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 175

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 176

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 177

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 395/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 178

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 179

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 181

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 182

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 183

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 184

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 396/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 185

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 186

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 187

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 188

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 397/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 189

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 190

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 192

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 193

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 194

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 398/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 195

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 196

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 197

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : 2011 198

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 199

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 399/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 11 200

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 201

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 202

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 203 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 204

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 205

(see next page)

Date of issue: 16/05/2023 Page: 400/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 206

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 207

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 208

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 209

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 210

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

•

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 401/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 211

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 212

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 213 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 214

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 215

Year of manufacture: 2011 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 402/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 216

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 217

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 218 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 219

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 220

(see next page)

Date of issue: 16/05/2023 Page: 403/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 221

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 222 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 223

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 224

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 225

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 404/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 226

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 227

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 228

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 229

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 230

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 231

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 405/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 232

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 233

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 234

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 235

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 236

Year of manufacture : 2011 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 406/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 237

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 238

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 239

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 240

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 241

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 407/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 242

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 243

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 244

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 245

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 246

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 247

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 408/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 248

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 249

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 250

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 251

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 252

Year of manufacture : 2011 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 409/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 253

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 254

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 256

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 257

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 258

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 259

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 410/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 2011 260

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 261

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 262 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 263

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 11 264

Year of manufacture: 2011 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 411/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 265

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 266

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 267

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 268

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 412/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 269

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 270

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 271

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 272

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 273

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 413/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 274

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 275

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 276

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 277

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 278

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 279

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

required before re-service

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 414/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 280

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 281 Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 282

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 283

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 284

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 415/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 11 285

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 286

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 287

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 288

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 289

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 290

Year of manufacture : 2011 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 416/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 291

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 292

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 293

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 294

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 417/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 295

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 2011 296

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 297

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 299

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 11 300

Year of manufacture : 2011 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 001

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

•

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 418/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 002

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 003

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 004

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 005

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 419/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 006

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 007

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 008

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 009

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 010

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 420/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 011

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 012

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 013

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 014

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 015

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 016

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 421/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 017

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 018

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 019

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 020

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number: A 13 160 021

Make: BENECA

Nature: SLING

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 422/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 022

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 023

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 024

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 025

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 026

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 423/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 027

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 028

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 029

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 030

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 031

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 424/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 032

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 033

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 034

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 035

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 036

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 425/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 037

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 038

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 039

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 040

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 041

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 426/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 042

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 043

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 044

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 045

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 046

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 427/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 047

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 048

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 049

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 050

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 051

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 428/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 052

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 053

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 054

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 160 055

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 056

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 057

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 429/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 058

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 059

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 060

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 061

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 062

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 430/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 063

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 064

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 065

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 160 066

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 067

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 431/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 160 068

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 069

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 070

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 071

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 072

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 073

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 432/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 074

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 075

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 076

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 077

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 433/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 078

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 079

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 080

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 081

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 082

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 434/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 083

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 160 084

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 085

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 086

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 087

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 088

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 435/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 089

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 090

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 091

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 092

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 093

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 095

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 436/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 096

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 097

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 098

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 099

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 100

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 437/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 101

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 102

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 103

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 104

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 105

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 438/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 106

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 107

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 108

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 109

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 110

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 439/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 111

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 112

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 113

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 114

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number : A 13 160 115

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 440/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 116

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 117

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 118

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 119

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 120

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 441/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 121

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 122

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 123

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 124

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 125

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 442/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 126

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 127

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 128

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 129

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 130

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 131

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 443/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 132

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 133

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 134

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 135

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 136

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 444/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 137

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 138

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 139

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 140

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 141

(see next page)

Date of issue: 16/05/2023 Page: 445/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 142

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 143

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 144

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 145

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 146

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 446/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 147

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 148

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

inspected, an additional inspection is

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 149

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 151

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 152

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 447/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 153

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 154

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 155

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 156

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 157

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Date of issue: 16/05/2023 Page: 448/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 158

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 159

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

The material can be used, no abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 160

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 161

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 162

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 163

Year of manufacture: 2013 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 449/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 160 164

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 165

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

The material can be used, no

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 166

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 167

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 160 168

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Date of issue: 16/05/2023 Page: 450/1083



DESCRIPTION OF THE DEVICES

Serial number: A 13 160 169

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 170

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 171

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 172

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 173

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 174

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 451/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 175

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 176

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 177

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 160 178

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 179

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 180

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 452/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 181

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 182

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 183

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 160 184

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 160 185

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M
Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 453/1083



* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

material was not available during

material was not available during

inspection, or could only be partially

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

abnormalities were found when inspecting

The material cannot be used anymore. The

The material cannot be used anymore. The

abnormalities were found when inspecting

abnormalities were found when inspecting

The material can be used, no

FINDINGS

Conclusion

the material

Conclusion

Conclusion

Conclusion

the material

Conclusion

Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 160 186

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 187

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING Not inspected: not presented.

Make: BENECA
Client number of the equipment: A 13 160 188

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 189

Year of manufacture : 2013 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 190

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 191

16/05/2023

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Date of issue:

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

Page: 454/1083

required before re-service

Sling (cable/synthetic) (see next page)



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 192

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 193

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 194

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 195

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 196

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 197

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 455/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 198

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 199

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 200

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 201

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 202

Year of manufacture: 2013 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 456/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 203

Year of manufacture : 2013 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 204

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 205

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 206

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 207

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 457/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 208

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 209

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 210

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 211

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 458/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 212

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 213

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 214

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 215

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 216

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

The material can be used, no

abnormalities were found when inspecting

Conditions and operation inspection (07.2023)

the material

Conclusion

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 217

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 459/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 218

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 219

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 220

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 222

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 460/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 223

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 224

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 225

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 226

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 227

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 461/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 228

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 229

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 230

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 231

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 232

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 233

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 462/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 234

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 236

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 237

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 238

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 463/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 239

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 240

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 241

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 242

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 243

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 244

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 464/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 246

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 247

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 248

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 249

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 250

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 251

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 465/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 252

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 253

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 254

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 255

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 256

Year of manufacture : 2013 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 466/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 257

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 258

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 259

Year of manufacture : 2013 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 260

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 261

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 467/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 262

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 263

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

FINDINGS

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

abnormalities were found when inspecting

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 264

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 265

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 266

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 268

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 468/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 269

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 270

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 271

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 272

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 273

Year of manufacture: 2013 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 274

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 469/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 275

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 276

Year of manufacture: 2013 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 277

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 278

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 279

Year of manufacture: 2013 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1,6M

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 280

Year of manufacture: 2013 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 470/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 281

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 282

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 283

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 284

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 471/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 285

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 286

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 287

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 288

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 289

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 472/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 290

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 291

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 292

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 293

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 160 294

Year of manufacture : 2013 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 473/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 13 160 295

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 296

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 297

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 298

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 299

Year of manufacture: 2013 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 13 160 300

Year of manufacture: 2013 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 474/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 001

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 002

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 003

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 004

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

the material

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 005

Year of manufacture: 2014 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 475/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 006

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 007

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 008

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 009

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 010

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 476/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 012

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 013

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 014

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 015

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 016

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 477/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 017

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 018

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 019

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 020

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 021

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 478/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 022

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 023

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 024

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 025

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 026

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 027

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 479/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 028

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 029

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 030

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 031

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 032

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 033

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 480/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 034

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 035

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 036

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 037

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 038

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 481/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 039

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 040

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 041

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 043

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 044

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 482/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 045

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 046

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 047

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 048

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 049

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 483/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 050

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 051

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 052

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 053

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 054

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 484/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 055

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 056

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 057

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 058

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 059

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 060

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 485/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 061

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 062

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 063

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 064

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 065

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 486/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 066

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 067

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 068

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 069

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 070

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 487/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 071

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 072

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 073

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 074

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 075

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 488/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 077

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 078

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 079

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 080

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 081

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 082

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 489/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 083

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 084

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 085

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 086

Year of manufacture : 2014 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

Langeth : 4 CM

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 087

Year of manufacture : 2014 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 490/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 088

Year of manufacture: 2014 Maximum load: 2000KG Length: 1,6M

Conclusion

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 089

Year of manufacture: 2014 Maximum load: 2000KG Length: 1,6M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 090

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 091

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 092

Year of manufacture: 2014 Maximum load: 2000KG Lenath: 1.6M

Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Nature: SLING

Date of issue: 16/05/2023 Page: 491/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: A 14 160 093

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 094

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 095

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 096

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 097

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 492/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 098

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 099

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 100

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 101

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)
Nature: SLING

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 102

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 103

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 493/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 104

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 105

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 106

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 108

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 494/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 110

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 111

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 112

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 113

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 114

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 495/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 115

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 116

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 117

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 118

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 119

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 496/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 120

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 121

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 122

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 123

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 124

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 497/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 126

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 128

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 129

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 130

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 131

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 498/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 132

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 133

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 134

Year of manufacture : 2014 Maximum load : 2000KG Conclusion
The mate

The material can be used, no abnormalities were found when inspecting

the material

Length: 1,6M
Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 135

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 136

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 137

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

(see next page)

Date of issue: 16/05/2023 Page: 499/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: A 14 160 138

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 139

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 140

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 141

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 142

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 143

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)
Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 500/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 144

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 145

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 146

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 147

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 148

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 501/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 149

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 150

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 151

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Nature: SLING Make: BENECA

Sling (cable/synthetic)

Client number of the equipment: A 14 160 152

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 153

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 502/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 154

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 155

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 156

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 157

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 158

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 159

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 503/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 160

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 162

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 163

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 164

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 165

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 504/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 166

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 167

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 169

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 171

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 172

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 173

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 505/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 174

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 175

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 176

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 177

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 506/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A 14 160 178

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 179

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 180

Year of manufacture: 2014

Length: 1,6M

Maximum load: 2000KG

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 181

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 182

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 183

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 507/1083



* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

material was not available during

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

abnormalities were found when inspecting

The material cannot be used anymore. The

The material can be used, no

FINDINGS

Conclusion

the material

Conclusion

Conclusion

Conclusion

Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 184

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 185

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: SLING

Make: BENECA Client number of the equipment: A 14 160 186

Year of manufacture: 2014 Maximum load: 2000KG

material was not available during inspection, or could only be partially Length: 1,6M

inspected, an additional inspection is

The material cannot be used anymore. The

The material cannot be used anymore. The

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING

Make: BENECA

Client number of the equipment: A 14 160 187

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 188

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING Make: BENECA

Client number of the equipment: A 14 160 189

Year of manufacture: 2014 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

The material can be used, no

Conclusion

the material

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 508/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 190

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 191

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 192

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 193

Year of manufacture : 2014 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 194

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 195

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 509/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 196

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 197

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 199

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 200

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 14 160 201

Year of manufacture : 2014 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A14 160 243

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 510/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 30084

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 38761

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 61076

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 68046

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 511/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: RDB 68047

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 68049

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 68052

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 68078

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73038

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73066

Make: BENECA Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 512/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: RDB 73067

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73068

Make : BENECA Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73069

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73072

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73076

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73078

Make : BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73079

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 513/1083



DESCRIPTION OF THE DEVICES

Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: RDB 73082

Make : BENECA Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73083

Make : BENECA

Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73084

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73103

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: RDB 73105

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 514/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: RDB 73107

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73109

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73135

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73136

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73143

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 73150

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74503

Make: BENECA

Date of issue: 16/05/2023 Page: 515/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB74504

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74505

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74508

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74510

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB74511

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 516/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: RDB 74525 Conclusion Make: BENECA The material can be used, no Maximum load: 2000KG abnormalities were found when inspecting Length: 1,6M the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: RDB 74526 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2015 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: RDB 74527 The material can be used, no Make: BENECA abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: RDB 74528 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2015 the material Maximum load: 2000KG Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: RDB 74530 The material can be used, no Make: BENECA abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: RDB 74531 The material can be used, no Make: BENECA abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : RDB 74533 Make : BENECA

Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 517/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: RDB 74534

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : RDB 74535

Make : BENECA Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74537

Make : BENECA

Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: RDB 74539

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 13/007781

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 16/18252

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 518/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 17/20081

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/20083

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20084

Make : BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/20085

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 17/20087

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20089

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 519/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/20090 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22396

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22397

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22400

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22401

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22403

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 520/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22406

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22409

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22414

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22456

Make: BENECA

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22460

Make: BENECA

Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 521/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 17/22466 Conclusion Make: BENECA The material can be used, no Maximum load: 2000KG abnormalities were found when inspecting Length: 1,6M the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 17/22469 The material can be used, no Make: BENECA abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 17/224109 Conclusion Make: BENECA The material cannot be used anymore. The Maximum load: 2000KG material was not available during Length: 1,6M inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 17/24760 The material can be used, no Make : BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24351 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG Length: 1,6M inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24352 Conclusion Make: BENECA The material cannot be used anymore. The

Sling (cable/synthetic)

Year of manufacture: 2018

Maximum load: 2000KG

Length: 1,6M

(see next page)

material was not available during

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

Date of issue: 16/05/2023 Page: 522/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/24353

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24354

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24355

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24356

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24357

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/24358

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24359

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 523/1083



DESCRIPTION OF THE DEVICES FINDINGS Make: BENECA * Conditions and operation inspection (07.2023) Not inspected: not presented. Year of manufacture: 2018 Maximum load: 2000KG Conclusion Length: 1,6M The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/24360 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/24361 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24362 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service

Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 18/24363	The material can be used, no
Make: BENECA	

abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M

* Conditions and operation inspection (07.2023) Sling (cable/synthetic) Not inspected: not presented. Nature: SLING

Serial number: 18/24364 Conclusion

Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is

(see next page)

required before re-service

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 524/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 18/24365 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/24366 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24367 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/24368 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24369 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24370 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 525/1083

(see next page)



DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 18/24371 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24372 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24373 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/24374 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/24375 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/24376 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 526/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/24377

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24378

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24379

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24380

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24381

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24382

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

required before re-service

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 527/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24384

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24385

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24386

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24387

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24388

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 528/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24389

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24390

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24391

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24392

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24393

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24394

(see next page)

Date of issue: 16/05/2023 Page: 529/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/24395

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

The material can be used, no

The material can be used, no

abnormalities were found when inspecting

the material

the material

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24396

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24397

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Conclusion

abnormalities were found when inspecting

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/24398

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24399

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Date of issue: 16/05/2023 Page: 530/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/24400

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24401

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24402

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number: 18/24403

Make : BENECA

Nature: SLING

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24404

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24405

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 531/1083



DESCRIPTION OF THE DEVICES FINDINGS Year of manufacture: 2018 * Conditions and operation inspection (07.2023) Maximum load: 2000KG Conclusion Length: 1,6M The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/24406 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24407 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 18/24408 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24409 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 18/24410

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 532/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/24426

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24427

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24428

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24429

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24430

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24431

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 533/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24432

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24433

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24434

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24435

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24436

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24437

(see next page)

Date of issue: 16/05/2023 Page: 534/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24438

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/24439

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Serial number : 18/24440

Make: BENECA

Nature: SLING

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24449

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24454

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 535/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24456

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24457

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/24458

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24459

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24460

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 536/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24461

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24462

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24463

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24464

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24465

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 537/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24466

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24467

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/24468

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24469

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24470

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 538/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/24473

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24491

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24492

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24493

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24494

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/24495

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 539/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 1,6M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/24496 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/24497 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/24498 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 18/24499 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Not inspected: not presented. Nature: SLING Serial number: 18/24500 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 540/1083

(see next page)



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/24810

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27101

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27102

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27103

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27104

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27105

Make: BENECA

Lenath: 1.6M

Year of manufacture: 2018 Maximum load: 2000KG

Sling (cable/synthetic)

Nature: SLING

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

Page: 541/1083

the material

(see next page)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Serial number: 18/27106

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27107

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27108

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27109

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27110

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27112

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 542/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Serial number: 18/27114

Year of manufacture: 2018

Maximum load: 2000KG

Make: BENECA

Length: 1,6M

Make: BENECA

Year of manufacture: 2018

Maximum load: 2000KG

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

FINDINGS

Length: 1,6M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/27113 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material

Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 18/27115

The material can be used, no abnormalities were found when inspecting the material

Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING

Serial number: 18/27491 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material

Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion

Serial number: 18/27492 The material can be used, no Make: BENECA

abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic) (see next page) Nature: SLING

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Serial number: 18/27493

Date of issue: 16/05/2023 Page: 543/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27494

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27495

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27496 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27497

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27498 Make: BENECA

Year of manufacture: 2018

Maximum load: 2000KG

Lenath: 1.6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic) Nature: SLING

Date of issue: 16/05/2023 Page: 544/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/27499

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27500

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/27501

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/27502

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27503

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/27504

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 545/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27505

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Sling (cable/synthetic)

Serial number: 18/31130

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Nature: SLING

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Make : BENECA
Year of manufacture : 2018
Maximum load : 2000KG

Length : 1,6M

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30281 Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30282

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30283

(see next page)

Date of issue: 16/05/2023 Page: 546/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30284

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30285

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30286

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30287

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30288

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Nature: SLING

Serial number: 19/30289

, , ,

Date of issue: 16/05/2023 Page: 547/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30290

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30291

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30292

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30293

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30294

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30295

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 548/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30296

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30297

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30298

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30299

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30300

(see next page)

Date of issue: 16/05/2023 Page: 549/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30301 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30302 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30303 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30304 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30305 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 550/1083

(see next page)



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30306

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30307

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30308

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30309

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30310

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30311

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 551/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30312

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30313

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30314

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30315

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30316

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 552/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30317

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30318

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30319

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30320

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Nature: SLING

Serial number: 19/30321

Sling (cable/synthetic)

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 553/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30322

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30323

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30324

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30325

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30326

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30327

Date of issue: 16/05/2023 Page: 554/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Make: BENECA * Conditions and operation inspection (07.2023) Not inspected: not presented. Year of manufacture: 2019 Maximum load: 2000KG Conclusion Length: 1,6M The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 19/30328 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30329 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30330 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30331 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Not inspected: not presented. Nature: SLING Serial number: 19/30332 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 555/1083

(see next page)



DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 19/30333 Make: BENECA Year of manufacture: 2019

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting	
Nature: SLING Serial number: 19/30334 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG		
	the material	
	Length: 1,6M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)	
Nature : SLING	Conclusion	
Serial number : 10/30335		

Serial number : 19/30335 Make: BENECA Year of manufacture: 2019

Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Serial number: 19/30336

Make: BENECA Year of manufacture: 2019

Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Serial number: 19/30337

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Make: BENECA

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) Nature: SLING

Serial number: 19/30338 Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 556/1083



Serial number : 19/30340 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Siling (cable/synthetic) Nature : SLING Serial number : 19/30342 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Siling (cable/synthetic) Nature : SLING Serial number : 19/30341 The material can be used, no abnormalities were found when inspecting the material Length : 1,6M Siling (cable/synthetic) Nature : SLING Serial number : 19/30342 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Siling (cable/synthetic) Nature : SLING Serial number : 19/30342 Maximum load : 2000KG Length : 1,6M Siling (cable/synthetic) Nature : SLING Serial number : 19/30343 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Siling (cable/synthetic) Not inspected: not presented. * Conclusion * Conclusion * Conclusion * Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service * Conclusion The material cannot be used anymore. The material cannot be used anymore. The material was not available during inspection of presented. * Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected; not presented. * Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected; not presented. * Conditions and operation inspection (07.2023) Not inspected; not presented. * Conditions and operation inspection (07.2023) Not inspected; not presented. * Conditions and operation inspection (07.2023) Not inspected; not presented.	DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 19/30339 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023)
Nature : SLING Serial number : 19/30341 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Maximum load : 2000KG Serial number : 19/30342 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30342 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30343 Make : BENECA Serial number : 19/30343 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Serial number : 19/30343 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30343 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M In material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is pection, or could only be partially inspected, an additional inspection is pection, or could only be partially inspected, an additional inspection is pection, or could only be partially inspected, an additional inspection is	Serial number : 19/30340 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG	abnormalities were found when inspecting the material
Sling (cable/synthetic) * Conditions and operation inspection (07.2023)	Nature: SLING Serial number: 19/30341 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG	Conclusion The material can be used, no abnormalities were found when inspecting
Nature : SLING Serial number : 19/30343 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Sling (cable/synthetic) Nature : SLING Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Serial number : 19/30344 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M Not inspected: not presented. Conclusion The material cannot be used anymore. The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service	Nature : SLING Serial number : 19/30342 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is
Nature: SLING Serial number: 19/30344 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is	Nature: SLING Serial number: 19/30343 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is
Sling (cable/synthetic) (see next page)	Nature: SLING Serial number: 19/30344 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 557/1083



Nature : SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 19/30345 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : 19/30346	The material can be used, no
Make: BENECA	·
Year of manufacture : 2019	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1,6M	*0 (27,000)
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 19/30347 Make : BENECA	The material can be used, no
Year of manufacture : 2019	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1,6M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 19/30348	The material can be used no
Make: BENECA	The material can be used, no
Year of manufacture : 2019	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1,6M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 19/30349	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2019	the material
Maximum load : 2000KG	
Length : 1,6M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 19/30350	The meterial can be used no
Make: BENECA	The material can be used, no
Year of manufacture : 2019	abnormalities were found when inspecting
Maximum load : 2000KG	the material
Length: 1,6M	
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature : SLING	Conclusion
Serial number : 19/30351	The material can be used, no
Make: BENECA	abnormalities were found when inspecting
Year of manufacture : 2019	the material
Maximum load : 2000KG	the material
Length: 1,6M	(see next page)
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 558/1083



DESCRIPTION OF THE DEVICES

Serial number: 19/30352

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30353

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30354

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30355

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

Conclusion

the material

Conclusion

Serial number: 19/30356

Nature: SLING

Make: BENECA

Sling (cable/synthetic)

Year of manufacture: 2019

Maximum load: 2000KG

Length: 1,6M

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30357

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1.6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Nature: SLING

Date of issue: 16/05/2023 Page: 559/1083



DESCRIPTION OF THE DEVICES

Serial number: 19/30358

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30359

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30360

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30361

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30362

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30363

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 560/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30364 Make : BENECA

Voor of manufactu

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30365

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30366

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30367

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30368

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30369

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 561/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30370

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30371

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30372

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30373

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30374

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30375

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 562/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30376

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30377

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30378

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30379

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30380

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 563/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 1,6M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30381 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30382 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 19/30383 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 19/30384 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30385 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M

Nature : SLING

Year of manufacture : 2019 Maximum load : 2000KG

Sling (cable/synthetic)

Serial number: 19/30386

Make: BENECA

Date of issue: 16/05/2023 Page: 564/1083

(see next page)



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30387

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30388

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30389

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30390

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 565/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30391

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30392

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30393

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30394 Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30395

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 566/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 19/30396 Conclusion Make: BENECA The material can be used, no Year of manufacture: 2019 abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30397 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30398 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 19/30399 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30400 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 19/30401

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30402

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 567/1083



DESCRIPTION OF THE DEVICES Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) Nature: SLING Serial number: 19/30403 Make: BENECA	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material *Conditions and operation inspection (07.2023) Conclusion The material can be used, no
Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M	abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : 1930404 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature: SLING Serial number: 19/30405 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	* Conditions and operation inspection (07.2023)
Nature: SLING Serial number: 19/30406 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Conclusion
Serial number : 19/30407 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	* Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 19/30408	Conclusion
Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 568/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIP	TION OF	THE	DEVICES
---------	---------	-----	---------

Nature: SLING

Serial number: 19/30409

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30410

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30411

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30412

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30413

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30414

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 569/1083



DESCRIPTION OF THE DEVICES

Serial number : 19/30415

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Condition

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30416

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30417

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30418

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30419

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30420

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30421

Date of issue: 16/05/2023 Page: 570/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30422

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30423

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30424

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30425

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 571/1083



Nature: SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 19/30426 Conclusion Make: BENECA The material can be used, no Year of manufacture: 2019 abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30427 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 19/30428 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30429 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 19/30430 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Lenath: 1.6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30431 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30432 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 572/1083



DESCRIPTION OF THE DEVICES

Serial number: 19/30433

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30434

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30435

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30436

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30437

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30438

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 573/1083



DESCRIPTION OF THE DEVICES Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30439 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30440 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30441 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30442 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30443 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service (see next page)

Date of issue: 16/05/2023 Page : 574/1083



DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 19/30444 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30445 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30446 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30447 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30448 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30449 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 575/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30450

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30451

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30452

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : 19/30453

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30454

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30455

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30456

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 576/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30457

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30458

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30459

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30460

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30461

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 577/1083



Sling (cable/synthetic)

Nature: SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 1,6M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30462 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 19/30463 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30464 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 19/30465 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Lenath: 1.6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30466 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 19/30467 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M

Date of issue: 16/05/2023 Page: 578/1083

(see next page)



DESCRIPTION OF THE DEVICES

Serial number: 19/30468

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30469

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30470

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30471

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30472

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30473

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 579/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30474

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30475

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30476

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30477

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30478

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 580/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30479

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30480

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30481

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30482

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30483

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 581/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30484

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30485

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30486

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30487

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30488

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30490

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 582/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30491

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30492

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30493

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30494

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30495

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30496

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 583/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30497

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30498

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30499

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30500

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30501

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M
Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 584/1083



DESCRIPTION OF THE DEVICES FINDINGS Nature: SLING * Conditions and operation inspection (07.2023) Serial number: 19/30502 Conclusion Make: BENECA The material can be used, no Year of manufacture: 2019 abnormalities were found when inspecting Maximum load: 2000KG the material Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30503 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 19/30504 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2019 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 1,6M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 19/30505 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2019 the material Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number: 19/30506

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) Nature: SLING

Serial number: 19/30507

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 585/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30508

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30510

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30511

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30512

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30513

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30514

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 586/1083



Nature : SLING

Serial number: 19/30520

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30515 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30516 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Serial number : 19/30517 Make : BENECA Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30518 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30519 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material (see next page)
Noture : SUNC	(See Hext page)

Date of issue: 16/05/2023 Page: 587/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30521

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30522

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30523

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) * Condition

Nature: SLING

Serial number: 19/30524

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30525

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 588/1083



DESCRIPTION OF THE DEVICES Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30526 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 1,6M Sling (cable/synthetic) Nature: SLING Serial number: 19/30527 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30528 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 19/30529 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 19/30530 Make: BENECA Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 589/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30531

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30532

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30533

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Serial number : 19/30534

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30535

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30536

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30537

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 590/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30538

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

the material

Conclusion

the material

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

abnormalities were found when inspecting

abnormalities were found when inspecting

required before re-service

The material can be used, no

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30539

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30540

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30541

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30542

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

(see next page)

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30543

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 591/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30544

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

the material

Conclusion

the material

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

abnormalities were found when inspecting

abnormalities were found when inspecting

required before re-service

The material can be used, no

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30545

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30546

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30547

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30548

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30549

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 592/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30550

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30551

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30552

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30553

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 593/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30554

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30555

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30556

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30557

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30558

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 594/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30559

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30560

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30561

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30562

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30563

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 595/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 19/30564

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 1930565

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30566

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30567

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30568

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 596/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30569

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30570

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30571

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30572

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30573

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 597/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 10/30574

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30575

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 19/30576

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30577

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30578

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 598/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30579

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30580

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30581

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30582 Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30583

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 599/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30584

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30585

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

tot mopostos. Hot proof

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 19/30586

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30587

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30588

Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 600/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 19/30589

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30590

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30591

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30592

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30593

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 601/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30594

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30595

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30596

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30597

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30598

Year of manufacture : 2019 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

Page: 602/1083

required before re-service

(see next page)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30599

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30600

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30601

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30602

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30603

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 603/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30604

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30605

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30606

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30607

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30608

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 604/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30609

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30610

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30611

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30612

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30613

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 605/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30614

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30615

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30617

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30618

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30619

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30620

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 606/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30621

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30622

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30623

Year of manufacture: 2019

Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30624

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30625

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 607/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30626

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30627

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30628

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30629

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30630

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30632

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Date of issue: 16/05/2023 Page: 608/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/30633

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30634

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30635

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30636

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30637

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30638

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 609/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30639

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30640

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30641

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30642

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30643

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30644

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 610/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30645

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30646

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30647

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30648

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 611/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30649

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30650

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30651

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30652

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30653

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 612/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30654

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30655

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30656

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30657

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30658

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 613/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30659

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30660

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30662

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30663

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30664

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30665

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 614/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30666

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30667

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30668

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30669

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30670

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 615/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30671

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30672

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30673

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30674

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30675

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 616/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30676

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30677

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30678

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30679

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30680

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 617/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30681

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30682

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30683

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30684

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30685

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 618/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30686

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30687

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30688

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30689

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30690

Year of manufacture : 2019 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 619/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30691

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30692

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30693

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30694

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30695

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 620/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30696

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30697

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30698

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30699

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30700

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 621/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30701

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30702

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30703

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30704

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30705

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 622/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30706

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30707

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30708

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30709

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30710

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 623/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30711

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30712

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30713

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30714

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30715

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 624/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30716

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30717

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30718

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30719

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30720

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30721

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 625/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30722

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30723

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30724

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30725

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30726

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30727

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 626/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30728

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30729

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30730

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30731

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30732

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30733

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 627/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30734

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30735

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30736

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30737

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30738

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 628/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30739

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30740

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30741

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30742

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30743

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 629/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30744

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30745

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30746

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30747

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30748

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 630/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30749

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30750

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30751

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30752

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30753

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30754

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 631/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30755

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30756

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30758

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30759

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30760

(see next page)

Date of issue: 16/05/2023 Page: 632/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30761

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30762

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30763

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30764

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30765

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30766

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 633/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30767

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30768

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30769

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30770

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 634/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30771

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30772

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30773

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30774

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30775

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30776

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 635/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30777

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30778

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30779

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30780

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30781

Year of manufacture: 2019 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 636/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30782

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30783

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30784

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30785

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30786

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 637/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30787

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30788

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30789

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30790

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30791

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30792

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30793

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 638/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30794

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30795

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30796

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30797

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30798

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 639/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30799

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30800

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30801

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30802

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30803

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30805

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 640/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30806

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30807

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30808

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30809

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30810

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30811

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30812

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 641/1083



DESCRIPTION OF THE DEVICES Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Client number of the equipment: 19/30813

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30814

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30815

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30816

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30817

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 642/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30818

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30819

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30820

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30821

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30822

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 643/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30823

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30824

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 18/30825

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 18/30826

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30827

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 644/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30828

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30829

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30830

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30831

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30832

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 645/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30833

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30834

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30835

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30836

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30837

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 646/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30838

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30839

Year of manufacture: 2019 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1,6M

Nature: SLING

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Conclusion

Make: BENECA The material can be used, no Client number of the equipment: 19/30840 abnormalities were found when inspecting Year of manufacture: 2019

the material

Conclusion

the material

Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic) Nature: SLING Make: BENECA

Client number of the equipment: 19/30841

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Nature: SLING Make: BENECA

Sling (cable/synthetic)

Client number of the equipment: 19/30842

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30843

Year of manufacture: 2019 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 647/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30844

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30845

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30846

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30847

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30848

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 648/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30849

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30850

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30851

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30852

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30853

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 649/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30854

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30855

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30857

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/30858 Make : BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30859

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30860

Year of manufacture : 2019 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 650/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Length: 1,6M	*Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Make: BENECA Client number of the equipment: 19/30861 Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Make: BENECA Client number of the equipment: 19/30862 Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Make: BENECA Client number of the equipment: 19/30863 Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Make: BENECA Client number of the equipment: 19/30864 Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Make: BENECA Client number of the equipment: 19/30865 Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 651/1083

(see next page)



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30866

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30867

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30868

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30869

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30870

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30871

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 652/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30872

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30873

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30874

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30875

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30876

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30877

Year of manufacture : 2019 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 653/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30878

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30879

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30880

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30881

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30882

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30883

Year of manufacture: 2019 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 654/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conclusion

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30884

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30885

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30886

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30887

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30888

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 655/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30889

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30890

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30891

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30893

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30894

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30895

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 656/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30896

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30897

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic) Nature: SLING Make: BENECA

Client number of the equipment: 19/30898

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30899

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30900

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30901

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 657/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Make: BENECA

Client number of the equipment: 19/30902

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30903

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30904

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30905

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30906

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30907

Year of manufacture: 2019 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 658/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30908

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30909

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30910

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30911

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30912

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 659/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30913

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30914

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30915

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30916

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30917

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30918

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30919

Year of manufacture : 2019 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

required before re-service

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 660/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30920

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30921

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30922

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30923

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30924

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 661/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30925

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30926

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30927

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30928

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/30929

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Lenath: 1.6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30930

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30931

16/05/2023

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic) Nature: SLING

Date of issue:

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

Page: 662/1083

the material

(see next page)



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/30932

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30933

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30934

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30935

Client number of the equipment: 19/30936

Year of manufacture: 2019 Maximum load: 2000KG

Sling (cable/synthetic)

Year of manufacture: 2019

Maximum load: 2000KG

Length: 1,6M

Nature : SLING Make : BENECA

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30937

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 663/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30938

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30939

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30940

Year of manufacture: 2019

Maximum load: 2000KG Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30941

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30942

Year of manufacture: 2019 Maximum load: 2000KG Lenath: 1.6M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 664/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/30943

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30944

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30945

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30947

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30948

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30949

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 665/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30950

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30951

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30952

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30953

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30954

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30955

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 666/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30956

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30957

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30958

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30959

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30960

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 667/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30961

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30962

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30963

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30964

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30965

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30966

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30967

Year of manufacture : 2019 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 668/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30968

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30969

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30970

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30971

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30972

Maximum load: 2000KG Length: 1,6M

Year of manufacture: 2019

Sling (cable/synthetic)

Nature: SLING Make: BENECA * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 669/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30973

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30974

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30975

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30976

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30977

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30978

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

Page: 670/1083

the material

(see next page)

Sling (cable/synthetic)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/30979

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30980

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30981

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30982

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30983

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30984

Year of manufacture : 2019 Maximum load : 2000KG Length : 1.6M

Year of manufacture : 2019

Sling (cable/synthetic)
Nature : SLING

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 671/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/30985

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30986

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30987

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30988

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/30989

Year of manufacture : 2019 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Length: 1,6M
Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 672/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/30990

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30991

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30992

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30993

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30994

Year of manufacture: 2019 Maximum load: 2000KG

Lenath: 1.6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30995

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30996

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Nature: SLING

Date of issue: 16/05/2023 Page: 673/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/30997

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

* Conditions and operation inspection (07.2023)

the material

the material

Conclusion

FINDINGS

Conclusion

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30998

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/30999

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31000

Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Year of manufacture: 2019

* Conditions and operation inspection (07.2023) Not inspected: not presented.

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31016

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31017

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

The material can be used, no

abnormalities were found when inspecting

the material

Conclusion

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Date of issue: 16/05/2023 Page: 674/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31018

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31019

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31020

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31021

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31023

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31024

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 675/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31025

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31026

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31027

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31028

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31029

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31030

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 676/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31031

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31032

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31033

Year of manufacture: 2019 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 1,6M

Nature: SLING Make: BENECA

Client number of the equipment: 19/31034

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31035

Year of manufacture: 2019 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 677/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31036

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31037

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31038

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)
Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31039

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

oquii ou boioi o i o coi i

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31040

Year of manufacture : 2019 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 678/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31041

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31042

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31043

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31044

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31045

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA (see next page)

Date of issue: 16/05/2023 Page: 679/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31046

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31060

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31061

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31062

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31063

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 680/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref. : 0001011189/10000

DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31064

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31065

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31066

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31067

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31068

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31069

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31070

Year of manufacture: 2019

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 681/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31071

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31072

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31073

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31074

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31075

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31076

Year of manufacture : 2019 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 682/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31077

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31078

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31079

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic) Nature: SLING Make: BENECA

Client number of the equipment: 19/31080

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31081

Year of manufacture: 2019 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 683/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31082

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31083

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31084

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31085

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31086

Year of manufacture: 2019 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 684/1083



DESCRIPTION OF THE DEVICES Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31087

Year of manufacture: 2019 Maximum load: 2000KG Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31088

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31089

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31090

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31091

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 685/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/31092

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31093

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31094

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31095

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31096

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31097

Year of manufacture : 2019 Maximum load : 2000KG Length : 1.6M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Nature: SLING

Date of issue: 16/05/2023 Page: 686/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/31098

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31099

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31100

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31101

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31102

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31103

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 687/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31104

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31105

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31106

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31107

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31108

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31109

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 688/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/31110

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31111

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31112

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31113

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31114

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31115

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Nature : SLING Make : BENECA

Date of issue: 16/05/2023 Page: 689/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31116

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31117

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31118

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31119

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31120

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31121

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Date of issue: 16/05/2023 Page: 690/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31122

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31123

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31124

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31125

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31126

Year of manufacture: 2019 Maximum load: 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: 19/31127

Year of manufacture: 2019 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 691/1083



DESCRIPTION OF THE DEVICES

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31128

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31129

Year of manufacture : 2019 Maximum load : 2000KG The material can be used, no

Conclusion

abnormalities were found when inspecting

the material

Length: 1,6M
Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31130

Year of manufacture : 2019 Maximum load : 2000KG Length : 1,6M * Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31131

Year of manufacture : 2019 Maximum load : 2000KG Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31132

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

(see next page)

Date of issue: 16/05/2023 Page: 692/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Client number of the equipment: 19/31133

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31134

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31135

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31136

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/3137

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA (see next page)

Date of issue: 16/05/2023 Page: 693/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: 19/31138

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31139

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31140

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31241

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31242

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 694/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 19/31243

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31244

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31245

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31246

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31247

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 19/31248

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 1931249

(see next page)

Date of issue: 16/05/2023 Page: 695/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

Sling (cable/synthetic)

Nature: SLING

Serial number : 19/31250

Make: BENECA

Year of manufacture : 2019 Maximum load : 2000KG

Length: 1,6M

SOFT STEELS 2000KG - 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0002 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Lenath: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0003 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0005 Make : BENECA

Year of manufacture: 2009

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 696/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0006 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0007 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0009 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0010 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0011 (see next page)

Date of issue: 16/05/2023 Page: 697/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0012 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0013 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0014 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0015 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 698/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0016 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0017 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0018 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0019 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0021 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 699/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0022 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0023 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0024 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0025 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0027 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 700/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0028 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0029 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0030 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0031 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0032 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 701/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0033 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0034 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0035 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0036 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0037 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 702/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0038 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0039 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0040 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0041 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0042 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 703/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0043 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0044 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0045 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0047 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0048 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 704/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0049 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0050 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0051 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0053 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0054 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 705/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0055 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0056 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0057 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0058 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0059 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 706/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0060 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0061 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0062 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0063 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0064 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 707/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0065 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0066 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0067 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0068 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0069 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

(see next page)

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 708/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0070 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0071 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0072 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0073 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0074 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 709/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0075 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0076 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0077 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0078 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0079 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 710/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0080 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0081 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0082 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0083 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0084 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 711/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0085 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0086 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0087 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0088 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0089 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 712/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0090 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0091 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0092 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0093 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0094 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 713/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0095 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0096 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0097 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0098 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0099 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 714/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0100 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING Serial number: A0101 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING Serial number: A0102 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING Serial number: A0103 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING Serial number: A0104 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

(see next page)

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 715/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0105 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0106 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0107 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0108 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0109 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 716/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0110 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0111 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0112 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0113 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0114 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 717/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0115 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0116 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0117 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Make: BENECA

Client number of the equipment: A0118

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0119 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 718/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0121 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0122 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0123 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0124 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0126 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 719/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0127 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0128 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0131 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0132 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0133 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 720/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0134 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0135 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0136 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0137 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0138 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0139 **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 721/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0140 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0141 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0142 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0143 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 722/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0144 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0145 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0146 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0147 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0148 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 723/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0149 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0150 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0151 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0152 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0153 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 724/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0154 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0155 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0156 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0157 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0160 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0161 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 725/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0162 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0163 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0164 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0165 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length : 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING Serial number : A0166

Date of issue: 16/05/2023 Page: 726/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0168 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0169 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0170 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0171 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 727/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 172

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 174

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 175

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 176

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 177

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 728/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 178

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 179

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 181

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 183

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 184

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 729/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 185

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 186

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0187 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 188

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0189 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 730/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 190

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 191

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 192

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 193

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 194

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 731/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 195

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 197

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 198

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 199

Year of manufacture: 2009 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 201

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 732/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 202

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 203

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 205

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 207

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 208

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 733/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 209

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 210

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 211

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 213

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 214

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 734/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 215

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A0216 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 217

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 218

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 219

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 735/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 220

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 221

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 222

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 223

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 224

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 736/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 225

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 226

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 227

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 228

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 229

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 737/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 235

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 236

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 237

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 239

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 240

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 738/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 241

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 242

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 243

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 244

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 245

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 739/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 246

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 247

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 248

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 249

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 250

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 740/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 251

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 253

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 254

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 256

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 257

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 741/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 258

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 259

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 260

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 261

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 262

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 742/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 264

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 265

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 267

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 269

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 270

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 743/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 271

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 272

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 273

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 277

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 279

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 744/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 280

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 281

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 282

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 283

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 284

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 745/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 285

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 286

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 287

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 288

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 289

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 746/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 290

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 291

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 293

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 294

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 295

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 747/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: 297

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: 298

Year of manufacture : 2009 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 002

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 004

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 005

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 748/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 006

Make : BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 007

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

tot mopostod. Hot procen

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 008

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 009

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 010

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 749/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: 2011 011 Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 012

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 013

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 014

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 015

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 017

(see next page)

Date of issue: 16/05/2023 Page: 750/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 018

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 019

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 020

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 021

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 751/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 022 Make : BENECA

Year of manufacture : 2011

Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 023

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

tot mopootoa. Not procent

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 024

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 025

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 027

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 752/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 029

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 031

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 032

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 033

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 034

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 753/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 036

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 037

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 038

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 039

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 040

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 042

(see next page)

Date of issue: 16/05/2023 Page: 754/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 043

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 044

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 045

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 046

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 755/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 048

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 049

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 050

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 053

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 054

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 756/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 055

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 056

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)
Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 057

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 058

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 059

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 062

(see next page)

Date of issue: 16/05/2023 Page: 757/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 063

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 064

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 066

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 068

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 758/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 069

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 070

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 071

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 072

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 073

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 759/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 074

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 075

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 076

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 077

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 078

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 760/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 079

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 080

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 081

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 082

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 084

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 085

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 761/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 086

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 087

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 088

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 089

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 762/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 090

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 092

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 093

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 094

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 095

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 097

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 763/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 2011 098

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 099

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 100

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 101

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 102

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 764/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 103

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 104

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 106

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 107

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 109

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 110

(see next page)

Date of issue: 16/05/2023 Page: 765/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 111

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 112

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 113

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 115

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 116

(see next page)

Date of issue: 16/05/2023 Page: 766/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 118

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 119

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 120

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 121 Make: BENECA

Year of manufacture: 2011

Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 767/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 122

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 123

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 124

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 125

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 127

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 128

(see next page)

Date of issue: 16/05/2023 Page: 768/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 129

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 130

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 131

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 132

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 133

(see next page)

Date of issue: 16/05/2023 Page: 769/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 134

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 135

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 136

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 137

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 770/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 138

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 140

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 141

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 142

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 143

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 771/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 144

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 146

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 2011 147

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 148

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 149

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 772/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 2011 150

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 152

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 153

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 154

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 156

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 157

(see next page)

Date of issue: 16/05/2023 Page: 773/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 158

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 160

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 161

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 162

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 774/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 163

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 164

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 165

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 166

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 167

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 168

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 775/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 169

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 170

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 171

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 173

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 776/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : 2011 174

Make - DENECA

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 175

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

rtot mopootod. Not procont

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 176

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 178

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 179

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 777/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number : 2011 180

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 181

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 182

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 183

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 184

Make : BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 185

(see next page)

Date of issue: 16/05/2023 Page: 778/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 186

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature : SLING

Serial number : 2011 187

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 188

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 189

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 190

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 779/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 191

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 193

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 194

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 195

Make: BENECA

Year of manufacture: 2011 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 780/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: 2011 196

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

Not inspected

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 2011 197

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 198

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 2011 200

Make: BENECA

Year of manufacture : 2011 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 001

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 781/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 002

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 003

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 004

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

Serial number: A 13 200 005

Make: BENECA

Nature: SLING

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

The material can be used, no abnormalities were found when inspecting the material

abnormalities were found when inspecting

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 006

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 007

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 782/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 008

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 010

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 011

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 015

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 016

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 783/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 200 017

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

abnormalities were found when inspecting

abnormalities were found when inspecting

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 018

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 2M

The material can be used, no

The material can be used, no

Conclusion

the material

the material

Conclusion

Conclusion

Serial number : A 13 200 019

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 020

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 021

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 022

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 784/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 023

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 024

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 025

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 026

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 027

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 028

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 785/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 029

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 030

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 031

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 032

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 033

(see next page)

Date of issue: 16/05/2023 Page: 786/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 034

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 035

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 036

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 038

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 787/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 039

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 041

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 042

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 044

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 046

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 047

(see next page)

Date of issue: 16/05/2023 Page: 788/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 048

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 049

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 050

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 051

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 789/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 053

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 054

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 057

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 059

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 060

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 061

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 790/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 062

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 063

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 064

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 065

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 067

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 068

(see next page)

Date of issue: 16/05/2023 Page: 791/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 069

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 071

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

the material

The material can be used, no

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 072

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 073

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 074

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 792/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 077

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 079

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 080

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 081

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 082

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 085

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 793/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 086

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 087

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 089

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 090

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 091

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 092

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 794/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 094

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A13 200 095

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 096

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 097

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 098

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 099

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 795/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 100

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 101

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 102

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 103

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 104

(see next page)

Date of issue: 16/05/2023 Page: 796/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 105

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 106

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 107

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 108

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 109

(see next page)

Date of issue: 16/05/2023 Page: 797/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 111

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 112

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 113

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 114

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 798/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 115

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 117

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 118

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 120

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 122

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 123

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 799/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 124

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 125

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 126

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 128

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 129

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 800/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 130

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A13 200 131

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 132

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 133

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 136

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 138

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 801/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 139

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 141

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 142

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 143

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 802/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 144

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 145

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 147

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 148

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 149

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 150

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 803/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 151

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 152

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 153

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 200 154

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 155

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 157

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 804/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 158

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 159

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 160

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 162

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 164

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 166

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 805/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 167

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 168

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 169

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 170

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 171

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 173

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 806/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 174

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 175

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 176

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 177

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 178

(see next page)

Date of issue: 16/05/2023 Page: 807/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 179

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 181

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

the material

The material can be used, no

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 183

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 184

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 185

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 808/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 186

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 187

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 188

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 189

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 190

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 191

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 809/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 194

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 195

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 196

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 197

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 810/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 200

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 201

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 202

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 2M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

the material

Serial number: A 13 200 203

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

The material can be used, no abnormalities were found when inspecting the material

tric material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 204

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 206

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 811/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 207

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 208

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 209

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 210

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 211

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 212

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 812/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 213

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 214

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 215

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 216

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 217

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 813/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 2M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 200 218 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 200 219 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service Sling (cable/synthetic) Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 200 220 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 200 222 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 200 223 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013

Sling (cable/synthetic)

Maximum load: 2000KG

Length: 2M

(see next page)

material was not available during

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

Date of issue: 16/05/2023 Page: 814/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 224

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 229

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 230

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 231

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 232

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 815/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 233

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 237

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 238

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 239

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 240

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 242

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 816/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 243

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 244

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 245

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 247

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 248

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 249

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 817/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 251

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 254

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 255

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 256

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 818/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 258

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 259

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 260

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 261

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 262

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 263

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 819/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 264

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 268

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 269

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 200 270

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 271

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 272

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 820/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 273

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 274

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 275

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 276

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 277

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 821/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 278

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 279

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 280

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 282

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 283

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 284

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 822/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 285

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 286

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 287

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 288

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 291

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 292

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 823/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 293

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 294

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 295

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 296

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 297

(see next page)

Date of issue: 16/05/2023 Page: 824/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 298

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 299

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 300

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 301

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 302

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 825/1083



Sling (cable/synthetic)

Nature: SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 2M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: A 13 200 304 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 200 305 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 306 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 200 307 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: A 13 200 308 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Lenath: 2M

Date of issue: 16/05/2023 Page: 826/1083

(see next page)



DESCRIPTION OF THE DEVICES

Serial number: A 13 200 309

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 311

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 2M

Nature: SLING

Serial number: A 13 200 312

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 315

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 316

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 317

(see next page)

Date of issue: 16/05/2023 Page: 827/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 320

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 323

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 324

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 328

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 828/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 13 200 331

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 332

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 333

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 335

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 336

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 339

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 829/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 340

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 341

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 342

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 343

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 349

(see next page)

Date of issue: 16/05/2023 Page: 830/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 350

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

tot mopostod. Hot procen

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 351

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 353

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 354

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 356

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 831/1083



DESCRIPTION OF THE DEVICES Length: 2M	*Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 359 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 361 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 363 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 364 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 369 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 832/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 370

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 371

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 372

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 373

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 374

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 375

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 378

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 833/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 379

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 380

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 381

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 383

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 384

(see next page)

Date of issue: 16/05/2023 Page: 834/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 385

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 386

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 387

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Serial number: A 13 200 389

Year of manufacture: 2013

Maximum load: 2000KG

Length: 2M

Nature: SLING

Make: BENECA

Length: 2M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 390

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 835/1083



Maximum load: 2000KG

Sling (cable/synthetic)

Lenath: 2M

Nature: SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 2M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: A 13 200 391 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 200 393 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 200 394 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: A 13 200 395 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 2M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: A 13 200 396 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013

Date of issue: 16/05/2023 Page: 836/1083

the material

(see next page)



DESCRIPTION OF THE DEVICES

Serial number : A 13 200 398

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 399

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 400

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 401

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 405

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 407

(see next page)

Date of issue: 16/05/2023 Page: 837/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 408

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 412

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 13 200 413

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 414

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 415

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 838/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 416

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 417

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 419

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 421

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 422

(see next page)

Date of issue: 16/05/2023 Page: 839/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 424

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 425

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 426

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 427

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 429

(see next page)

Date of issue: 16/05/2023 Page: 840/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 432

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 435

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 436

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 437

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 438

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 841/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 441

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 442

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 444

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 445

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 446

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 447

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 842/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 448

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 449

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

The material can be used, no

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 451

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 452

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 453

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 455

(see next page)

Date of issue: 16/05/2023 Page: 843/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 456

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 457

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 458

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 459

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 461

Date of issue: 16/05/2023 Page: 844/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 462

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 463

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 466

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 467

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 470

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 845/1083



DESCRIPTION OF THE DEVICES Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 471 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 476 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023) Not inspected: not presented.
Nature: SLING Serial number: A 13 200 477 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A 13 200 478 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: A13 200 479 Make: BENECA Year of manufacture: 2013 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 846/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 480

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 481

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 482

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 483

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 485

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 847/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 200 486

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 488

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 200 490

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 491

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 492

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 200 493

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 848/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 200 494

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 496

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 497

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG Length : 2M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 499

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 200 500

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 849/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 004

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 005

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 006

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 007

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 009

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 010

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 850/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 012

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 013

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 014

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Conclusion

The material can be used, no

Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 015

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 016

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see n

Nature: SLING

Serial number : A 14 200 019

(see next page)

Date of issue: 16/05/2023 Page: 851/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 020

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 021

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 022

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 024

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 852/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 026

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 028

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 029

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 030

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 031

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 032

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 853/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 033

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 034

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 035

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 036

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 854/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 038

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Nature: SLING

Serial number: A 14 200 039

Sling (cable/synthetic)

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 040

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic) Conditions and operation inspection (07.2023)

Nature: SLING

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Serial number: A 14 200 041

Length: 2M

required before re-service

Sling (cable/synthetic) Nature: SLING

Serial number: A 14 200 042

Make: BENECA

Year of manufacture: 2014

Length: 2M

material was not available during Maximum load: 2000KG

Sling (cable/synthetic) (see next page)

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The inspection, or could only be partially inspected, an additional inspection is

required before re-service

Date of issue: 16/05/2023 Page: 855/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 043

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 044

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 045

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 046

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 047

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 048

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 856/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 049

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 050

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 051

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 052

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 054

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 056

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 857/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 057

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 058

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 059

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 060

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 061

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 858/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 062

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 063

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 064

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 14 200 066

Make: BENECA

Nature: SLING

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 067

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 068

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 859/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 069

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 070

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 071

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 072

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 073

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 074

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Condition

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 860/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 076

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 077

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

The material can be used, no

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 078

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 079

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 080

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during increasing are sould only be partially.

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 081

(see next page)

Date of issue: 16/05/2023 Page: 861/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 082

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 083

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 084

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 086

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 088

(see next page)

Date of issue: 16/05/2023 Page: 862/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 089

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 090

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Serial number : A 14 200 091

Make: BENECA

Nature: SLING

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 092

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 093

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 863/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 095

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 096

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 097

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 14 200 098

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 099

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 100

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 101

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 864/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 102

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 103

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 105

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 106

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 865/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 107

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 108

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 109

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

The material can be used, no

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 110

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 111

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 112

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 866/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 114

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 115

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 116

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 117

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 119

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 867/1083



DESCRIPTION OF THE DEVICES

Nature : SLING

Serial number: A 14 200 120

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 121

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 122

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 123

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 124

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 125

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 868/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 126

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 127

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

The material can be used, no

The material can be used, no

The material can be used, no

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 129

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion

the material

the material

Nature: SLING

Serial number: A 14 200 131

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Nature: SLING Serial number: A 14 200 132 Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Conclusion

abnormalities were found when inspecting

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 133

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 869/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 134

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 139

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 140

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 141

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 142

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 143

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 870/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 144

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 145

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 146

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 147

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 871/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 148

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 149

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

the material

the material

Conclusion

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 150

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

+0 111 1 1 (07.000)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 151

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

The material cannot be used anymore. The

abnormalities were found when inspecting

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 153

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 154

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

(see next page)

Date of issue: 16/05/2023 Page: 872/1083



DESCRIPTION OF THE DEVICES

Serial number: A 14 200 155

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 156

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 157

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 158

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 159

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 160

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 873/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 162

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 163

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 164

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 165

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 166

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 874/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 167

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 168

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 169

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 170

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 171

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 875/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 172

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 173

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 174

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 175

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 176

Date of issue: 16/05/2023 Page: 876/1083



/INCOTTE

DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 180

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 181

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 182

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 183

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 185

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 877/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 187

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 188

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 190

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 192

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 193

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 878/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 14 200 195

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 14 200 197

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 14 200 198

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 14 200 200

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : RDB 61205

Make : BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 879/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: RDB 68119

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : RDB35070

Make: BENECA

Year of manufacture : 2014 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/24357

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27108

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/27110

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 880/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/27916

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28251

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28252

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Conclusion

* Conditions and operation inspection (07.2023)

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28253

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28254

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28256

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 881/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28257

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28258

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28259

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28260

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28261

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023

Page: 882/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28262

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28263

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28264

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28265

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28266

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28267

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28268

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 883/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28269

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28270

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/28271

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28272

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28274

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 884/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28275

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28276

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28277

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28278

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28279

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28280

Date of issue: 16/05/2023 Page: 885/1083



DESCRIPTION OF THE DEVICES FINDINGS Make: BENECA * Conditions and operation inspection (07.2023) Year of manufacture: 2018 Conclusion Maximum load: 2000KG The material can be used, no Length: 2M abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 18/28281 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 18/28282 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018 the material Maximum load: 2000KG Length: 2M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/28284 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 18/28285 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2018 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 2M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: 18/28286 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2018

Sling (cable/synthetic)

Maximum load: 2000KG

Nature : SLING

Length: 2M

Serial number: 18/28287

(see next page)

the material

Date of issue: 16/05/2023 Page: 886/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28288

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28289

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28290

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28291

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28292

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 887/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28293

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28294

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28295

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28296

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28297

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 888/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28298

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28299

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28300

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28301

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28302

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 889/1083



DESCRIPTION OF THE DEVICES Length: 2M	* Conditions and operation inspection (07.2023) Conclusion
	The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/28303 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M Sling (cable/synthetic) Nature: SLING Serial number: 18/28305 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/28306 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/28307 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/28308 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material (see next page)

Date of issue: 16/05/2023 Page: 890/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/28309

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28310

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28311

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28313

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28314

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28315

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 891/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28316

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28317

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28318

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

the material

Conclusion

Serial number: 18/28319

Sling (cable/synthetic)

Make: BENECA

Nature: SLING

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28320

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28321 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Sling (cable/synthetic)

Nature: SLING

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 892/1083



DESCRIPTION OF THE DEVICES

Serial number: 18/28322

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

<u>FINDINGS</u>

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28323

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28324

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28325

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28326

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28327

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 893/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28328

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28329

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28330

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING Serial number : 18/28331

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28332

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28333

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 894/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28334

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28335

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28336

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28338

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Nature: SLING

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Serial number : 18/28339 Conclusion

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28340

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 895/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28341

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28342

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28343

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28344

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28345

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 896/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28347

Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28348

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28349

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28350 Make: BENECA

Year of manufacture: 2014 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 897/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28351 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28352

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28353

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28354

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28356

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28357

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

required before re-service

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 898/1083



DESCRIPTION OF THE DEVICES Length: 2M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 18/28358 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M Sling (cable/synthetic) Nature: SLING	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023) Not inspected: not presented.
Serial number : 18/28360 Make : BENECA Year of manufacture : 2018 Maximum load : 2000KG Length : 2M	Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/28361 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Length: 2M Sling (cable/synthetic) Nature: SLING Serial number: 18/28362 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 18/28363 Make: BENECA Year of manufacture: 2018 Maximum load: 2000KG Length: 2M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Date of issue: 16/05/2023 Page: 899/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/28364

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Condition

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28365

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/28366

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28367

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)
Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28368

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28369

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 900/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28370

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28371

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28372

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28373

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28374

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28375

(see next page)

Date of issue: 16/05/2023 Page: 901/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28376

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28377

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28378

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28379

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28380

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 902/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28382

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28383

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28384

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28385

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28387

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28388

Make: BENECA

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 903/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28391

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28392

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28393

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/28394

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28395

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/28396

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 904/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28397

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 18/28398

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28400

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28401

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 905/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28402

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28403

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28405

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28406

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28407 Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28410

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28411

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 906/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28412

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28413

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28414

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28415

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28416

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 907/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28417

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28418

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28419

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28420

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28421

(see next page)

Date of issue: 16/05/2023 Page: 908/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28422

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28423

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28424 Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

•

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING Not inspected: not presented.

Serial number : 18/28425

Make : BENECA

Year of manufacture : 2018

Maximum load : 2000KG

Length: 2M

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28426

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 909/1083



DESCRIPTION OF THE DEVICES

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28427

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28428

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28429

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG Length : 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28430

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28431 Make : BENECA

Year of manufacture : 2018

Maximum load : 2000KG Length : 2M * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 910/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 18/28432

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28433

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28434

Make : BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28435

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28436

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28437

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28438

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 911/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28439

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

The material can be used, no

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28440

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

Nature: SLING

* Conditions and operation inspection (07.2023)

Conclusion

Serial number: 18/28441

Sling (cable/synthetic)

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28442

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28443

Make: BENECA

Year of manufacture: 2018 Maximum load: 2000KG

Lenath: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 912/1083



DESCRIPTION OF THE DEVICES

Serial number : 18/28444

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number : 18/28445

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 18/28446

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28447

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28448

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 18/28449

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Sling (cable/synthetic)

Length : 2M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 913/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number : 18/28450

Make: BENECA

Year of manufacture : 2018 Maximum load : 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

SOFT STEELS 2000KG - 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0001 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0003 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0004 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0005 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 914/1083



DESCRIPTION OF THE DEVICES

Serial number: A0011 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0013 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0015 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0016 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0018 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 915/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0019 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0020 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0021 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0022 Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0023 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0024 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 916/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0025 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0026 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0027 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0028 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 917/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0030 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0031 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0032 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0034 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0035 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0036 **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 918/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0038 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0039 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0040 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0041 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0042 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 919/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0043 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0044 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0045 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0046 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M
Sling (cable/synthetic)

Nature : SLING Serial number : A0049 * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

ine material

(see next page)

Date of issue: 16/05/2023 Page: 920/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0050 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0051 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0052 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0053 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0054 (see next page)

Date of issue: 16/05/2023 Page: 921/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0055 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0056 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0057 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0058 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0059 (see next page)

Date of issue: 16/05/2023 Page: 922/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0061 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0062 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0064 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0065 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 923/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0066 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0067 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0068 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0069 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0072 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A0073

Year of manufacture : 2009 Maximum load : 2000KG Length : 3M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 924/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Make : BENECA

Client number of the equipment: A0074

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0075 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0078 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0082 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0084 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0088 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 925/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0089 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0091 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0092 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0093 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 926/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0094 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0096 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A0097

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0098 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0099 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0100 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 927/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0102 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0103 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0104 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0105 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0106 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 928/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0107 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0108 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0109 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0110 Make : BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0111 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M Sling (cable/synthetic)

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 929/1083



DESCRIPTION OF THE DEVICES

Nature : SLING Serial number : A0112 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Not inspected: not presented.

FINDINGS

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0113 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0114 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0115 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0116 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0117 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 930/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0118 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0119 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0120 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0121 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0122 (see next page)

Date of issue: 16/05/2023 Page: 931/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0123 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0124 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0125 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING Serial number: A0126 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0128 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 932/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0129 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0130 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0131 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0132 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 933/1083



DESCRIPTION OF THE DEVICES

Nature: SLING Serial number: A0133 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0134 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0135 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0136 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING Serial number: A0139 Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Sling (cable/synthetic)

Nature: SLING Serial number: A0140 * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 16/05/2023 Page: 934/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2009 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0141 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0142 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0143 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0144 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A0145 Make : BENECA **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 935/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING Serial number : A0147 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING Serial number : A0148 Make : BENECA

Year of manufacture : 2009 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 001

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 002

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 003

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 936/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 004

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 005

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 3M

The material can be used, no

Conclusion

Conclusion

the material

Serial number : A 13 300 006

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 007

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 008

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Lenath: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 937/1083



DESCRIPTION OF THE DEVICES

Serial number : A 13 300 009

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 010

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 011

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 012

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 013

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 014

Date of issue: 16/05/2023 Page: 938/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 016

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 017

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 018

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 019

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 020

(see next page)

Date of issue: 16/05/2023 Page: 939/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 021

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 022

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 023

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 024

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 025

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 940/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 026

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 027

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 028

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : A 13 300 029

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 030

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 031

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or sould only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 941/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 032

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 034

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 035

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Serial number : A 13 300 036

Make: BENECA

Nature: SLING

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number : A 13 300 037

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Conclusion

Oonerasion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature : SLING

Serial number: A 13 300 038

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Sling (cable/synthetic)

Length: 3M

The material can be used, no

Conclusion

abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 942/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 039

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 040

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 041

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 042

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 043

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 044

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 943/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 045

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 046

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 047

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 048

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 049

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 944/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 050

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 051

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

The material can be used, no

The material can be used, no

abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 052

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Sling (cable/synthetic)

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

Serial number: A 13 300 053

Make: BENECA

Nature: SLING

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

The material can be used, no abnormalities were found when inspecting the material

abnormalities were found when inspecting

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 054

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 055

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Lenath: 3M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Date of issue: 16/05/2023 Page: 945/1083



DESCRIPTION OF THE DEVICES

Serial number: A 13 300 057

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 058

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 059

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 060

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 061

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 946/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 063

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 064

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 065

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 066

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 067

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 068

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 947/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 069

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 070

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 071

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 072

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 073

Make: BENECA

(see next page)

Date of issue: 16/05/2023 Page: 948/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling	(cabl	le/syı	nthetic	;)
-------	-------	--------	---------	----

Nature: SLING

Serial number: A 13 300 074

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 075

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 076

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 077

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 079

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 949/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 080

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 081

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 082

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 083

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 085

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 086

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 950/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 3M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 300 087 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 300 088 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service Sling (cable/synthetic) Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 300 089 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 300 090 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013

Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 091

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 951/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 092

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 093

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 094

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 095

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 096

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 097

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 952/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 098

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 099

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 101

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 102

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 103

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 104

Date of issue: 16/05/2023 Page: 953/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 105

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 107

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 108

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 109

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 110

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 954/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 111

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 112

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 113

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 114

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 115

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 116

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 955/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 117

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 118

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 119

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 120

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 121

(see next page)

Date of issue: 16/05/2023 Page: 956/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 122

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 123

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 124

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 125

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 126

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 957/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 127

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 128

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 129

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 130

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 131

Date of issue: 16/05/2023 Page: 958/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 132

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 133

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 134

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 135

Make : BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 136

(see next page)

Date of issue: 16/05/2023 Page: 959/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 137

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 138

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 140

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 142

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 143

Date of issue: 16/05/2023 Page: 960/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 144

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 145

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 146

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 147

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 148

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 961/1083



Length: 3M

Nature: SLING

Sling (cable/synthetic)

Serial number: A 13 300 154

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 3M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: A 13 300 149 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: A 13 300 150 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 300 151 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: A 13 300 152 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2013 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Nature: SLING Conclusion Serial number: A 13 300 153 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013 the material Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 962/1083

(see next page)



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 155

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 157

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 158

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 159

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 160

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 963/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 161

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Serial number: A 13 300 162 Make: BENECA

Nature: SLING

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 163

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 164

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 165

(see next page)

Date of issue: 16/05/2023 Page: 964/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 166

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

abnormalities were found when inspecting

required before re-service

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 167

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING Conclusion

Serial number: A 13 300 168

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M Sling (cable/synthetic)

Nature: SLING

* Conditions and operation inspection (07.2023)

Conclusion

the material

Serial number: A 13 300 169 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2013

the material Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 171

Make: BENECA

Year of manufacture: 2013 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 965/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 172

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Make : BENECA

Client number of the equipment: A 13 300 173

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 174

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 175

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 176

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 177

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 966/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 178

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 179

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 181

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 182

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 183

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 967/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 184

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 185

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 186

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 187

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 188

Date of issue: 16/05/2023 Page: 968/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 189

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 190

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 191

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 192

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 969/1083



DESCRIPTION OF THE DEVICES
Nature: SLING

Serial number: A 13 300 193

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number : A 13 300 194

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: A 13 300 195

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: A 13 300 196

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 197

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 198

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 970/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: A 13 300 199

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : A 13 300 200

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: ROB 68148

Make: BENECA

Year of manufacture : 2013 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/20801 Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/20813

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 971/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/20815

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20817

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20833

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20854 Make: BENECA

Year of manufacture: 2017

Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20861

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/20863

(see next page)

Date of issue: 16/05/2023 Page: 972/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22809

Make: BENECA

Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22861

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : 17/22862

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22863

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22864

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic) (see next page)

Date of issue: 16/05/2023 Page: 973/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/22865

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22866

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22867

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Nature: SLING

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

Serial number : 17/22868

Sling (cable/synthetic)

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22870

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22871 Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Lenath: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature : SLING

(see next page)

Date of issue: 16/05/2023 Page: 974/1083



DESCRIPTION OF THE DEVICES

Serial number: 17/22872

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22873

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22874

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22875 Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Sling (cable/synthetic)

Serial number: 17/22876

Year of manufacture: 2017

Maximum load: 2000KG

Length: 3M

Nature: SLING

Make: BENECA

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22877

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 975/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22878

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22879

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22880

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22881

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22882

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22883

Date of issue: 16/05/2023 Page: 976/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22884

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22885

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22886 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Sling (cable/synthetic)

Serial number: 17/22887

Year of manufacture: 2017

Maximum load: 2000KG

Length: 3M

Nature: SLING

Make: BENECA

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22888

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 977/1083



Year of manufacture: 2017

Maximum load: 2000KG

Sling (cable/synthetic)

Lenath: 3M

Nature: SLING

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Length: 3M * Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 17/22889 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 17/22890 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2017 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 17/22891 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Nature: SLING Conclusion Serial number: 17/22892 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 2000KG Length: 3M * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 17/22893 The material can be used, no Make: BENECA abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 978/1083



DESCRIPTION OF THE DEVICES

Serial number: 17/22894

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22895

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22896

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING Serial number : 17/22897

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number : 17/22898

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22899

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22900

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 979/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22909

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22910

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22911

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22912

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22913

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 980/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/22914

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22915

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

The material can be used, no abnormalities were found when inspecting

The material can be used, no

the material

Conclusion

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22916

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

Nature: SLING Serial number: 17/22917

Make: BENECA

Sling (cable/synthetic)

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22918

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22919

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

(see next page)

Date of issue: 16/05/2023 Page: 981/1083



DESCRIPTION OF THE DEVICES

Serial number: 17/22920

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22921

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

inspected, an additional inspection is

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22922

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22923

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22924

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22926

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG (see next page)

Date of issue: 16/05/2023 Page: 982/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22927

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22928

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22929

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22930

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22931

(see next page)

Date of issue: 16/05/2023 Page: 983/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/22932

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22934

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

the material

The material can be used, no

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

Conclusion

the material

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

required before re-service

The material can be used, no

The material can be used, no

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22949

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number : 17/22950

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Nature: SLING

Serial number : 17/22951 Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

Obligations and operation inspection (07.2025)

* Conditions and operation inspection (07.2023)

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature : SLING

Serial number : 17/22952

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Date of issue: 16/05/2023 Page: 984/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22953

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22954

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22955

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22956

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22957

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22958

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 985/1083



DESCRIPTION OF THE DEVICES FINDINGS Length: 3M * Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 17/22959 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2017 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: SLING Serial number: 17/22960 Conclusion Make: BENECA The material cannot be used anymore. The Year of manufacture: 2017 material was not available during Maximum load: 2000KG inspection, or could only be partially Length: 3M inspected, an additional inspection is required before re-service * Conditions and operation inspection (07.2023) Sling (cable/synthetic) Conclusion Nature: SLING Serial number: 17/22961 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 2000KG Length: 3M Sling (cable/synthetic) * Conditions and operation inspection (07.2023) Conclusion Nature: SLING Serial number: 17/22962 The material can be used, no Make: BENECA abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 2000KG Length: 3M

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22963

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 986/1083



Sling (cable/synthetic)

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES Nature: SLING Serial number: 17/22964 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 17/22965 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M Sling (cable/synthetic)	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material * Conditions and operation inspection (07.2023)
Nature: SLING Serial number: 17/22966 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M	Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 17/22967 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M	* Conditions and operation inspection (07.2023) Conclusion The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature: SLING Serial number: 17/22968 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature: SLING Serial number: 17/22969 Make: BENECA Year of manufacture: 2017 Maximum load: 2000KG Length: 3M	* Conditions and operation inspection (07.2023) Not inspected: not presented. Conclusion The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 987/1083

(see next page)



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/22970

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22971

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22972

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

Sling (cable/synthetic)

Serial number: 17/22981

Make: BENECA

Nature: SLING

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22982

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature : SLING

Serial number: 17/22983

(see next page)

Date of issue: 16/05/2023 Page: 988/1083



DESCRIPTION OF THE DEVICES

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22985

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22986

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22987 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22988 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22989

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

(see next page)

Date of issue: 16/05/2023 Page: 989/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22996

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22997

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22998 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/22999

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26441

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Date of issue: 16/05/2023 Page: 990/1083



DESCRIPTION OF THE DEVICES

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26444

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26448

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26449

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26451 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 991/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26454

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26455

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/26457

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26458

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26466

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

(see next page)

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Date of issue: 16/05/2023 Page: 992/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26471 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26472

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26473

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26475

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26479

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 993/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26625

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26634

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26636

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26681 Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26686

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 994/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26689

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26691

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26694

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26697

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 17/26699

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 995/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26700

Make : BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/26782

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/26789

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/26790

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number : 17/26794

Make: BENECA

Year of manufacture : 2017 Maximum load : 2000KG

Length: 3M

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Sling (cable/synthetic)

(see next page)

Date of issue: 16/05/2023 Page: 996/1083



DESCRIPTION OF THE DEVICES

Nature: SLING

Serial number: 17/26797

Make: BENECA

Year of manufacture: 2017 Maximum load: 2000KG

Length: 3M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

required before re-service

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/31760

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 3M

The material can be used, no

The material can be used, no

abnormalities were found when inspecting

abnormalities were found when inspecting

the material

the material

Conclusion

Conclusion

Conclusion

Sling (cable/synthetic)

Nature: SLING

Serial number: 19/31761

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 3M

Sling (cable/synthetic) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: SLING

Serial number: 19/34858

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 3M

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Sling (cable/synthetic)

Nature: SLING

Serial number: 19/34759

Make: BENECA

Year of manufacture: 2019 Maximum load: 2000KG

Length: 3M

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Date of issue: 16/05/2023 Page: 997/1083



DESCRIPTION OF THE DEVICES

CHAIN SLINGS

SINGLE CHAIN 1,5T - 2M

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15002

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15003

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15004

Year of manufacture : 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15005

Year of manufacture: 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15006

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 998/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15007

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15008

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15009

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15010

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 999/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15012

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15013

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15014

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15015

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15016

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs) (see next page)

Nature: CHAIN

Date of issue: 16/05/2023 Page: 1000/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15017

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15018

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15019

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) Nature: CHAIN

Client number of the equipment: A15020

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15021

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1001/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15022

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15023

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15024

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15025

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15027

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1002/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15028

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15029

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG Length : 2M

Text client : WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15030

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15031

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15032

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1003/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15033

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

inspection, or could only be partially

inspected, an additional inspection is

material was not available during

* Conditions and operation inspection (07.2023)

The material cannot be used anymore. The

Not inspected: not presented.

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15034

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conclusion

FINDINGS

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15035

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15036

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15037

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1004/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15038

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15039

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15041

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15042

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15043

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1005/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15044

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15045

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15046

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15047

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN Client number of the equipment: A15048

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1006/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15050

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15051

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15052

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15053

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15054

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1007/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15056

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

material was not available during

inspection, or could only be partially

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

The material cannot be used anymore. The

Not inspected: not presented.

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15057

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conclusion

FINDINGS

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15058

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15059

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15060

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1008/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15061

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15062

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15063

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15064

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15065

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1009/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15066

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15067

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15068

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15069

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15071

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1010/1083



Not inspected: not presented.

* Conditions and operation inspection (07.2023)

material was not available during

material was not available during

material was not available during

inspection, or could only be partially

inspected, an additional inspection is

inspection, or could only be partially

inspected, an additional inspection is

required before re-service

required before re-service

required before re-service

inspection, or could only be partially

inspected, an additional inspection is

The material cannot be used anymore. The

FINDINGS

Conclusion

Conclusion

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15072

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: CHAIN

Client number of the equipment: A15073

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: CHAIN Client number of the equipment: A15074 Conclusion

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) Conditions and operation inspection (07.2023) Not inspected: not presented.

Nature: CHAIN

Client number of the equipment: A15075

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15076

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

inspection, or could only be partially

material was not available during

Not inspected: not presented.

Conclusion

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs) (see next page)

Date of issue: 16/05/2023 Page: 1011/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15077

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15078

Year of manufacture: 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15079

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15080

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15081

Year of manufacture : 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1012/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15082

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15083

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15084

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15085

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15086

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1013/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15088

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15089

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15091

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15092

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15093

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1014/1083



DESCRIPTION OF THE DEVICES

Nature : CHAIN

Client number of the equipment: A15094

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

IITCH insn

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15095

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN
Client number of the equipment: A15096

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15097

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15098

Year of manufacture : 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 1015/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15099

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15100

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15101

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15102

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15103

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1016/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15104

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15105

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

* Conditions and operation inspection (07.2023)

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15106

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15107

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Client number of the equipment: A15108

Year of manufacture: 2015

Diameter: 8 mm

Nature: CHAIN

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1017/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15110

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15111

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15112

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15113

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15114

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1018/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15115

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15116

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15117

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15118

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15119

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1019/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15120

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15121

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15122

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15123

Year of manufacture: 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15124

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15125

Year of manufacture : 2015

Diameter: 8 mm

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1020/1083



DESCRIPTION OF THE DEVICES

Maximum load: 2000KG

Lenath: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15127

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15128

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15130

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15131

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15132

Year of manufacture: 2015

(see next page)

Date of issue: 16/05/2023 Page: 1021/1083



DESCRIPTION OF THE DEVICES

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15133

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15134

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15135

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15138

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1022/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15139

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)
Nature: CHAIN

Client number of the equipment: A15140

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15141

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15142

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15143

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15144

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1023/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15145

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15147

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15148

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15149

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs) (see next page)

Nature: CHAIN

Date of issue: 16/05/2023 Page: 1024/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15150

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15151

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15152

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15153

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15154

Year of manufacture : 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15156

Year of manufacture : 2015

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1025/1083



DESCRIPTION OF THE DEVICES

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15158

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15159

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15161

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15162

Year of manufacture: 2015

Diameter : 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature : CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1026/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15163

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15164

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15165

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15166

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15167

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1027/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15168

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)
Nature: CHAIN

Client number of the equipment: A15169

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15170

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15171

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15172

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15173

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1028/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15174

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15175

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15176

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15177

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1029/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15178

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15179

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15180

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15181

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15182

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1030/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15183

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15184

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15185

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15186

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15187

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15188

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1031/1083



DESCRIPTION OF THE DEVICES

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15189

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15190

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15191

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15192

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1032/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15193

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15194

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15195

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15196

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15197

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15198

Year of manufacture: 2015

Diameter: 8 mm

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023 Page: 1033/1083



DESCRIPTION OF THE DEVICES

Maximum load : 2000KG

Length: 2M

Text client : WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15199

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15200

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15201

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15202

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1034/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15203

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15204

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15205

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15206

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15207

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs) (see next page)

Nature: CHAIN

Date of issue: 16/05/2023 Page: 1035/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15208

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15209

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15210

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15211

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15212

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15213

Year of manufacture : 2015

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

•

(see next page)

Date of issue: 16/05/2023 Page: 1036/1083



DESCRIPTION OF THE DEVICES

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15215

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15218

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15220

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15221

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1037/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15222

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15223

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15224

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15225

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Client number of the equipment: A15226

Year of manufacture : 2015

Diameter: 8 mm

Nature: CHAIN

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

Page: 1038/1083

inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15227

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023)

Nature: CHAIN

Client number of the equipment: A15228

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15229

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15230

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Nature: CHAIN

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Client number of the equipment: A15232

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

Page: 1039/1083

required before re-service

(see next page)

Date of issue: 16/05/2023



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15233

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15234

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

Client number of the equipment: A15235

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client : WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15236

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15237

Year of manufacture: 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature : CHAIN

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1040/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15238

Year of manufacture: 2015

Maximum load : 2000KG

Length: 2M

Diameter: 8 mm

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15240

Year of manufacture: 2015

Diameter: 8 mm

Maximum load : 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15241

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15242

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15243

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1041/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15244

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15245

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15246

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

vot inspected. Not presente

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15247

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15248

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1042/1083



Not inspected: not presented.

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15249

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

inspection, or could only be partially

inspected, an additional inspection is

material was not available during

* Conditions and operation inspection (07.2023)

The material cannot be used anymore. The

Not inspected: not presented.

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15250

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conclusion

FINDINGS

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15251

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15252

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15253

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1043/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15254

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15255

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN Client number of the equipment: A15256

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: CHAIN

Client number of the equipment: A15257

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023) Nature: CHAIN

Client number of the equipment: A15258

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) (see next page)

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Date of issue: 16/05/2023 Page: 1044/1083



Not inspected: not presented.

* Conditions and operation inspection (07.2023)

material was not available during

material was not available during

material was not available during

inspection, or could only be partially

inspected, an additional inspection is

inspection, or could only be partially

inspected, an additional inspection is

required before re-service

required before re-service

Not inspected: not presented.

inspection, or could only be partially

inspected, an additional inspection is

The material cannot be used anymore. The

FINDINGS

Conclusion

Conclusion

Conclusion

Conclusion

Conclusion

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15259

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: CHAIN

Client number of the equipment: A15260 Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023)

Not inspected: not presented. Nature: CHAIN Client number of the equipment: A15261

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

required before re-service Chain sling (short links/leafs) Conditions and operation inspection (07.2023)

Nature: CHAIN

Client number of the equipment: A15262

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Chain sling (short links/leafs) * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: CHAIN

Client number of the equipment: A15263

Year of manufacture: 2015

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Diameter: 8 mm material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs) (see next page)

Date of issue: 16/05/2023 Page: 1045/1083



DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15264

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15265

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15266

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15267

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15268

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Chain sling (short links/leafs)

Nature: CHAIN

(see next page)

Date of issue: 16/05/2023 Page: 1046/1083



DESCRIPTION OF THE DEVICES

Client number of the equipment: A15269

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15270

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15271

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15272

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15273

Year of manufacture : 2015

Diameter : 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15274

Year of manufacture: 2015

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1047/1083



DESCRIPTION OF THE DEVICES

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15275

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15276

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15277

Year of manufacture: 2015

Diameter: 8 mm Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15278

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Chain sling (short links/leafs)

(see next page)

Date of issue: 16/05/2023 Page: 1048/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref. : 0001011189/10000

DESCRIPTION OF THE DEVICES

Nature: CHAIN

Client number of the equipment: A15279

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

Chain sling (short links/leafs)

Nature: CHAIN

Client number of the equipment: A15280

Year of manufacture: 2015

Diameter: 8 mm

Maximum load: 2000KG

Length: 2M

Text client: WITH CLUTCH

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 1049/1083



DESCRIPTION OF THE DEVICES

FINDINGS

O-RINGS

O-RINGS 1000KG

Lifting accessories, <5T Nature : LIFTING RING

Client number of the equipment: Z/NR

Maximum load : 1000KG Text client : 134 Pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

O-RINGS 5000KG

Lifting accessories, <5T Nature : LIFTING RING

Client number of the equipment: Z/NR

Maximum load : 5000KG Text client : 56 pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Date of issue: 16/05/2023 Page: 1050/1083



DESCRIPTION OF THE DEVICES

SHACKLES

FINDINGS

SHACKLES 1000KG

Lifting accessories, <5T

Nature : SHACKLE Make : CROSBY

Client number of the equipment: Z/NR

Maximum load : 1000KG Text client : 187 Pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

SHACKLES 1500KG

Lifting accessories, <5T

Nature : SHACKLE Make : CROSBY

Client number of the equipment: Z/NR

Maximum load : 1500KG Text client : 390 Pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

SHACKLES 2000KG

Lifting accessories, <5T

Nature : SHACKLE Make : CROSBY

Client number of the equipment: Z/NR

Maximum load: 2000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

SHACKLES 3250KG

Lifting accessories, <5T

Nature : SHACKLE Make : CROSBY

Client number of the equipment: Z/NR

Maximum load : 3250KG Text client : 2071 Pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

SHACKLES 4750KG

Lifting accessories, <5T

Nature : SHACKLE Make : CROSBY

Client number of the equipment: Z/NR

Maximum load : 4750KG Text client : 0 Pieces * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no

abnormalities were found when inspecting

the material

Date of issue: 16/05/2023 Page: 1051/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

BEAMCLAMPS

FINDINGS

BEAMCLAMPS 1000KG

Lifting accessories, <5T

Nature: CLAMP

Serial number: F200395

Make: CORSO

Client number of the equipment: 001

Year of manufacture: 2002 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: F200251

Make: CORSO

Client number of the equipment: 007

Year of manufacture: 2002 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: F502532

Make: CORSO

Client number of the equipment: 017

Year of manufacture: 2005 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: F502541

Make: CORSO

Client number of the equipment: 019

Year of manufacture: 2005 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: F502540

Make: CORSO

Client number of the equipment: 020

Year of manufacture: 2005 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: Page: 1052/1083 16/05/2023



DESCRIPTION OF THE DEVICES

Nature: CLAMP Serial number: F502537

Make: CORSO

Client number of the equipment: 028

Year of manufacture: 2005 Maximum load: 1000KG

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10086

Make: CAMLOK

Client number of the equipment: 032

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10091 Make: CAMLOK

Client number of the equipment: 037

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10096 Make: CAMLOK

Client number of the equipment: 042

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10098

Make: CAMLOK

Client number of the equipment: 044

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1053/1083



DESCRIPTION OF THE DEVICES

Nature: CLAMP

Serial number: XY10100

Make: CAMLOK

Client number of the equipment: 046

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10101

Make: CAMLOK

Client number of the equipment: 047

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10167 Make: CAMLOK

Client number of the equipment: 053

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10169 Make: CAMLOK

Client number of the equipment: 055

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10170

Make: CAMLOK

Client number of the equipment: 056

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1054/1083



DESCRIPTION OF THE DEVICES

Nature : CLAMP

Serial number : XY10172 Make : CAMLOK

Client number of the equipment: 058

Type: SC921

Year of manufacture : 2007 Maximum load : 1000KG **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY10174

Make: CAMLOK

Client number of the equipment: 060

Type: SC921

Year of manufacture : 2007 Maximum load : 1000KG * Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY10177

Make: CAMLOK

Client number of the equipment: 063

Type: SC921

Year of manufacture : 2007 Maximum load : 1000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY10180 Make : SCREWLOK

Client number of the equipment: 066

Type: SC921

Year of manufacture : 2007 Maximum load : 1000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY10181

Make: CAMLOK

Client number of the equipment: 067

Type: SC921

Year of manufacture : 2007 Maximum load : 1000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

(see next page)

Date of issue: 16/05/2023 Page: 1055/1083



DESCRIPTION OF THE DEVICES

Serial number: XY10184

Make: CAMLOK

Client number of the equipment: 070

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially

abnormalities were found when inspecting

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

required before re-service

The material can be used, no

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY10185 Make: SCREWLOK

Client number of the equipment: 071

Type: SC921

Year of manufacture: 2007 Maximum load: 1000KG

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Lifting accessories, <5T Nature: CLAMP

Client number of the equipment: 075

Maximum load: 1000KG

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: 208013419

Make: YALE

Client number of the equipment: 076

Type: YC 1

Year of manufacture: 2008 Maximum load: 1000KG Text client: 75 - 230MM

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210011798

Make: YALE

Client number of the equipment: 077

Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG Text client: 75 - 230MM

Lifting accessories, <5T

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Nature: CLAMP

Date of issue: 16/05/2023 Page: 1056/1083



DESCRIPTION OF THE DEVICES

Serial number : 210011832

Make: YALE

Client number of the equipment: 078

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP

Serial number : 210012009

Make: YALE

Client number of the equipment: 079

Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG Text client: 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210012018

Make: YALE

Client number of the equipment: 080

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP

Serial number: 210012026

Make: YALE

Client number of the equipment: 081

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012029

Make: YALE

Client number of the equipment: 082

Type: YC 1

Year of manufacture : 2011 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012031

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1057/1083



DESCRIPTION OF THE DEVICES

Make: YALE

Client number of the equipment: 083

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012032

Make: YALE

Client number of the equipment: 084

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM The material can be used, no abnormalities were found when inspecting

* Conditions and operation inspection (07.2023)

the material

Conclusion

Lifting accessories, <5T

Nature : CLAMP

Serial number : 210012035

Make: YALE

Client number of the equipment: 085

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012227

Make : YALE

Client number of the equipment: 086

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012234

Make: YALE

Client number of the equipment: 087

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210012243

(see next page)

Date of issue: 16/05/2023 Page: 1058/1083



DESCRIPTION OF THE DEVICES

Make: YALE

Client number of the equipment: 088

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210012250

Make: YALE

Client number of the equipment: 089

Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG Text client: 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210012252

Make : YALE

Client number of the equipment: 090

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012253

Make : YALE

Client number of the equipment: 091

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012254

Make : YALE

Client number of the equipment: 092

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP

Serial number : 210012256

Make: YALE

Client number of the equipment: 093

Type: YC 1

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1059/1083



DESCRIPTION OF THE DEVICES

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210012257

Make: YALE

Client number of the equipment: 094

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature : CLAMP

Serial number : 210012258

Make : YALE

Client number of the equipment: 095

Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG Text client: 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: 210012259

Make: YALE

Client number of the equipment: 096

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : 210012260

Make: YALE

Client number of the equipment: 097

Type: YC 1

Year of manufacture : 2010 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1060/1083



DESCRIPTION OF THE DEVICES

Nature: CLAMP

Serial number: 210012261

Make: YALE

Client number of the equipment: 098

Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG Text client: 75 - 230MM

Serial number: 210012236

Lifting accessories, <5T * Conditions and operation inspection (07.2023)

Nature: CLAMP

Make: YALE

Client number of the equipment: 099 Type: YC 1

Year of manufacture: 2010 Maximum load: 1000KG

Text client: 75 - 230MM Lifting accessories, <5T

Nature: CLAMP Serial number: 1401278 Make: MASTERLIFT

Client number of the equipment: 101

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401283 Make: MASTERLIFT

Client number of the equipment: 102

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM Lifting accessories, <5T

Nature: CLAMP

Serial number: 1401284 Make: MASTERLIFT

Client number of the equipment: 103

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401285 Make: MASTERLIFT

Client number of the equipment: 104

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

FINDINGS

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1061/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

FINDINGS

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401286 Make: MASTERLIFT

Client number of the equipment: 105

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401297 Make: MASTERLIFT

Client number of the equipment: 106

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401298 Make: MASTERLIFT

Client number of the equipment: 107

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP Serial number: 1401299 Make: MASTERLIFT

Client number of the equipment: 108

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP

Serial number: 1401300

(see next page)

Date of issue: Page: 1062/1083 16/05/2023



DESCRIPTION OF THE DEVICES

Make: MASTERLIFT

Client number of the equipment: 109

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM **FINDINGS**

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401301 Make : MASTERLIFT

Client number of the equipment: 110

Type: RB-BK-010

Year of manufacture: 2014 Maximum load: 1000KG Text client: 75 - 230MM * Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401307 Make : MASTERLIFT

Client number of the equipment: 111

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401308 Make : MASTERLIFT

Client number of the equipment: 112

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401309 Make : MASTERLIFT

Client number of the equipment: 113

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

(see next page)

Date of issue: 16/05/2023 Page: 1063/1083



DESCRIPTION OF THE DEVICES

Serial number : 1401310 Make : MASTERLIFT

Client number of the equipment: 114

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM

Nature : CLAMP Serial number : 1401313 Make : MASTERLIFT

Lifting accessories, <5T

Client number of the equipment: 115

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401314 Make : MASTERLIFT

Client number of the equipment: 116

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401315 Make : MASTERLIFT

Client number of the equipment: 117

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401316 Make : MASTERLIFT

Client number of the equipment: 118

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM

Lifting accessories, <5T

Nature : CLAMP Serial number : 1401448 Make : MASTERLIFT

Client number of the equipment: 119

FINDINGS

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

(see next page)

Date of issue: 16/05/2023 Page: 1064/1083



DESCRIPTION OF THE DEVICES

Type: RB-BK-010

Year of manufacture : 2014 Maximum load : 1000KG Text client : 75 - 230MM **FINDINGS**

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : B10025JC

Make : Scan-Rigg

Client number of the equipment: 120

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : B10203JC

Make: Scan-Rigg

Client number of the equipment: 121

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10207JC

Make : Scan-Rigg

Client number of the equipment: 122

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : B10171JC

Make : Scan-Rigg

Client number of the equipment: 123

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP

(see next page)

Date of issue: 16/05/2023 Page: 1065/1083



DESCRIPTION OF THE DEVICES

Serial number: B10025JC

Make: Scan-Rigg

Client number of the equipment: 124

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

FINDINGS

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10026JC

Make: Scan-Rigg

Client number of the equipment: 125

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10085JC

Make: Scan-Rigg

Client number of the equipment: 126

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10119JC

Make: Scan-Rigg

Client number of the equipment: 127

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service Lifting accessories, <5T

Nature: CLAMP

Serial number: B10018JC

Make: Scan-Rigg

Client number of the equipment: 128

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

(see next page)

Date of issue: 16/05/2023 Page: 1066/1083



DESCRIPTION OF THE DEVICES

Serial number: B10163JC

Make: Scan-Rigg

Client number of the equipment: 129

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

Not inspected: not presented. Conclusion

FINDINGS

The material cannot be used anymore. The material was not available during inspection, or could only be partially

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10100JC

Make: Scan-Rigg

Client number of the equipment: 130

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

inspected, an additional inspection is

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10190JC

Make: Scan-Rigg

Client number of the equipment: 131

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM Lifting accessories, <5T

Nature: CLAMP

Serial number: B10084JC

Make: Scan-Rigg

Client number of the equipment: 132

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10099JC

Make: Scan-Rigg

Client number of the equipment: 133

Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10120JC

Make: Scan-Rigg

Client number of the equipment: 134

Year of manufacture: 2017

Date of issue: 16/05/2023 Page: 1067/1083



DESCRIPTION OF THE DEVICES

Maximum load : 1000KG Text client : 75 - 230MM **FINDINGS**

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : B10085JC

Make: Scan-Rigg

Client number of the equipment: 135

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature : CLAMP

Serial number: B10076JC

Make: Scan-Rigg

Client number of the equipment: 136

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number: B10027JC

Make: Scan-Rigg

Client number of the equipment: 137

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature: CLAMP

Serial number: B19174JC

Make: Scan-Rigg

Client number of the equipment: 138

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : B10023JC

Make: Scan-Rigg

Client number of the equipment: 139

Year of manufacture : 2017 Maximum load : 1000KG Text client : 75 - 230MM * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1068/1083



Lifting accessories, <5T

Serial number: F203305

Year of manufacture : 2002 Maximum load : 3000KG **Lifting accessories**, <5T

Client number of the equipment: 019

Nature: CLAMP

Make: TRACTEL

Report n°: AUD/10/14446193/00/EN Contract Ref.: 0001011189/10000

DESCRIPTION OF THE DEVICES FINDINGS Nature: CLAMP * Conditions and operation inspection (07.2023) Serial number: B10233JC Conclusion Make: Scan-Rigg The material can be used, no Client number of the equipment: 140 abnormalities were found when inspecting Year of manufacture: 2017 the material Maximum load: 1000KG Text client: 75 - 230MM * Conditions and operation inspection (07.2023) Lifting accessories, <5T Nature: CLAMP Conclusion Serial number: B10087JC The material can be used, no Make: Scan-Rigg abnormalities were found when inspecting Client number of the equipment: 141 the material Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM Lifting accessories, <5T * Conditions and operation inspection (07.2023) Conclusion Nature: CLAMP Serial number: B10209JC The material can be used, no Make: Scan-Rigg abnormalities were found when inspecting Client number of the equipment: 142 the material Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM * Conditions and operation inspection (07.2023) Lifting accessories, <5T Nature: CLAMP Conclusion Serial number: B10185JC The material can be used, no Make: Scan-Rigg abnormalities were found when inspecting Client number of the equipment: 143 the material Year of manufacture: 2017 Maximum load: 1000KG Text client: 75 - 230MM **BEAMCLAMPS 3000KG** Lifting accessories, <5T * Conditions and operation inspection (07.2023) Not inspected: not presented. Nature: CLAMP Serial number: F203308 Conclusion Make: CORSO The material cannot be used anymore. The Client number of the equipment: 018 material was not available during Year of manufacture: 2002 inspection, or could only be partially Maximum load: 3000KG inspected, an additional inspection is required before re-service

Date of issue: 16/05/2023 Page: 1069/1083

Conclusion

the material

(see next page)

* Conditions and operation inspection (07.2023)

abnormalities were found when inspecting

The material can be used, no



Nature : CLAMP Serial number : F402011 Make : TRACTEL

Client number of the equipment: 021

Year of manufacture : 2004 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP

Serial number : F402012 Make : TRACTEL

Client number of the equipment: 022

Year of manufacture : 2004 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP Serial number : 402004 Make : CORSO

Client number of the equipment: 023

Year of manufacture: 2004 Maximum load: 3000KG

Cheffit flumber of the equipment . 023

Lifting accessories, <5T

Nature : CLAMP Serial number : F402063

Make: CORSO

Client number of the equipment: 025

Year of manufacture : 2004 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP Serial number : F402062

Make : TRACTEL

Client number of the equipment: 026

Maximum load : 3000KG
Lifting accessories, <5T
Nature : CLAMP

Year of manufacture: 2004

Serial number : 402017 Make : CORSO

Client number of the equipment: 027

Year of manufacture : 2004 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially

inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during

inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T (see next page)

Date of issue: 16/05/2023 Page: 1070/1083



Nature : CLAMP Serial number : F402009

Make: CORSO

Client number of the equipment: 029

Year of manufacture : 2004 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : 402045 Make : CORSO

Client number of the equipment: 031

Year of manufacture : 2004 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : 402003 Make : TRACTEL

Client number of the equipment: 034

Year of manufacture : 2004 Maximum load : 3000KG **Lifting accessories, <5T**

Nature : CLAMP Serial number : 402001

Make: CORSO

Client number of the equipment: 035

Year of manufacture : 2004 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Nature: CLAMP

Serial number : F402002 Make : TRACTEL

Client number of the equipment: 036

Year of manufacture : 2004 Maximum load : 3000KG **Lifting accessories, <5T**

Serial number: F402006

Make : TRACTEL

Client number of the equipment : 038 Year of manufacture : 2004 Maximum load : 3000KG

Lifting accessories, <5T

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 16/05/2023

Page: 1071/1083



Nature : CLAMP Serial number : F402061

Make: CORSO

Client number of the equipment: 039

Year of manufacture : 2004 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : F100853 Make : TRACTEL

Client number of the equipment: 049

Year of manufacture : 2001 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY30176

Make : CAMLOK

Client number of the equipment: 051

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : XY30177 Make : CAMLOK

Client number of the equipment: 052

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP Serial number : XY30178 Make : CAMLOK

Client number of the equipment: 053

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1072/1083



Nature: CLAMP

Serial number : XY30179

Make: CAMLOK

Client number of the equipment: 054

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY30180

Make: CAMLOK

Client number of the equipment: 055

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature : CLAMP

Serial number : XY30183 Make : CAMLOK

Client number of the equipment: 058

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP Make : CAMLOK

Client number of the equipment : 059

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number: XY30185

Make: CAMLOK

Client number of the equipment: 060

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : XY30187

(see next page)

Date of issue: 16/05/2023 Page: 1073/1083



Make: CAMLOK

Client number of the equipment: 062

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30188 Make: CAMLOK

Client number of the equipment: 063

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30189

Make: CAMLOK

Client number of the equipment: 064

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30190

Make: CAMLOK

Client number of the equipment: 065

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30193

Make: CAMLOK

Client number of the equipment: 068

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30194

(see next page)

Date of issue: 16/05/2023 Page: 1074/1083



Make: CAMLOK

Client number of the equipment: 069

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY30320 Make : CAMLOK

Client number of the equipment: 070

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Lifting accessories, <5T

Nature : CLAMP

Serial number : XY30321 Make : CAMLOK

Client number of the equipment: 071

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Conclusion

Conclusion

the material

Nature : CLAMP Serial number : XY30323

Lifting accessories, <5T

Make : CAMLOK

Client number of the equipment: 072

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature : CLAMP

Serial number : XY30324

Make : CAMLOK

Client number of the equipment: 073

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : XY30327

Make : CAMLOK

Client number of the equipment: 075

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1075/1083



Nature: CLAMP

Serial number: XY30341

Make: CAMLOK

Client number of the equipment: 079

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

Conclusion

the material

Conclusion

the material

Conclusion

the material

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

abnormalities were found when inspecting

required before re-service

The material can be used, no

Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30344

Make: CAMLOK

Client number of the equipment: 082

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

Lifting accessories, <5T * Conditions and operation inspection (07.2023)

Nature: CLAMP

Serial number: XY30345

Make: CAMLOK

Client number of the equipment: 083

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

Lifting accessories, <5T * Conditions and operation inspection (07.2023)

Nature: CLAMP

Serial number: XY30346

Make: CAMLOK

Client number of the equipment: 084

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

* Conditions and operation inspection (07.2023) Lifting accessories, <5T

Nature: CLAMP

Serial number: XY30347

Make: CAMLOK

Client number of the equipment: 085

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

Lifting accessories, <5T * Conditions and operation inspection (07.2023) Not inspected: not presented.

Nature: CLAMP

Serial number: XY30351 Make: CAMLOK

Client number of the equipment: 086

Type: SC923

Year of manufacture: 2007 Maximum load: 3000KG

The material cannot be used anymore. The

material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T (see next page)

Date of issue: 16/05/2023 Page: 1076/1083



Nature: CLAMP

Serial number : XY30352

Make: CAMLOK

Client number of the equipment: 087

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY30355 Make : CAMLOK

Client number of the equipment: 088

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : XY30358

Make: CAMLOK

Client number of the equipment: 090

Type: SC923

Year of manufacture : 2007 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

abnormalities were found when inspecting

Lifting accessories, <5T

Nature : CLAMP

Serial number: YY30578

Make : CAMLOK

Client number of the equipment : 092

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

Conclusion

the material

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature : CLAMP

Serial number : YY30622

Make : CAMLOK

Client number of the equipment: 093

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP

Serial number: YY30628

Make: CAMLOK

Client number of the equipment: 094

(see next page)

Date of issue: 16/05/2023 Page: 1077/1083



Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30630 Make : CAMLOK

Client number of the equipment: 096

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : YY30631 Make : CAMLOK

Client number of the equipment: 097

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP Make : CAMLOK

Client number of the equipment: 098

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30635 Make : CAMLOK

Client number of the equipment: 099

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Lifting accessories, <5T

Nature: CLAMP

Serial number: YY30638

Make: CAMLOK

Client number of the equipment: 100

Type: SC923

Year of manufacture: 2008

Date of issue: 16/05/2023 Page: 1078/1083



Report n°: AUD/10/14446193/00/EN

Contract Ref.: 0001011189/10000

Maximum load: 3000KG

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30639 Make : CAMLOK

Client number of the equipment: 101

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

abnormalities were found when inspecting

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30642

Make: CAMLOK

Client number of the equipment: 102

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

* Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Not inspected: not presented.

Lifting accessories, <5T

Nature : CLAMP

Serial number: YY30650

Make : CAMLOK

Client number of the equipment: 103

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30661

Make : CAMLOK

Client number of the equipment: 104

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP

Serial number : YY30652

(see next page)

Date of issue: 16/05/2023 Page: 1079/1083



Make: CAMLOK

Client number of the equipment: 105

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : YY30655 Make : CAMLOK

Client number of the equipment: 106

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Lifting accessories, <5T

Nature: CLAMP

Serial number: YY30656

Make: CAMLOK

Client number of the equipment: 107

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP Make : CAMLOK

Client number of the equipment: 109

Type: SC923

Year of manufacture : 2008 Maximum load : 3000KG

Lifting accessories, <5T

Serial number: YY30627

Nature: CLAMP

Make: CAMLOK

Type: SC923

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Year of manufacture : 2008 Maximum load : 3000KG

Nature: CLAMP

Serial number: 210031215

Make: YALE

Client number of the equipment: 111

Client number of the equipment: 110

(see next page)

Date of issue: 16/05/2023 Page: 1080/1083



Type: YC3

Year of manufacture : 2010 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

* Conditions and operation inspection (07.2023)

The material can be used, no

Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting the material

abnormalities were found when inspecting

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210031216

Make: YALE

Client number of the equipment: 112

Type: YC3

Year of manufacture : 2010 Maximum load : 3000KG

Lifting accessories, <5T

Nature : CLAMP

Serial number: 210031217

Make: YALE

Client number of the equipment: 113

Type: YC3

Year of manufacture : 2010 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 210031218

Make: YALE

Client number of the equipment: 114

Type: YC3

Year of manufacture : 2010 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 212031245

Make : YALE

Client number of the equipment: 115

Type: YC3

Year of manufacture : 2012 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Lifting accessories, <5T

Nature : CLAMP Make : YALE

Client number of the equipment: 116

Type: YC3

Year of manufacture : 2013 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1081/1083



Nature: CLAMP

Serial number : 213031687

Make: YALE

Client number of the equipment: 117

Type: YC3

Year of manufacture : 2013 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 214030233

Make: YALE

Client number of the equipment: 118

Type: YC3

Year of manufacture : 2014 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Lifting accessories, <5T

Nature : CLAMP Make : YALE

Client number of the equipment: 119

Type: YC3

Year of manufacture : 2014 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number: 213031626

Make: YALE

Client number of the equipment: 120

Type: YC3

Year of manufacture : 2013 Maximum load : 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

Nature: CLAMP

Serial number : 216030169

Make: YALE

Client number of the equipment: 121

Type: YC3 80-320mm Year of manufacture: 2016 Maximum load: 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Lifting accessories, <5T

(see next page)

Date of issue: 16/05/2023 Page: 1082/1083



Nature: CLAMP

Serial number : 212031172

Make: YALE

Client number of the equipment: 122

Type: YC3 80-320 mm Year of manufacture: 2012 Maximum load: 3000KG * Conditions and operation inspection (07.2023)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Total of the equipment inspected

2910406001Chain sling(short links/leafs)Cond. & Oper.Insp. or Prev.176810407001Sling (cable/synthetic)Cond. & Oper.Insp. or Prev.6810408001Lifting accessories < 5T</td>Cond. & Oper.Insp. or Prev.

Total of the equipment not inspected

227	10406001	Chain sling(short links/leafs)	Cond. & Oper.Insp. or Prev.
3565	10407001	Sling (cable/synthetic)	Cond. & Oper.Insp. or Prev.
102	10408001	Lifting accessories < 5T	Cond. & Oper.Insp. or Prev.

Date of issue: 16/05/2023 Page: 1083/1083