VINÇOTTE vzw
Certified inspection body l External service for technical inspections at the workplace
Registered Office : Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium
VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC : GEBABEBB
Bollebergen 2a bus 12 • 9052 Gent • Belgium • phone: +32 9 244 77 11 • gent@vincotte.be

Copy

AED Rent nv

Bedrijvenpark De Veert, 12
2830 Willebroek
BELGIUM

Our References
Report n° : GEN/10/13266312/00/EN
Contract Ref. : 0001011189/8000

Your References
Ref.: Brief ref. : WBE/ADB dd 04/11/09 04112009

Intervention data
Area : AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit : 14.08.2018
Performed by : MUTERT GUILLAUME (681)

Periodical report concerning your Lifting accessories and similar equipment.

Conclusions founded in this report:

Performed according to the programme described on page 2 of this report, an inspection of the equipment referred to below failed to revealany irregularities, so the equipment that was inspected may continue to be used.
When any equipment is referred to as partly inspected or not inspected, please take steps to have a further inspection carried out before bringing it back into service.

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

Important note
Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.
When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.
Please also ensure you that other regulations are not applicable for you.

BASIS AND CONTENTS OF OUR INSPECTIONS

1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection.
The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

3. INSPECTION PROGRAMS (non exhaustive lisiting)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories,lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.
Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.
Our electrical inspection department is available for carrying out the measurements.
Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.
Inspections marked "*" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.
- Remarks: these result in the obligation to remedy the situation as soon as possible.
- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.
This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.
Please also make sure there are no other applicable regulations.
We are at you disposal if you require any further information.

DESCRIPTION OF THE DEVICES	FINDINGS
STEEL SLINGS	
SLINGS 1000KG - 0,5M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-01 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-02 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-03 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-04 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-06 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-09 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-10 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 01-12 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-13 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-15 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-16 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-20 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-21 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-23 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 01-27 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-32 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-33 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-36 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-37 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-38 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-39 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 01-40 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-41 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-44 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-45 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-49 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-58 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-62 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 01-64 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-67 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-69 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-76 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-84 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-01 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-02 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 02-04 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-05 Year of manufacture : 2001 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-01 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-02 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-04 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-05 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-07 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-09 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-10 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-11 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-12 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-13 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-14 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-15 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-18 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-19 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-20 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-21 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-23 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-24 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-25 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-26 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-27 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-28 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-31 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-32 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-34 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-35 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-37 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-38 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-40 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-41 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-42 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-43 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-45 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-47	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-48 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-49 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-50 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-51 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-75 Year of manufacture : 2004 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-04 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-05 Year of manufacture : 2005 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-08 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-09 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-10 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-12 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-14 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-15 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-17 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-18 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-19 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-22 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-23 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-24 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-25 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-26 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-27 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-28 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-30 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-33 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-36 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-37 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-38 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-40 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-44 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-45 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-47 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-48 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-49 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-50 Year of manufacture : 2005 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-01 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-03 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-04 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-05 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-06 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-07 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-08 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-09 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-10 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-11 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-12 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-14 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-15 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-16	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-17 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-20 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-22 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-23 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-24 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-25 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-26 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-28 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-29 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-33 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-35 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-36 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-37 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-38 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-39 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-40 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-41 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-42 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-43 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-44 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-45 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-46 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-47 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-48 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-49 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-50 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-51 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-52 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-53 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-54 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-55 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-56 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-57 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-58 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-60 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-61 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-62 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-63 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-64 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-65 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-66 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-67	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-68 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-69 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-70 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-71 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-72 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-73 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-74 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-75 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-76 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-78 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-79 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-80 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-81 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-82 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-83 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-84 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-85 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-86 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-87 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-88 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-89 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-90 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-91 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-92 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-93 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-94 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-95 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-96 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-97 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-98 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-99 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-100 Year of manufacture : 2006 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-001 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-002 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-003	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-006 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-008 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-009 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 1M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-011 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-012 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-013 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 01-015 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-016 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-019 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-020 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-022 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-024 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-025 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 01-028 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-032 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-033 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-037 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-040 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-041 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-048 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-056 Year of manufacture : 2001	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-070 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-073 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-081 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-085 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-088 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-091 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-096 Year of manufacture : 2001	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-098 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-099 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-103 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-105 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-109 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-111 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-112	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-113 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-122 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-123 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-124 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-128 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-129 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 01-137 Year of manufacture : 2001 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-060 Year of manufacture : 2002 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-063 Year of manufacture : 2002 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-066 Year of manufacture : 2002 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-069 Year of manufacture : 2002 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-086 Year of manufacture : 2002 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-006 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-009 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-013 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-014 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-015 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-020	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-025 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-026 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-027 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-028 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-029 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-030 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-034 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-036 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-037 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-038 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-040 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-041 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-043 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-046	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-047 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-048 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-054 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-056 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-066 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-088 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-092 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-095 Year of manufacture : 2004 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-003 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-004 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-008 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-011 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-015 Year of manufacture : 2005 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-016 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-020 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-023 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-024 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-025 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-033 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-039 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-041 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-043 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-044 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-046 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-047 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-048 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-049 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-050 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-053 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-054 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-055 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-056 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-057 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-058 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-063 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-064 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-065 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-066 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-067 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-070 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-071 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-073 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-083 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-084 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-086 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-088 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-089 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-090 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-092 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-094 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-095 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-099 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-101 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-102 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-104 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-105 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-106 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-110 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-113 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-115 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-116 Year of manufacture : 2005 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-118 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-120 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-122 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-124 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-125 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-126 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-128 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-129 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-130 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-131 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-134 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-135 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-136 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-137 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-139 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-140 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-142 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-143 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-144 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-145 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-147 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 05-149 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-150 Year of manufacture : 2005 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-016 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-041 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-054 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-056 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-068 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-070 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-071	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-072 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-075 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-082 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-085 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-086 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-088 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-090 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-092 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-097 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-102 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-103 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-105 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-106 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-107 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-108 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-109 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-112 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-113 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-114 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-115 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-118 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-121 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-123 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-125 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-127 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-128 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-129 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-130 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-133 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-134 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-135 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-136 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-139 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-141 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-143 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-144 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-149	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-151 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-152 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-155 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-157 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-161 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-162 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-164 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-166 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-167 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-168 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-171 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-172 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-173 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-175 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-176 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-178 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-181 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-183 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-185 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-186 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-188 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-190 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-191 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-192 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-193 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-196 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-199 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-200	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-201 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-205 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-206 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-208 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-209 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-211 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-213 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-215 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-217 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-218 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-219 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-220 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-222 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-223 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-224 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-231 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-232 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-233 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-234 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-236 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-237 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-239 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-244 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-245 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-247 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-248 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-249 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-250 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-251 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-252 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-254 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-256 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-257 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-261 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-262	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-265 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-266 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-268 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-271 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-272 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-274 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-279	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-280 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-281 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-285 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-286 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-287 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-288 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-289 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-290 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-291 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-296 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-297 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-300 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-301 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-303	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-307 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-308 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-310 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-311 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-313 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-314 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-315 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-319 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-320 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-321 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-322 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-323 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-325 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-326 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-328	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-329 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-333 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-335 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-337 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-338 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-340 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-341	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-344 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-346 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-349 Year of manufacture : 2006 Maximum load : 1000KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 1,5M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-001 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-003 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-004 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-005 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-006 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-007 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-008 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-009 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-010 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-011 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-012 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-013 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-014 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-015 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-019 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-020 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-022 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-024 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-025 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-026 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-027 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-028 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-029	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-030 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-032 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-034 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-035 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-036 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-037 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-038 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-040 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-042 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-043 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-044 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-046 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-047 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-048 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-050 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-051 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-053 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-054 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-055 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-056 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-058 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-059 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-061 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-063 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-064 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-065 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-066 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-067	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-068 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-069 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-070 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-071 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-072 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-075 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-077 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-079 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-080 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-081 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-082 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-084 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-085 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-087 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-088 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-089 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-090 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-092 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-094 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-095 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-099 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-100 Year of manufacture : 2004 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-002 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-003 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-004 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-005 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-006 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-008 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-010 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-012 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-013 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-014 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-015 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-018 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-019 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-020 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-022 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-023 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-025 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-027 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-029 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-034 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-035 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-036 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-037 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-038 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-039	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-040 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-041 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-042 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-043 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-044 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-045 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-047	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-048 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-049 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-050 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-052 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-053 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-055 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-057	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-059 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-060 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-061 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-064 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-067 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-068 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-069 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 05-070 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-071 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-072 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-075 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-077 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-078 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-079 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-080 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-083 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-085 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-086 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-087 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-088 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-089 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-090 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-091 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-092 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-093 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-094 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-095 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-096 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-097 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-098 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-100 Year of manufacture : 2005 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-012 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-055 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-058 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-060 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-061 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-063 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-065 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-068 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-070 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-071 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-072 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-075 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-077 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-083 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-084 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-086 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-090 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-091 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-093 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-094 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-097 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-099 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-100 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-103 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-104 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-105 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-106 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-107 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-109 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-110 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-112 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-114 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-116 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-117 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-118 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-120 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-121 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-122 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-123 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-124 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-125 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-126 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-128 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-130 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-131 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-132 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-133 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-134 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-135 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-136 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-137 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-139 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-140 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-141 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-142 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-143 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-144 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-145 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-150 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-151 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-153 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-154 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-155 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-156 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-157 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-158 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-159 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-160 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-161 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-162 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-163 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-164 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-165 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-168 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-169 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-170 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-171 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-175 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-177 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-179 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-180 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-181 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-183 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-184 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-185 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-186 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-187 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-188 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-190 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-191 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-193 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-194 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-195	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-196 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-197 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-198 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-200 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-201 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-203 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-204 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-205 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-206 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-207 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-208 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-210 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-212 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-213 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-214 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-215 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-217 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-218 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-220 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-221 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-222 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-223 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-224 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-225 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-226 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-227 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-228 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-229 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-230 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-231 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-232 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-233 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-234 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-236 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-237 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-238 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-239 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-240 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-241 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-244 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-247 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-248 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-249 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-250 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-252 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-253 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-254 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-256 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-257 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-259 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-262 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-263 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-264 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-265 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-266 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-267 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-268 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-269 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-270 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-271 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-273 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-274 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-275 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-276 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-277	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-279 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-281 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-282 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-284 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-285 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-286 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-287 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-288 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-289 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-290 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-294 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-295 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-296 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-297 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-299 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-300 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-001 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-002 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-003 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-004 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-005 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 09-006 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-007 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-008 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-009 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-010 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-011 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-012 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-013 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 09-014 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-016 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-017 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-018 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-019 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-021 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-022 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-023 Year of manufacture : 2009 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-024 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-025 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-026 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-027 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-028 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-029 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-031 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 09-032 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-033 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-034 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-035 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-036 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-037 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-038 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-039 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 09-040 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-041 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-042 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-043 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-044 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-045 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-046 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-047 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-048 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-049 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-051 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-052 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-053 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-054 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-055 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 09-056 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-057 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-059 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-060 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-061 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-062 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-063 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-064 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-065 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-066 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-070 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-071 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-073 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-074 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-076 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-077 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-078 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-079 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-080 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-081 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-083 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-085 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-087 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-088 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-089 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-090 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-091 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-092 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-093	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-094 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-095 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-097 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-098 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-099 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-100 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-101 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-102 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-103 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-104 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-106 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-107 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-109 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 09-110 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-111 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-112 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-113 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-114 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-116 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-117 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-118 Year of manufacture : 2009 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-119 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-120 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-121 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-123 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-124 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-125 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-126	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-127 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-129 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-130 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-132 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-133 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-134 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-135 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-136 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-137 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-138 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-139 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-142 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-143 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-144 Year of manufacture : 2009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-145 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-146 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-147 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-148 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-149 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-150 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 2M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-039 Year of manufacture : 2001	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-050 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-053 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-060 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-061 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-062 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-082 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-091	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-094 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-097 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-111 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-114 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-119 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-120 Year of manufacture : 2001 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-007 Year of manufacture : 2002	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-033 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-035 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-050 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-054 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-058 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-071 Year of manufacture : 2002 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-004 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-005 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-006 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-007 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-008 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-012 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-021 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-022 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-025 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-026 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-027 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-028 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-029 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-031 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-032 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-035 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-036 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-038 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-040 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-042 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-043 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-048 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-052 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-053 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-059 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-060 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-062 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-064 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-068 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-069 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-070 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-071 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-072 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-075 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-077 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-082 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-083 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-084 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-086 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-087 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-092 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-095 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-097 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-099 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-100 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-105 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-106 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-108 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-109 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-110 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-112 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-115 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-116 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-119 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-120 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-122 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-127 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-130 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-131 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-132 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-136 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-139 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-140 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-141 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-142 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-144 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-145 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-148 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-150 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-151 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-152 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-153 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-154 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-159 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-160 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-162 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-165 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-168 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-169 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-170 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-171 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-174 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-175 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-176 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-178 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-179 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-182 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-183 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-185 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-187 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-188 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-191 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-193 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-198 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-199 Year of manufacture : 2004 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-002 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-004 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-005 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-006 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-011 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-012 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-014 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-018 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-022 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-023 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-024 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 05-025 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-028 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-029 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-032 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-033 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-034 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-035 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-036 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-037 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-038 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-041 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-042 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-044 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-045 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-048 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-049 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-050 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-051 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-053 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-054 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-055 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-056 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-058 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-060 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-062 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-063 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-065 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-066 Year of manufacture : 2005 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-067 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-068 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-070 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-071 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-072 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-074 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-075 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-080 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-085 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-086 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-088 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-092 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-093 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-094	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-095 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-096 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-097 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-099 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-100 Year of manufacture : 2005 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-012 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-016 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-024 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-054 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-055 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-058 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-060 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-061 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-063 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-068 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-075 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-077 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-082 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-083 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-086 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-088 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-092 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-093 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-094 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-097 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-098 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-100 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-103 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-105 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-107 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-108 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-109 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-110 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-111 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-113 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-115 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-116 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-117 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-118 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-120 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-121 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-122 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-124 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-125 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-127 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-128 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-130 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-132 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-135 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-136 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-137 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-138 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-139 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-142	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-144 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-146 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-147 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-148 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-149 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-151 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-152 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-154 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-155 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-160 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-162 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-163 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-165 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-166 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-167 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-168 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-169 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-170 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-171 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-173 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-177 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-178	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-179 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-180 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-181 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-182 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-185 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-186 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-187 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-188 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-190 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-191 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-193 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-194 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-197 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-198 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-201 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-204 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-205 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-206 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-207 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-208 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-209 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-210 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-211 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-214 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-215 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-220 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-222 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-224 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-225 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-226 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-227 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-228 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-232 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-237 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-238 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-240 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-244 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-245 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-247 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-248 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-250 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-251 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-252 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-253 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-255 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-256 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-258 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-259 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-260 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-261 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-264 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-265 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-267 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-270 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-273 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-276 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-277 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-278 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-280 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-282 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-288 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-290 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-291 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-293 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-294 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-296 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-300 Year of manufacture : 2006 Maximum load : 1000KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 2,6M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-002 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-016 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-001 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-003 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-004 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-005 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-006 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-007 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-008 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-009 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-010 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-011 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-012 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-013 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-014 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-015 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-016 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-018 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-019 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-020 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-021 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-022 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-023 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-024 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-025 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-026 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-027 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-028 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-029 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-030 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-031 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-032 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-033 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-034 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-035 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-036 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-037 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-038 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-040 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-041 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-042 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-043 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-044 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-045 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-046 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-047 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-049 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-050 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-051 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-052 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-053 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-054 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-055 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-056 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-057 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-058 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-059 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-060 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-061 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-062 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-063 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-064 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-065 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-066 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-067 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-068 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-069 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-070 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-071 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-072	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-073 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-074 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-075 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-076 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-077 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-078 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-079	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-080 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-081 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-082 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-083 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-084 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-085 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-086 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-087 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-088 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-089 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-090 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-091 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-092 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-093 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-094 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-095 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-096 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-097 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-098 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-099 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-101 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-102 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-103 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-104 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-105 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-106 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-107 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-108 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-109 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-110 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-111 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-112 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-113 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-114 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-115 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-116 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-117 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-118 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-119 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-120 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-121 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-122 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-123 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-124 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-125 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-126 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-127 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-128 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-129 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-130 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-131 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-132 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-133 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-134 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-135 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-136 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-137 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-138 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-139 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-140 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-141 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-142 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-143 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-144 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-145 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-146 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-147 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-148 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-149 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-150 Year of manufacture : 2004 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-002 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-003 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-004 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-006 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-007 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-008 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-009 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-010 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-011 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-012 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-013 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-014 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-015 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-016 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-017 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-018 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-019 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-020 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-021 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-022 Year of manufacture : 2005 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-023 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-024 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-025 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-026 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-027 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-028 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-029	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-031 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-032 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-033 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-034 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-035 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-036 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-037 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-038 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-039 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-040 Year of manufacture : 2005 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-007 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-012 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-024 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-041 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-054 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-055 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-056 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-058 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-060 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-061 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-063 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-065 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-068 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-070 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-071 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-072 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-075 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-077 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-082 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-083 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-084 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-085 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-088 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-090 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-091 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-092 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-093 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-094 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-097 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-098 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-099 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-100 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-102 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-103 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-104 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-105 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-106 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-107 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-108 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-109 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-110 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-111	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-112 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-113 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-114 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-115 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-116 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-117 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-118	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-120 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-128 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-136 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-161 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-177 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-188 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-190 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-192 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-193 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-196 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-202 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-211 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-226 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-241 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 11.006 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 11-12-039 Year of manufacture : 2006 Maximum load : 1000KG Length : 2,6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 3M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-040 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-005 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 02-007 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-008 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-010 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-011 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-014 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-015 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-016 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 02-020 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-025 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-026 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-027 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-033 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-35 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-037 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-039 Year of manufacture : 2002 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-041 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-044 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-049 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-050 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-052 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-053 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-054 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 02-055 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-058 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-059 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-060 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-063 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-064 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-066 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-067	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-068 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-070 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-071 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-077 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-079 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 02-080 Year of manufacture : 2002 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-001 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-003 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-005 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-006 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-007 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-008 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-010 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-011 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-012 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-014 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-015 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-016 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-018 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-019 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-020 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-021 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-022 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-024 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-025 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-026 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-027 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-030 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-031 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-033 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-034 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-035 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-040 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-041 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-042 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-043 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-044 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-045 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-046 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-047 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-048 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-050 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-051 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-052 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-054 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-055 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-056 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-058 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-059 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-060 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-061 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-064 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-071 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-072 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-074 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-075 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-077 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-078 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-080 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-081 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-083 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-084 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-086 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-087 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-088 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-089 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-095	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-097 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-098 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-099 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-100 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-101 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-102 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-103 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-104 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-105 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-106 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-108 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-109 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-110 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-111 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-112 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-113 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-114 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-116 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-117 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-118 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-121 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-122 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-126 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-128 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-129 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-130 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-134 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-135 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-136 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-137 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-138 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-139 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-140 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-142 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-143 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-145	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-146 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-147 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-149 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-150 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-012 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-016 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-024 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-041 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-055 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-056 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-058 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-060 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-061 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-065 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-068 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-070 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-075 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-077 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-082 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-083 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-085 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-086 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-088 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-090 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-093 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-094 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-097 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-098 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-099 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-104 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-108 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-109 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-110 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-111 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-113 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-114 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-116 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-118 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-120 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-123 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-124 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-126 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-127 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-128 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-129 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-130 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-131 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-132 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-133	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-135 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-136 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-137 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-138 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-139 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-140 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-141 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-142 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-143 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-144 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-145 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-147 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-148 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-149 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-150 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-151 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-152 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-155 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-156 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-157 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-158 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-161	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-163 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-166 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-168 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-169 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-170 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-171 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-174 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-175 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-176 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-177 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-178 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-179 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-183 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-185 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-186 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-187 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-189 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-190 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-192 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-193 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-194 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-195 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-196 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-197 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-198 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-200 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-202 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-203 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-204 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-205 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-206 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-207 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-208 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-209 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-210 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-212 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-215 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-216 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-217 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-218 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-219 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-221 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-222 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-223	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-225 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-226 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-227 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-228 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-229 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-230 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-231 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-232 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-233 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-235 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-236 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-237 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-238 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-239 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-240 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-241 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-242 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-243 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-244 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-245 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-246 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-248 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-250 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 48.060 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 4M WITH PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-001 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-003 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-012	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-017 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-018 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-021 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-025 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-028 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.001 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.002 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04.003 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.004 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.006 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.007 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.008 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.009 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.011 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.013 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.014 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.015 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.016 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.017 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.018 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.019 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.020 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.022 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.024 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.027 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.028 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.029 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.030 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.032 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.034 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.036 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.037 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.039 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.041 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.042 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.043	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.044 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.046 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.047 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.048 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.050 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.051 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.052	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.054 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.056 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.057 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.058 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.059 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.061 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04.063 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.064 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.065 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.066 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.067 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.068 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.069 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.070 Year of manufacture : 2004 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.071 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.072 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.073 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.074 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.075 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.076 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04.077 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.078 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.079 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.081 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.082 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-083 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.084 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.085 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04.086 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.087 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.088 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.089 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.090 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.091 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.092 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.094 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04.095 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.096 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.097 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.098 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.099 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04.100 Year of manufacture : 2004 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 05-002 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-003 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-004 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-006 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-008 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-009 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-010 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-011	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-012 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-013 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-014 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-015 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-016 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-017 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-018 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-019 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-020 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-021 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-022 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-024 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-025 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-026 Year of manufacture : 2005	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-027 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-029 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-031 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-032 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-033 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-034	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-035 Year of manufacture : 2005 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-007 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-024 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-041 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-054 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-055 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-056 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-057 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-058 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-059 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-060 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-061 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-062 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-063 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-064 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-065 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-066 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-067 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-068	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-069 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-070 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-071 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-072 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-073 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-074 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-075 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-076 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-077 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-078 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-079 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-080 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-081 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-082 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-083 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-084 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-085 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-086 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-087 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-088 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-089 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-090	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-091 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-092 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-093 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-094 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-095 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-096 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-097	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-098 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-100 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-101 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-102 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-103 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-105 Year of manufacture : 2006 Maximum load : 1000KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 0.5M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 001 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 002 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 003 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 004 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 005 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 006 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 007 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 008	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 009 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 010 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 011 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 012 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 013 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 014 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 015 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 016 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 017 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 018 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 019 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 020 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 021 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 022 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 023 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 024 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 025 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 026 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 027 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 028 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 029 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 030 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 031 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 032 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 033 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 034 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 035 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 036	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 037 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 038 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 039 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 040 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 041 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 042 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 043 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 044 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 045 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 046 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 047 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 048 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 049 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 050	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 051 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 052 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 053 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 054 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 055 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 056 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 057	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 058 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 059 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 060 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 061 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 062 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 063 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 064	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 065 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 066 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 067 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 068 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 069 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 070 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 071 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 072 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 073 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 074 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 075 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 076 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 077 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 078	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 079 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 080 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 081 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 082 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 083 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 084 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 085 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 086 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 087 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 088 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 089 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 090 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 091 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 092 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 093 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 094 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 095 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 096 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 097 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 098 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 099 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 100 Year of manufacture : 2006 Maximum load : 1280KG Length : 0.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-004 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-005 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-007 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 10-010 Year of manufacture : 2010 Maximum load : 1000KG Length : 0,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 1M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 101 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 102 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 103 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 104 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 105 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 106 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 107 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 108 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 109 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 110 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 111 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 112 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 113 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 114 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 115 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 116 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 117 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 118 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 119 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 120 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 121 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 122 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 123 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 124 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 125 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 126 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 127 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 128 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 129 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 130 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 131 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 132 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 133 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 134 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 135 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 136 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 137 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 138 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 139 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 140 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 141 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 142 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 143 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 144 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 145 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 146 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 147 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 148 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 149 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 150	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 151 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 152 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 153 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 154 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 155 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 156 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 157 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 158	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 159 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 160 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 161 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 162 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 163 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 164 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 165 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 166	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 167 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 168 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 169 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 170 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 171 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 172 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 173 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 174	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 175 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 176 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 177 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 178 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 179 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 180 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 181 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 182 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 183 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 184 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 185 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 186 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 187 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 188 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 189 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 190	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 191 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 192 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 193 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 194 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 195 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 196 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 197 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 198 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 199 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 200 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 201 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 202 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 203 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 204 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 205 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 206 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 207 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 208 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 209 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 210 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 211 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 212 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 213 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 214	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 215 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 216 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 217 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 218 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 219 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 220 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 221 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 222 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 223 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 224 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 225 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 226 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 227 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 228 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 229 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 230 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 231 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 232 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 233 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 234 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 235 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 236 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 237 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 238 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 239 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 240 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 241 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 242 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 243 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 244 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 245 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 246	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 247 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 248 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 249 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 250 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 251 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 252 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 253 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 254 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 255 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 256 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 257 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 258 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 259 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 260 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 261 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 262 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 263 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 264 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 265 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 266 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 267 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 268 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 269	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 270 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 271 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 272 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 273 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 274 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 275 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 276 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 277 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 278 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 279 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 280 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 281 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 282 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 283 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 284 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 285 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 286 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 287 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 288 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 289 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 290 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 291 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 292 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 293 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 294 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 295 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 296 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 297 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 298 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 299 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 300 Year of manufacture : 2006 Maximum load : 1280KG Length : 1M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 1.5M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-002	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-003 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-004 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-006 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-011 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-017 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-020 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-024 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 03-028 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-032 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-033 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-034 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-038 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-044 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-045 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-050 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 03-051 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-052 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-053 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-060 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-061 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-062 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-070 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-071 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-072 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-073 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-083 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-084 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-089 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 03-090 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-002 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-009	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-010 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-012 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-017 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-028 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-030 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-034 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-037 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-038 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-039 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-042 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-045 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-050 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-051 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-064 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-067 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-068 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-069 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-070 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-073 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-079 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-081 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-082 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-085 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-086 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-088 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-089 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-094 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-096 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-097 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-099 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-001	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-002 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-007 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-009 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-011 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-012 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-019 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-020 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-022 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-030 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-032 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-034 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-040 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-044 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-048 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 05-051 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-054 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-060 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-061 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-063 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-066 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-067 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-072	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-075 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-080 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-086 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-094 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-096 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 05-099 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 301 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 302 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 303 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 304 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 305 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 306 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 307 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 308 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 309	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 310 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 311 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 312 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 313 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 314 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 315 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 316 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 317 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 318 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 319 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 320 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 321 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 322 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 323 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 324 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 325 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 326 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 327 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 328 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 329 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 330 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 331 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 332 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 333 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 334 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 335 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 336 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 337 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 338 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 339 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 340 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 341 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 342 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 343 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 344 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 345 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 346 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 347 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 348 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 349 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 350 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 351 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 352 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 353	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 354 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 355 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 356 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 357 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 358 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 359 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 360 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 361 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 362 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 363 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 364 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 365 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 366 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 367 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 368 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 369 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 370 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 371 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 372 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 373 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 374 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 375 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 376 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 377 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 378 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 379 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 380 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 381 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 382 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 383	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 384 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 385 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 386 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 387 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 388 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 389 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 390 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 391 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 392 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 393 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 394 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 395 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 396 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 397 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 398 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 399 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 400 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 401 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 402 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 403 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 404 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 405 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 406 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 407 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 408 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 409 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 410 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 411 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 412 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 413 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 414 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 415 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 416 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 417 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 418 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 419 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 420 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 421 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 422 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 423 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 424 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 425 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 426 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 427 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 428 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 429 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 430 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 431 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 432 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 433 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 434 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 435 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 436 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 437 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 438 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 439 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 440 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 441 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 442	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 443 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 444 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 445 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 446 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 447 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 448 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 449 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 450 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 451 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 452 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 453 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 454 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 455 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 456 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 457 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 458 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 459 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 460 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 461 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 462 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 463 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 464 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 465 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 466 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 467 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 468 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 469 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 470 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 471 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 472 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 473 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 474 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 475 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 476 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 477 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 478 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 479 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 480 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 481 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 482 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 483 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 484 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 485 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 486 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 487 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 488 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 489 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 490 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 491 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 492 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 493 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 494 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 495 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 496 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 497 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 498 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 499 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 500 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 501 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 502 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 503 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 504 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 505 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 506 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 507 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 508 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 509 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 510 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 511 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 512 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 513 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 514 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 515 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 516 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 517 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 518 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 519 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 520 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 521 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 522 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 523 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 524 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 525 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 526 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 527 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 528 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 529 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 530 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 531 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 532 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 533 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 534 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 535 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 536 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 537 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 538 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 539 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 540 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 541 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 542 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 543 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 544 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 545 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 546 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 547 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 548 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 549 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 550 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 551 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 552 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 553 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 554 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 555 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 556 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 557 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 558 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 559 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 560 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 561 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 562 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 563 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 564 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 565 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 566 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 567 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 568 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 569 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 570 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 571 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 572 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 573 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 574 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 575 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 576 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 577	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 578 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 579 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 580 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 581 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 582 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 583 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 584	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 585 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 586 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 587 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 588 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 589 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 590 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 591 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 592 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 593 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 594 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 595 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 596 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 597 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 598	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 599 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 600 Year of manufacture : 2006 Maximum load : 1280KG Length : 1.5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 2M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-098 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 601 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 602 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 603 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 604 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 605 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 606 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 607 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 608 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 609 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 610 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 611 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 612 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 613 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 614 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 615 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 616 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 617 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 618 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 619 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 620 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 621 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 622 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 623 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 624 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 625 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 626 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 627 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 628	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 629 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 630 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 631 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 632 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 633 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 634 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 635 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 636 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 637 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 638 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 639 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 640 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 641 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 642 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 643 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 644 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 645 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 646 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 647 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 648 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 649 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 650 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 651 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 652 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 653 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 654 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 655 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 656 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 657 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 658 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 659 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 660 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 661 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 662 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 663 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 664 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 665 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 666 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 667 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 668 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 669 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 670 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 671 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 672 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 673 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 674 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 675 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 676 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 677 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 678 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 679 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 680 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 681 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 682 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 683 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 684 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 685 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 686 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 687 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 688 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 689 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 690 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 691 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 692 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 693 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 694 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 695 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 696 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 697 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 698 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 699 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 700 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 701 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 702 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 703 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 704 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 705 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 706 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 707 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 708 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 709 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 710 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 711 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 712 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 713 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 714 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 715	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 716 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 717 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 718 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 719 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 720 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 721 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 722 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 723	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 724 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 725 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 726 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 727 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 728 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 729 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 730 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 731 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 732 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 733 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 734 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 735 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 736 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 737 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 738 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 739 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 740 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 741 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 742 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 743 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 744 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 745 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 746 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 747	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 748 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 749 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 750 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 751 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 752 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 753 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 754 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 755 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 756 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 757 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 758 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 759 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 760 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 761 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 762 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 763 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 764 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 765 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 766 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 767 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 768 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 769	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 770 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 771 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 772 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 773 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 774 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 775 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 776 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 777 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 778 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 779 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 780 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 781 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 782 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 783 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 784 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 785 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 786 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 787 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 788 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 789 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 790 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 791 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 792 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 793 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 794 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 795 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 796 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 797 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 798 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 799 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 800	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 801 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 802 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 803 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 804 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 805 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 806 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 807 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 808 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 809 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 810 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 811 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 812 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 813 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 814 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 815 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 816 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 817 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 818 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 819 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 820 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 821 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 822 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 823 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 824 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 825 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 826 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 827 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 828 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 829 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 830 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 831 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 832 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 833 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 834 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 835 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 836 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 837 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 838 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 839 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 840 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 841 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 842 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 843 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 844 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 845 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 846 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 847 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 848 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 849 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 850 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 851 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 852 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 853 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 854 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 855 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 856 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 857 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 858 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 859 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 860 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 861 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 862 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 863 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 864 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 865 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 866 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 867 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 868 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 869 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 870	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 871 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 872 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 873 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 874 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 875 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 876 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 877 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 878 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 879 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 880 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 881 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 882 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 883 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 884 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 885 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 886 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 887 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 888 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 889 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 890 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 891 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 892 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 893 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 894 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 895 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 896 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 897 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 898 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 899 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 900 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 901 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 902 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 903 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 904 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 905 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 906 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 907 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 908 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 909 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 910 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 911 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 912 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 913 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 914 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 915 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 916 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 917 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 918 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 919 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 920 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 921 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 922 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 923 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 924 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 925 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 926 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 927 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 928 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 929 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 930 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 931 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 932 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 933 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 934 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 935 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 936 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 937 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 938 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 939 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 940 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 941 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 942 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 943 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 944 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 945 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 946 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 947 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 948 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 949 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 950 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 951 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 952 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 953 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 954 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 955 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 956 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 957	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 958 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 959 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 960 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 961 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 962 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 963 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 964 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 965 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 966 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 967 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 968 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 969 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 970 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 971 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 972 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 973 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 974 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 975 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 976 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 977 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 978 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 979 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 980 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 981	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 982 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 983 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 984 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 985 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 986 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 987 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 988 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 989 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 990 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 991 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 992 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 993 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 994 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 995 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 996 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 997 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 998 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 999 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1000 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1001 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 07-030 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 07-079 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-036 Year of manufacture : 2006 Maximum load : 1280KG Length : 2M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 3M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-008	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2001 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-046 Year of manufacture : 2001 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 01-053 Year of manufacture : 2001 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-037 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-079 Year of manufacture : 2004 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-063 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-099 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-112	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-0142 Year of manufacture : 2006 Maximum load : 1000KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1001 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1002 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1003 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1004 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1005 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1006 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1007 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1008 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1009 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1010 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1011 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1012 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1013 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1014 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1015 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1016 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1017 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1018 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1019 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1020 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1021 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1022 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1023 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1024 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1025 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1026 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1027 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1028 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1029 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1030 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1031 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1032 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1033 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1034 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1035 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1036 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1037 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1038 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1039 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1040 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1041 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1042 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1043 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1044 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1045 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1046 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1047 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1048 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1049 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1050 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1051 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1052 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1053 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1054 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1055 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1056 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1057 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1058 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1059 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1060 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1061 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1062 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1063 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1064 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1065 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1066 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1067 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1068 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1069 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1070 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1071 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1072 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1073 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1074 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1075 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1076 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1077 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1078 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1079 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1080 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1081 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1082 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1083 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1084 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1085	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1086 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1087 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1088 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1089 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1090 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1091 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1092 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1093	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1094 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1095 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1096 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1097 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1098 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1099 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1100 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1101 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1102 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1103 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1104 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1105 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1106 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1107 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1108	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1109 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1110 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1111 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1112 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1113 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1114 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1115 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1116	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1117 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1118 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1120 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1121 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1122 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1123 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1124 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1125 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1126 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1127 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1128 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1129 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1130 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1131 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1132 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1133 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1134 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1135 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1136 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1137 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1138 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1139 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1140 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1141 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1142 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1143 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1144 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1145 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1146 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1147 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1148 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1149 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1150 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1151 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1152 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1153 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1154 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1155 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1156 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1157 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1158 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1159 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1160 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1161 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1162 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1163 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1164	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1165 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1166 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1167 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1168 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1169 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1170 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1171 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1172 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1173 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1174 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1175 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1176 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1177 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1178 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1179 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1180 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1181 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1182 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1183 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1184 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1185 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1186 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1187 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1188 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1189 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1190 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1191 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1192 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1193 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1194 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1195 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1196 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1197 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1198 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1199 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1200 Year of manufacture : 2006 Maximum load : 1280KG Length : 3M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 4M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1201 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1202 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1203 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1204 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1205 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1206 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1207 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1208 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1209 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1210 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1211 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1212 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1213 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1214 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1215 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1216 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1217 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1218 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1219 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1220 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1221 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1222 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1223 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1224 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1225 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1226 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1227 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1228 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1229 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1230 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1231 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1232 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1233 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1234 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1235 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1236 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1237 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1238 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1239 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1240 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1241 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1242 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1243 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1244 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1245 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1246 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1247	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1248 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1249 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1250 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1251 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1252 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1253 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1254 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1255 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1256 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1257 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1258 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1259 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1260 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1261 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1262 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1263 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1264 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1265 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1266 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1267 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1268 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1269 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1270 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1271 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1272 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1273 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1274 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1275 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1276 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1277 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1278 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1279 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1280 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1281 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1282 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1283 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1284	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1285 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1286 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1287 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1288 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1289 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1290 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1291 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1292 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1293 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1294 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1295 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1296 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1297 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1298 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1299 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1300 Year of manufacture : 2006 Maximum load : 1280KG Length : 4M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 5M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 002 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 007 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 009 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 011 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 016 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 030 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 031 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 033 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 035 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 036 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 038 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-02 Year of manufacture : 2004 Maximum load : 100KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-03	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-04 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-05 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-07 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-08 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-11 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-12 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-15 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-18 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-19 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-20 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-21 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-22 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-24 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-25 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-26 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-27 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-28 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-29 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-30 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-31 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-32 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-35 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-36 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-37 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-40 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-42 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-43 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-49 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-50 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-51 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-52 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-53 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-54 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-59 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-60 Year of manufacture : 2004 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-007 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1500KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-021 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-023 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-041 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-042 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-045 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1500KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-001 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-002 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-003 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-004 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-005 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-006 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : A18-007 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-008 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-010 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-011 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-012 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-013 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-014 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-015 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-017 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-018 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : A18-019 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-020 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-022 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-023 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-024 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-025 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-026 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-027 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-028 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-029 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : A18-030 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18--032 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-033 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-034 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-035 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-036 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-037 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-038 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-039 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : A18-040 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-041 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-042 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-044 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-045 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-046 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-048 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-049 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-051 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-052 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-053 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-054 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-057 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-058 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-059 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-061 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-062 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-065 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-066	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-067 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-068 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-072 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-074 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-076 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-077 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-078 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-079 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : A18-080 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-082 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-083 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-084 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-085 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-089 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-091 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-093 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-094 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-095 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : A18-099 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-097 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-095 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A18-099 Maximum load : 1000KG Length : 5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 6M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1301 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1302 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1303 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1304 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 06 1305 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1306 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1307 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1308 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1309 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1310 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1311 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1312 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1313 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1314 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1315 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1316 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1317 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1318 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1319 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1320 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1321 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1322 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1323 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1324 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1325 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1326 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1327 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1328 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1329 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1330 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1331 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1332 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1333 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1334 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1335 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1336 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1337 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1338 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1339 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1340 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1341 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1342 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1343 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1344 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1345 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1346 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1347 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1348 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1349 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06 1350 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1351 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1352 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1353 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1354 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1355 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1356 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1357	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1358 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1359 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1360 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1361 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1362 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1363 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1364	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1365 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1366 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1367 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1368 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1369 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1370 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1371 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1372 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1373 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1374 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1375 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1376 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1377 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1378 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1379 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1380 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1381 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1382 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1383 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1384 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1385 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1386 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1388 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1389 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1390 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1391 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1392 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1393 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1394 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1395 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1396 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1397 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1398 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1399 Year of manufacture : 2006 Maximum load : 1280KG Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06 1400 Year of manufacture : 2006 Maximum load : 1280KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 6M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
SLINGS 1000KG - 8M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 001 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 002 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 003 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 005 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 007 Maximum load : 1500KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 008 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 009 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 011 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 012 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 014 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 015 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 016 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 017 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 018 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 019 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 022 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 024 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 026 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 028 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 029 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 030 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 032 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 035 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 036 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 037 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-01 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-02 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-03 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 04-04 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-05 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-06 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-07 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-09 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-10 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-11 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-12 Year of manufacture : 2004	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-13 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-14 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-16 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-17 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-18 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-19 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-20	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-21 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-22 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-25 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-26 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-27 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-29 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-30	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-31 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-32 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-33 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-34 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-35 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-37 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Client number of the equipment : 04-39 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 04-40 Year of manufacture : 2004 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-001 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-004 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-007 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-009 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-010 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-011 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-012 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-013 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-014 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-015 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-016 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-017 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-018 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-019 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-020 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-022 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-024 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-025 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-026 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-027 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-028 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-029 Year of manufacture : 2006	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-030 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-031 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-032 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-033 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-034 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-035 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-036 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Nature : SLING Client number of the equipment : 06-037 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-038 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-039 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-040 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-043 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-044 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-046 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-047 Year of manufacture : 2006 Maximum load : 1500KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 98/8/86 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 98/8/87 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 98/8/88 Maximum load : 1500KG Length : 8M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
SLINGS 1000KG - 12M WITHOUT PLASTIC	
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 003 Year of manufacture : 2010 Maximum load : 1000KG	(see next page)

DESCRIPTION OF THE DEVICES	FINDINGS
Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 004 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 005 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 007 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 011 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 013 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A10 014 Year of manufacture : 2010 Maximum load : 1000KG Length : 12M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
BASKET RIG 1000KG - 1,5M WITH PLASTIC	
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 001
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 002
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 003
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 004
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 005
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 007
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 008

(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 010 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 011 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 012 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 014 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 016 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 018 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING Client number of the equipment : 019 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 020 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 022 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 023 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 024 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 025 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 026 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 027 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 028
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 029
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 030
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 031
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 032
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 033
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 034
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 035
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 036
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 037
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 038
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 039
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 040
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 041
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 042
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 043
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 044
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 045
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 046
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 047
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 048
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 049
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 051
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 052
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 053
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 054
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 055
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 056
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 057
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 058
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 059
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 060

(see next page)

Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 061
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 062
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 063
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 064
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 065
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 066
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 067
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 068
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 071
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 075
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 076
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 077
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 079
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 080
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 081

(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 083 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 084 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 085 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 086 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 087 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 088 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 089	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 090 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 091 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 092 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 094 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 097 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 098 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 099	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 100 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 101 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 102 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 104 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 108 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 109 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 113	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 114 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 115 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 116 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 118 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 119 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 120 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 121	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 122 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 125 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 126 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 127 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 128 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 129 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 130 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 132
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 133
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 135
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 136
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 138
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 139
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 141
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 142

(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 144 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 145 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 146 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 147 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 148 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 149 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 150 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 151
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 152
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 154
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 155
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 156
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 157
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 159
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 160
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING Client number of the equipment : 161 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 164 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 165 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 166 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 167 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 169 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 170 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 172 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 175	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 176 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 177 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 178 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 179 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 180 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 181 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 182 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 184
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 185
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 186
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 187
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 188
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 189
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 195
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 196
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING

(see next page)

Client number of the equipment : 197
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 198
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 200
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A008
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A011
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A012
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A016
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A018
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING Client number of the equipment : A019 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A025 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A034 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A036 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A044 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A052 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A062 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A065 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : A066
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A076
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A084
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A086
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A092
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A093
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A096
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A097
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : A098
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A105
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A108
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A109
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A114
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A115
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A116
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A123
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING

(see next page)

Client number of the equipment : A124
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A126
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A133
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A137
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A138
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A139
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A142
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A146
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : A156
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A158
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A159
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A163
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A164
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A165
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A169
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A170
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : A176
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A177
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A182
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A184
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A187
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A188
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A189
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : A190

(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A191 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A193 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A194 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A195 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A196 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A197 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A198	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : A200 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-002 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-003 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-005 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-006 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-007 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-008 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 06-009
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-010
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-012
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-014
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-015
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-016
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-018
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-019

(see next page)

Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-020
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-022
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-023
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-024
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-025
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-027
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-028
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 06-029
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-031
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-032
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-033
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-034
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-035
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-036
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-037
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 06-040
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-041
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-042
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-043
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-044
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-045
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-046
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-047
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-048 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-049 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-050 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-051 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-052 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-053 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-054	(see next page)

Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-055
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-056
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-057
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-059
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-060
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-061
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-062

(see next page)

Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-065
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-066
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-067
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-068
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-070
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-071
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-072
Year of manufacture : 2006

(see next page)

Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-073
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-075
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-076
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-077
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-078
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-079
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-080

(see next page)

Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-081
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-083
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-084
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-085
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-086
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-087
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-088
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-089
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-090
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-091
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-092
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-094
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-095
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-096
Year of manufacture : 2006

(see next page)

Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-097
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-099
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-100
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-101
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-102
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-103
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-104
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-105
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-106
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-107
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-108
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-109
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-110
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-111
Year of manufacture : 2006

(see next page)

Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-112
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-113
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-114
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-115
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-116
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-117
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-118
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-119 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-120 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-122 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-123 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-125 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-126 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-127 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

Client number of the equipment : 06-128
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-130
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-132
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-135
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-136
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-137
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-138
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-139
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 06-140
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-143
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-144
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-145
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-146
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-147
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-148
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-149
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-150
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-151
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-154
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-155
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-156
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-157
Year of manufacture : 2006
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 06-158
Year of manufacture : 2006
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-159 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-160 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-163 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-164 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 06-165 Year of manufacture : 2006 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-002 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-005 Year of manufacture : 2009	(see next page)

Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-006
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-007
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-008
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-009
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-011
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-012
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-013
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-014
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-015
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-018
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-019
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-021
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-022
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-023
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-024
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-025
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-026
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-027
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-028
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-029
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-030
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-031
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-032
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-033
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-034
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-035
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-036
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-037
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-038
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-039
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-040
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-041
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-042
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-043
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-044
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-045
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-046
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-047
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-048
Year of manufacture : 2009

(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-049 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-051 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-052 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-053 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-054 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-055 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-056 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 09-057
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-058
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-059
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-062
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-064
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-065
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-066
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-067
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-068
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-069
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-070
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-071
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-072
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-073
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-074
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-076
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-077
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-078
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-079
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-080
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-081
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-082
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-083
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-084 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-086 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-087 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-088 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-089 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-090 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-091 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

Client number of the equipment : 09-092 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-093 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-094 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-095 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-096 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-098 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-099 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-100 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 09-101
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-102
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-103
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-104
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-105
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-106
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-107
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-108
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING

(see next page)

Client number of the equipment : 09-110
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-111
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-112
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-113
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-114
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-115
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-116
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-117
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-118 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-119 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-120 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-121 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-122 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-123 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-124 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

Client number of the equipment : 09-126
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-127
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-128
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-129
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-130
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-131
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-132
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-134
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-135 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-136 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-137 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-138 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-139 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-140 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-141 Year of manufacture : 2009	(see next page)

Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-142 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-143 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-144 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-145 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-146 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-147 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-148 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 09-149
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-150
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-151
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-152
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-154
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-155
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-156
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-157
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-158 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-159 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-160 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-161 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-162 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-163 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-164 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING	(see next page)

Client number of the equipment : 09-165
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-167
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-168
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-169
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-170
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-171
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-172
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-173
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-174
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-175
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-176
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-177
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-179
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-180
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-181
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-182
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-183
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-184
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-185
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-186
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-188
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-189
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-190
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-191
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-192
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-193
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-194
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-195
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-196
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-197
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-198
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-199
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-200
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-201
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-202
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-203
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-204
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-205
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-206
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-207
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-208
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-210
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-211
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-212
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-213
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-214
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-215
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-216
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-217
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-218
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-219
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-220
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-221
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-223
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-224
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-226
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-228
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-229
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-230
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-233
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-234
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-235
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-236
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-238
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING

(see next page)

Client number of the equipment : 09-239
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-240
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-241
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-242
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-243
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-244
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-245
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-246
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-248
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-249
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-250
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-251
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-252
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-253
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-254
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-255
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-256
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-258
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-259
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-260
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-261
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-262
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-263
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-264
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)

(see next page)

Nature : SLING
Client number of the equipment : 09-265
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-266
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-267
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-268
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-269
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-270
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-272
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

---

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-273
Year of manufacture : 2009
Maximum load : 1000KG

(see next page)

Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-274 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-275 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-277 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-279 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-280 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-281 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-282 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic)	(see next page)

Nature : SLING
Client number of the equipment : 09-283
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-284
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-285
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-286
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-287
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-288
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-289
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-290
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING

(see next page)

Client number of the equipment : 09-291 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-292 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-293 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-294 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-295 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-296 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-297 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** Not inspected: not presented. ***Conclusion*** The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service
Sling (cable/synthetic) Nature : SLING Client number of the equipment : 09-298 Year of manufacture : 2009 Maximum load : 1000KG Length : 1,5M	**** Conditions and operation inspection (10.2018)*** ***Conclusion*** The material can be used, no abnormalities were found when inspecting the material
Sling (cable/synthetic) Nature : SLING	(see next page)

Client number of the equipment : 09-299
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***

Conclusion
The material can be used, no abnormalities were found when inspecting the material

Sling (cable/synthetic)
Nature : SLING
Client number of the equipment : 09-300
Year of manufacture : 2009
Maximum load : 1000KG
Length : 1,5M

**** Conditions and operation inspection (10.2018)***
Not inspected: not presented.

Conclusion
The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Total of the equipment inspected

1813	10407001	Sling (cable/synthetic)	Cond. & Oper.Insp. or Prev.

Total of the equipment not inspected

2917	10407001	Sling (cable/synthetic)	Cond. & Oper.Insp. or Prev.