

VINÇOTTE vzw

Certified inspection body I External service for technical inspections at the workplace Registered Office: Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium

VAT BE 0402.726.875 • RPM/RPR Brussels • BNP Paribas Fortis: BE25 2100 4144 1482 • BIC : GEBABEBB



Jan Olieslagerslaan 35 • 1800 Vilvoorde • Belgium • phone: +32 2 674 57 11 • brussels@vincotte.be

Our References

Report n°: AUD/10/14446288/00/EN Contract Ref.: 0001011189/22000

Your References

Ref.: Brief ref.: WBE/ADB dd 04/11/09 04112009

Intervention data

Area: AED Rent nv Bedrijvenpark De Veert, 12 2830 Willebroek BELGIUM

Date of visit: 26.04.2023

Performed by: DE MAEYER STEIN (5907)

Periodical report concerning your Common lifting equipment and similar equipment.

AED Rent nv

2830 Willebroek

**BELGIUM** 

Bedrijvenpark De Veert, 12

# Conclusions founded in this report:

- 121 The material was not available during inspection, or could only be partly inspected, without an additional inspection we cannot ensure the safe use of the material
- 89 The material can be used

Please also take into account the conclusions mentioned in any other reports concerning the identified material.

# Important note

Covered by article 2 of the Belgian Royal Decree of 12 August 1993, applicable since 01 January 1997, the inspected equipment involves work equipment. Periodical inspections on the basis of art. 281 of the ARAB (Belgian General Regulations on Occupational Safety) are not intended to check the compliance of this equipment with the new requirements in the Royal Decree on work equipment.

When required, we are available to carry out a specific inspection on the basis of this RD. Please do not hesitate to contact us for further information.

Please also ensure you that other regulations are not applicable for you.

Ing. J. WINDEY General Manager

If you wish to make a complaint or comment on our services, please contact us on www.vincotte.be, section Contact.

Date of issue: 03/05/2023 Page: 1/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

# **BASIS AND CONTENTS OF OUR INSPECTIONS**

#### 1. GENERAL PRINCIPLES

Our periodical inspections are carried out without any prior dismantling and without any loads, as stipulated in art. 281 of the Belgian General Regulations on Occupational Safety (ARAB) and according to the RD of 9 March 2003 + amendments for passenger lifts. They include the visual inspection of the proper condition of the accessible elements and checking the devices and components that are important for safety. These inspections are not intended to check the design of the equipment, nor do they include the inspection ensuring compliance with the requirements of the RD of 12 August 1993 as amended (Work equipment).

- New passenger lifts shall be subject to a final inspection according to the prescriptions of the lifts Directive 2014/33/EU;
- Existing passenger lifts shall be subject to a risk analysis and/or a pre-recommissioning inspection by an EDTC according to the RD of 09 March 2003 + amendments;
- Lifting equipment and lifting accessories shall be subject to a pre-(re)commissioning inspection by an EDTC, according to art. 280 of the ARAB. After any major modification or repair of such equipment, an inspection prior to recommissioning is also required by an EDTC. The report on the pre-(re)commissioning inspection must be in your possession at all times.
- Personal protective equipment against falling from heights shall be subject to a pre-recommissioning inspection by an EDTC after a fall of a person, according to the RD of 13/06/2005.

#### 2. FREQUENCY

For businesses and enterprises subject to the ARAB, the frequency of lifting equipment inspections is at least every 3 months, in accordance with art. 281. Moreover, an annual inspection of the mechanisms and the structures is required. For other equipment, the frequency is determined by the articles in the regulation mentioned below, or by the agreement. For passenger lifts, the frequency of the preventive inspections is at least every three months or, under certain circumstances, annually, completed by a six-monthly inspection. The next inspection (or beginning of that inspection) must be within the applicable periodicity, calculated from the date of this inspection (inspection period).

# 3. INSPECTION PROGRAMS (non exhaustive lisiting)

Vinçotte reference	Equipment	Vinçotte procedure	Legislation
L1010	passenger lifts	CL1	RD of 09/03/2003
L1010	Site lifts, goods lifts, servicelift	CL13	ARAB, art. 281
L1011 L1051 L1012 L1022 L1013	Standard lifting equipment, lifting accessories,lifting platforms, material for scaffolding, standard handling equipment, firefighting equipment	CL2 - CL3 CL9 - CL15	ARAB, art. 281 RD of 31/08/2005
L1014	Personal protective equipment (PPE) against falling from heights: safety belts and harnesses, anchorage points, lifelines	CL14	art. 27-RD of 13/06/2005
L1016 L1017	Building site equipment and similar: tower cranes, mobile cranes, materials lifts, movable suspended scaffolding, buckets, baskets, saddles, construction site hoists	CL2, CL4, CL6, CL16, CL18, CL19, CL20	ARAB, art. 281, 452, 453
L1031	cableways	CL11	ARAB, art. 281, 282
L1019	escalators and travellators	CL8	Code H&S, Directive 2006/42/EC
L1026	metal curtains	CL10	ARAB, art. 662
L1020, L1021	specific port equipment and gear	CL2 - CL17	ARAB, art. 281, regulations of 01/02/1994 + amendment
L1018	vehicle lifts	CL5	ARAB, art. 283bis
L1028	playgrounds and playground equipment	CL7	RD of 28/03/2001
L1030	attractions and amusement park equipment	CL12	RD of 10/06/01, of 18/06/03
P3513	acetylene generators, pressure regulators, burners, flame arresters	35130043	RD of 13/06/1999
P3515	centrifuges and similar equipment	3515	ARAB, art. 323

Other equipment is inspected in the light of art. 281 of the ARAB.

Electrical welding equipment: visual inspection without measurements. Electrical measurements must be carried out to check compliance of such equipment with the requirements of art. 57 of the AREI (Belgian general regulations on electrical installations). They should be carried out in particular at the time of commissioning, after each repair or modification, at each new destination or installation in a higher risk environment, on a periodical basis, the frequency being determined according to the results of a risk analysis.

Our electrical inspection department is available for carrying out the measurements.

Stands, stages: our inspection only concerns the state of the stand of the stage. It does not concern the national requirements regarding evacuation in case of fire or other statutory provisions. In particular the correct implementation of the requirements of the Belgian Royal Decree of 17 July 1989 + amendment, regarding the protection of spectators against fire and panic in permanent stadiums, was not checked.

# 4. INFORMATION FOR READING THE REPORT

Equipment identification: the information reported here is intended solely for clearly identifying the inspected equipment and is given for illustrative purposes only, in particular as regards the payload.

Inspections marked "\*" must statutorily be carried out by an external agency for technical inspections at the work location (EDTC)(RD of 29/04/1999).

- Notes: these are provided for information purposes only and do not affect the conclusions of the inspection.
- Remarks: these result in the obligation to remedy the situation as soon as possible.
- Urgent remarks: these result in the obligation to remedy the situation before any further use.

A copy of the checklists (CL) used during the inspections is available upon request.

This report is not the risk analyses stipulated in the Royal Decree of 12/08/1993 + amendments (Work equipment - Code) nor the approval of the choice of the work equipment by the user.

Please also make sure there are no other applicable regulations.

We are at you disposal if you require any further information.

Date of issue: 03/05/2023 Page: 2/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

# **DESCRIPTION OF THE DEVICES**

# **ELECTRIC HOISTS 1000KG TYPE SR10**

# **PULLEYS ELECTRICAL 1000KG TYPE SR10**

# **Motor-driven hoist**

Nature: MOTOR-DRIVEN HOIST Serial number: 1403000176 Make: VERLINDE - STAGEMAKER Client number of the equipment: 005

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1404000399 Make: VERLINDE - STAGEMAKER Client number of the equipment: 009

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1404000402 Make: VERLINDE - STAGEMAKER Client number of the equipment: 010

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1404000406

Make: VERLINDE - STAGEMAKER Client number of the equipment: 014

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# **FINDINGS**

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 3/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1404000410 Make: VERLINDE - STAGEMAKER Client number of the equipment: 018

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1404000420 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 026

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1404000421 Make: VERLINDE - STAGEMAKER Client number of the equipment: 027

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1404000440 Make: VERLINDE - STAGEMAKER Client number of the equipment: 037

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1404000442 Make: VERLINDE - STAGEMAKER Client number of the equipment: 038

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 03/05/2023 Page: 4/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1404000446 Make: VERLINDE - STAGEMAKER Client number of the equipment: 040

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000628 Make: VERLINDE - STAGEMAKER Client number of the equipment: 047

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000629 Make: VERLINDE - STAGEMAKER Client number of the equipment: 048

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000639 Make: VERLINDE - STAGEMAKER Client number of the equipment: 057

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1405000642 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 060

Type: SR10 1004 M1-A

Date of issue: 03/05/2023 Page: 5/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000645 Make: VERLINDE - STAGEMAKER Client number of the equipment: 063

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000649 Make: VERLINDE - STAGEMAKER Client number of the equipment: 067

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000654 Make: VERLINDE - STAGEMAKER Client number of the equipment: 072

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1405000667 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 084

Type: SR10 1004 M1-A

Date of issue: 03/05/2023 Page: 6/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000668 Make: VERLINDE - STAGEMAKER Client number of the equipment: 085

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1405000675 Make: VERLINDE - STAGEMAKER Client number of the equipment: 092

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1406000681 Make: VERLINDE - STAGEMAKER Client number of the equipment: 098

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1405000692 (see next page)

Date of issue: 03/05/2023 Page: 7/49



Make: VERLINDE - STAGEMAKER Client number of the equipment: 106

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist Nature: MOTOR-DRIVEN HOIST Serial number: 1405000693

Make: VERLINDE - STAGEMAKER Client number of the equipment: 107

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1407000910 Make: VERLINDE - STAGEMAKER Client number of the equipment: 109

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1407000930 Make: VERLINDE - STAGEMAKER Client number of the equipment: 113

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1407000939 Make: VERLINDE - STAGEMAKER Client number of the equipment: 122

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1407000947

(see next page)

Date of issue: 03/05/2023 Page: 8/49



Make: VERLINDE - STAGEMAKER Client number of the equipment: 130

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1408001081 Make: VERLINDE - STAGEMAKER Client number of the equipment: 132

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1408001085 Make: VERLINDE - STAGEMAKER Client number of the equipment: 135

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001323 Make: VERLINDE - STAGEMAKER Client number of the equipment: 157

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001324 Make: VERLINDE - STAGEMAKER Client number of the equipment: 158

Type: SR10 1004 M1-A Year of manufacture: 2014 \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

#### Conclusion

# The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 9/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001327 Make: VERLINDE - STAGEMAKER Client number of the equipment: 161

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001335 Make: VERLINDE - STAGEMAKER Client number of the equipment: 167

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001338 Make: VERLINDE - STAGEMAKER Client number of the equipment: 170

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1409001342 (see next page)

Date of issue: 03/05/2023 Page: 10/49



Make : VERLINDE - STAGEMAKER Client number of the equipment : 173

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist \* Conditions and operation inspection (07.2023)

Nature: MOTOR-DRIVEN HOIST Not inspected: not presented.

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001345 Make: VERLINDE - STAGEMAKER Client number of the equipment: 176

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Serial number: 1409001346

Type: SR10 1004 M1-A

Maximum load: 1000KG

Year of manufacture: 2014

Make: VERLINDE - STAGEMAKER

Client number of the equipment: 177

Length: 20M

\* Mechanism and structure inspection (04 2024

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist\* Conditions and operation inspection (07.2023)Nature: MOTOR-DRIVEN HOISTNot inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Length: 20M

Nature: MOTOR-DRIVEN HOIST Serial number: 1409001347 Make: VERLINDE - STAGEMAKER Client number of the equipment: 178

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1410001468 (see next page)

Date of issue: 03/05/2023 Page: 11/49



Make: VERLINDE - STAGEMAKER Client number of the equipment: 181

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001470 Make: VERLINDE - STAGEMAKER Client number of the equipment: 183

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001471 Make: VERLINDE - STAGEMAKER

Client number of the equipment: 184

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001472 Make: VERLINDE - STAGEMAKER Client number of the equipment: 185

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001476 Make: VERLINDE - STAGEMAKER Client number of the equipment: 189

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 12/49



Nature : MOTOR-DRIVEN HOIST Serial number : 1410001485 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 196

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001486 Make: VERLINDE - STAGEMAKER Client number of the equipment: 197

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001492 Make: VERLINDE - STAGEMAKER Client number of the equipment: 201

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1410001494 Make: VERLINDE - STAGEMAKER Client number of the equipment: 202

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1412001897 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 204

Type: SR10 1004 M1-A

Date of issue: 03/05/2023 Page: 13/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001898 Make: VERLINDE - STAGEMAKER Client number of the equipment: 205

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001899 Make: VERLINDE - STAGEMAKER Client number of the equipment: 206

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001910 Make: VERLINDE - STAGEMAKER Client number of the equipment: 207

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001911 Make: VERLINDE - STAGEMAKER Client number of the equipment: 208

Type: SR10 1004 M1-A Year of manufacture: 2014

Date of issue: 03/05/2023 Page: 14/49



Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist
Nature: MOTOR-DRIVEN HOIST
Serial number: 1412001915

Make: VERLINDE - STAGEMAKER
Client number of the equipment: 212

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001918 Make: VERLINDE - STAGEMAKER Client number of the equipment: 215

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001919 Make: VERLINDE - STAGEMAKER Client number of the equipment: 216

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001920 Make: VERLINDE - STAGEMAKER Client number of the equipment: 217

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Length: 20M Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 15/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1412001921 Make: VERLINDE - STAGEMAKER Client number of the equipment: 218

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist
Nature: MOTOR-DRIVEN HOIST
Serial number: 1412001923
Make: VERLINDE - STAGEMAKER
Client number of the equipment: 220

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001926 Make: VERLINDE - STAGEMAKER Client number of the equipment: 223

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001928 Make: VERLINDE - STAGEMAKER Client number of the equipment: 225

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001929 Make: VERLINDE - STAGEMAKER Client number of the equipment: 226

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 16/49



Nature : MOTOR-DRIVEN HOIST Serial number : 1412001930 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 227

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001932 Make: VERLINDE - STAGEMAKER Client number of the equipment: 229

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001935 Make: VERLINDE - STAGEMAKER Client number of the equipment: 232

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001936 Make: VERLINDE - STAGEMAKER Client number of the equipment: 233

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001939 Make: VERLINDE - STAGEMAKER Client number of the equipment: 236

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 17/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1412001940 Make: VERLINDE - STAGEMAKER Client number of the equipment: 237

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

**Motor-driven hoist** 

Nature : MOTOR-DRIVEN HOIST Serial number : 1412001941 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 238

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001951 Make: VERLINDE - STAGEMAKER Client number of the equipment: 240

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001952 Make: VERLINDE - STAGEMAKER Client number of the equipment: 241

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001956 Make: VERLINDE - STAGEMAKER Client number of the equipment: 243

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist
Nature: MOTOR-DRIVEN HOIST

Serial number : 1412001959

Make: VERLINDE - STAGEMAKER

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

(see next page)

Date of issue: 03/05/2023 Page: 18/49



Client number of the equipment: 245

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1412001961 Make: VERLINDE - STAGEMAKER Client number of the equipment: 246

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002015 Make: VERLINDE - STAGEMAKER Client number of the equipment: 251

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002146 Make: VERLINDE - STAGEMAKER Client number of the equipment: 253

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)
Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002148 Make: VERLINDE - STAGEMAKER Client number of the equipment: 255

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 19/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1413002149 Make: VERLINDE - STAGEMAKER Client number of the equipment: 256

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002154 Make: VERLINDE - STAGEMAKER Client number of the equipment: 261

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002157 Make: VERLINDE - STAGEMAKER Client number of the equipment: 263

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002158 Make: VERLINDE - STAGEMAKER Client number of the equipment: 264

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1413002159 Make: VERLINDE - STAGEMAKER Client number of the equipment: 265

Type: SR10 1004 M1-A

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 20/49



Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002166 Make: VERLINDE - STAGEMAKER Client number of the equipment: 267

Type : SR10 1004 M1-A Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1414002168

Make: VERLINDE - STAGEMAKER Client number of the equipment: 269

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002169 Make: VERLINDE - STAGEMAKER Client number of the equipment: 270

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002171

Make: VERLINDE - STAGEMAKER

Client number of the equipment: 272

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Maximum load : 1000KG Length : 20M

Motor-driven hoist

Type: SR10 1004 M1-A

Year of manufacture: 2014

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002252 Make: VERLINDE - STAGEMAKER Client number of the equipment: 273 (see next page)

Date of issue: 03/05/2023 Page: 21/49



Type : SR10 1004 M1-A \*Conditions and operation inspection (07.2023)

Year of manufacture : 2014 \* Mechanism and structure inspection (04.2024)

Maximum load : 1000KG

Length : 20M

The mate

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002254 Make: VERLINDE - STAGEMAKER Client number of the equipment: 274

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002407 Make: VERLINDE - STAGEMAKER Client number of the equipment: 276

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002414 Make: VERLINDE - STAGEMAKER Client number of the equipment: 279

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002415 Make: VERLINDE - STAGEMAKER Client number of the equipment: 280

Type: SR10 1004 M1-A Year of manufacture: 2014 \* Conditions and operation inspection (07.2023) Not inspected: not presented.

abnormalities were found when inspecting

The material can be used, no

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 22/49



Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002416 Make: VERLINDE - STAGEMAKER Client number of the equipment: 281

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002417 Make: VERLINDE - STAGEMAKER Client number of the equipment: 282

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002418 Make: VERLINDE - STAGEMAKER

Client number of the equipment: 283

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002458 Make: VERLINDE - STAGEMAKER Client number of the equipment: 284

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 23/49



Nature : MOTOR-DRIVEN HOIST Serial number : 1415002463 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 285 Type : SR10 1004 M1-A

Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002464 Make: VERLINDE - STAGEMAKER Client number of the equipment: 286

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002465 Make: VERLINDE - STAGEMAKER Client number of the equipment: 287

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002469 Make: VERLINDE - STAGEMAKER Client number of the equipment: 291

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002470 Make: VERLINDE - STAGEMAKER Client number of the equipment: 292

Type: SR10 1004 M1-A

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 24/49



Year of manufacture : 2014 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002471 Make: VERLINDE - STAGEMAKER Client number of the equipment: 293

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002472 Make: VERLINDE - STAGEMAKER Client number of the equipment: 294

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002476 Make: VERLINDE - STAGEMAKER Client number of the equipment: 295

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1415002488 Make: VERLINDE - STAGEMAKER Client number of the equipment: 296

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 25/49



Nature : MOTOR-DRIVEN HOIST Serial number : 1415002495 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 298 Type : SR10 1004 M1-A

Year of manufacture : 2014 Maximum load : 1000KG

Motor-driven hoist

Length: 20M

Nature : MOTOR-DRIVEN HOIST Serial number : 1413002079 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 300

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1413002081

Make: VERLINDE - STAGEMAKER Client number of the equipment: 301

Type: SR10 1004 M1-A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003513 Make: VERLINDE - STAGEMAKER Client number of the equipment: 303

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003518 Make: VERLINDE - STAGEMAKER Client number of the equipment: 305

Type: SR10 1004 M2-A20 Year of manufacture: 2015 \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 26/49



Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003519 Make: VERLINDE - STAGEMAKER Client number of the equipment: 306

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003520 Make: VERLINDE - STAGEMAKER Client number of the equipment: 307

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003521 Make: VERLINDE - STAGEMAKER Client number of the equipment: 308

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1535003522 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 309

Type: SR10 1004 M2-A20

Date of issue: 03/05/2023 Page: 27/49



Year of manufacture : 2015 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003526 Make: VERLINDE - STAGEMAKER Client number of the equipment: 313

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003527 Make: VERLINDE - STAGEMAKER Client number of the equipment: 314

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003532 Make: VERLINDE - STAGEMAKER Client number of the equipment: 316

Type : SR10 1004 M2-A20 Year of manufacture : 2015 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003533 Make: VERLINDE - STAGEMAKER Client number of the equipment: 317

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 28/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1535003534 Make: VERLINDE - STAGEMAKER Client number of the equipment: 318

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003536 Make: VERLINDE - STAGEMAKER Client number of the equipment: 320

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003544 Make: VERLINDE - STAGEMAKER Client number of the equipment: 322

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003545 Make: VERLINDE - STAGEMAKER Client number of the equipment: 323

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1535003548 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 324

Type: SR10 1004 M2-A20

Date of issue: 03/05/2023 Page: 29/49



Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003550 Make: VERLINDE - STAGEMAKER Client number of the equipment: 326

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003551

Make: VERLINDE - STAGEMAKER Client number of the equipment: 327

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003554 Make: VERLINDE - STAGEMAKER Client number of the equipment: 329

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003555 Make: VERLINDE - STAGEMAKER Client number of the equipment: 330

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003557 Make: VERLINDE - STAGEMAKER Client number of the equipment: 332 (see next page)

Date of issue: 03/05/2023 Page: 30/49



Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003559 Make: VERLINDE - STAGEMAKER Client number of the equipment: 334

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003560 Make: VERLINDE - STAGEMAKER Client number of the equipment: 335

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003564 Make: VERLINDE - STAGEMAKER Client number of the equipment: 337

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003565 Make: VERLINDE - STAGEMAKER Client number of the equipment: 338

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 31/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1535003568 Make: VERLINDE - STAGEMAKER Client number of the equipment: 339

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003569 Make: VERLINDE - STAGEMAKER Client number of the equipment: 340

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003574 Make: VERLINDE - STAGEMAKER Client number of the equipment: 342

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023)
- Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024)
  Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003575 Make: VERLINDE - STAGEMAKER Client number of the equipment: 343

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1535003576 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 344

Type: SR10 1004 M2-A20

Date of issue: 03/05/2023 Page: 32/49



Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003577 Make: VERLINDE - STAGEMAKER Client number of the equipment: 345

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003578

Make: VERLINDE - STAGEMAKER Client number of the equipment: 346

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1535003583 Make: VERLINDE - STAGEMAKER Client number of the equipment: 349

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003603 Make: VERLINDE - STAGEMAKER Client number of the equipment: 352

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 33/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1536003653 Make: VERLINDE - STAGEMAKER Client number of the equipment: 356

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003654 Make: VERLINDE - STAGEMAKER Client number of the equipment: 357

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003664 Make: VERLINDE - STAGEMAKER Client number of the equipment: 358

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003665 Make: VERLINDE - STAGEMAKER Client number of the equipment: 359

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003666 Make: VERLINDE - STAGEMAKER Client number of the equipment: 360

Type: SR10 1004 M2-A20 Year of manufacture: 2015 \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

Date of issue: 03/05/2023 Page: 34/49



Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003685 Make: VERLINDE - STAGEMAKER Client number of the equipment: 361

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003688 Make: VERLINDE - STAGEMAKER Client number of the equipment: 362

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003691 Make: VERLINDE - STAGEMAKER Client number of the equipment: 364

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003692 Make: VERLINDE - STAGEMAKER Client number of the equipment: 365

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist (see next page)

Date of issue: 03/05/2023 Page: 35/49



Report n°: AUD/10/14446288/00/EN

Contract Ref.: 0001011189/22000

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003696 Make: VERLINDE - STAGEMAKER Client number of the equipment: 366

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1536003697 Make: VERLINDE - STAGEMAKER

Client number of the equipment: 367

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

abnormalities were found when inspecting

\* Conditions and operation inspection (07.2023) \* Mechanism and structure inspection (04.2024)

The material can be used, no

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

Conclusion

the material

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003702 Make: VERLINDE - STAGEMAKER Client number of the equipment: 368

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003703 Make: VERLINDE - STAGEMAKER Client number of the equipment: 369

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003704 Make: VERLINDE - STAGEMAKER Client number of the equipment: 370

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M Motor-driven hoist \* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 03/05/2023 Page: 36/49



Contract Ref.: 0001011189/22000

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003705 Make: VERLINDE - STAGEMAKER Client number of the equipment: 371

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1537003717 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 372

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1537003721

Make: VERLINDE - STAGEMAKER Client number of the equipment: 374

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003722 Make: VERLINDE - STAGEMAKER Client number of the equipment: 375

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Motor-driven hoist

Length: 20M

Nature : MOTOR-DRIVEN HOIST Serial number : 1537003724 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 376 Type : SR10 1004 M2-A20 Year of manufacture : 2015

Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist (see next page)

Date of issue: 03/05/2023 Page: 37/49



Contract Ref. : 0001011189/22000

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003727 Make: VERLINDE - STAGEMAKER Client number of the equipment: 377

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003728 Make: VERLINDE - STAGEMAKER Client number of the equipment: 378

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003729 Make: VERLINDE - STAGEMAKER Client number of the equipment: 379

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003730 Make: VERLINDE - STAGEMAKER Client number of the equipment: 380

Type : SR10 1004 M2-A20 Year of manufacture : 2015 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003735 Make: VERLINDE - STAGEMAKER Client number of the equipment: 381

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 38/49



Contract Ref.: 0001011189/22000

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003736 Make: VERLINDE - STAGEMAKER Client number of the equipment: 382

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1537003738 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 384

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003739 Make: VERLINDE - STAGEMAKER Client number of the equipment: 385

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003740 Make: VERLINDE - STAGEMAKER Client number of the equipment: 386

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003741 Make: VERLINDE - STAGEMAKER Client number of the equipment: 387

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist (see next page)

Date of issue: 03/05/2023 Page: 39/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1537003742 Make: VERLINDE - STAGEMAKER Client number of the equipment: 388

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003743 Make: VERLINDE - STAGEMAKER

Client number of the equipment: 389

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Nature: MOTOR-DRIVEN HOIST

Client number of the equipment: 390

Serial number: 1537003744 Make: VERLINDE - STAGEMAKER

Type: SR10 1004 M2-A20

Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003747 Make: VERLINDE - STAGEMAKER Client number of the equipment: 391

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003748 Make: VERLINDE - STAGEMAKER Client number of the equipment: 392

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 40/49



Nature : MOTOR-DRIVEN HOIST Serial number : 1537003751 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 394 Type: SR10 1004 M2-A20

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003752 Make: VERLINDE - STAGEMAKER Client number of the equipment: 395

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003753 Make: VERLINDE - STAGEMAKER Client number of the equipment: 396

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003754 Make: VERLINDE - STAGEMAKER Client number of the equipment: 397

Type : SR10 1004 M2-A20 Year of manufacture : 2015 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1537003757 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 399

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 41/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1537003758 Make: VERLINDE - STAGEMAKER Client number of the equipment: 400

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1537003759 Make: VERLINDE - STAGEMAKER Client number of the equipment: 401

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001288 Make: VERLINDE - STAGEMAKER Client number of the equipment: 402

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001289 Make: VERLINDE - STAGEMAKER Client number of the equipment: 403

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

\* Conditions and operation inspection (07.2023) \* Mechanism and structure inspection (04.2024)

Conclusion

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001302 Make: VERLINDE - STAGEMAKER Client number of the equipment: 408

Type: SR10 1004 M2-A20 Year of manufacture: 2015 Maximum load: 1000KG

The material can be used, no abnormalities were found when inspecting the material

Length: 20M

Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 42/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1613001305 Make: VERLINDE - STAGEMAKER

Client number of the equipment: 411

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001333 Make: VERLINDE - STAGEMAKER Client number of the equipment: 413

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001334 Make: VERLINDE - STAGEMAKER Client number of the equipment: 414

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1613001337 Make: VERLINDE - STAGEMAKER Client number of the equipment: 417

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001341

Make: VERLINDE - STAGEMAKER Client number of the equipment: 421

Type: SR10 1004 M2 A

(see next page)

Date of issue: 03/05/2023 Page: 43/49



Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001344 Make: VERLINDE - STAGEMAKER Client number of the equipment: 424

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001363

Make: VERLINDE - STAGEMAKER Client number of the equipment: 442

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001370 Make: VERLINDE - STAGEMAKER Client number of the equipment: 448

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001371

Make: VERLINDE - STAGEMAKER Client number of the equipment: 449

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

**Conclusion** 

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

Motor-driven hoist (see next page)

Date of issue: 03/05/2023 Page: 44/49



Nature: MOTOR-DRIVEN HOIST Serial number: 1614001373 Make: VERLINDE - STAGEMAKER Client number of the equipment: 451

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001375 Make: VERLINDE - STAGEMAKER Client number of the equipment: 453

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001379 Make: VERLINDE - STAGEMAKER Client number of the equipment: 457

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001382 Make: VERLINDE - STAGEMAKER Client number of the equipment: 460

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

- \* Conditions and operation inspection (07.2023) Not inspected: not presented.
- \* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

(see next page)

# Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1614001385 Make : VERLINDE - STAGEMAKER

Client number of the equipment: 463

Type: SR10 1004 M2 A

Date of issue: 03/05/2023 Page: 45/49



Contract Ref.: 0001011189/22000

Year of manufacture : 2016 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001386 Make: VERLINDE - STAGEMAKER Client number of the equipment: 464

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001387 Make: VERLINDE - STAGEMAKER Client number of the equipment: 465

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

#### Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001389 Make: VERLINDE - STAGEMAKER Client number of the equipment: 467

Type : SR10 1004 M2 A Year of manufacture : 2016 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

# Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001394 Make: VERLINDE - STAGEMAKER Client number of the equipment: 472

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023) Not inspected: not presented.

\* Mechanism and structure inspection (04.2024) Not inspected: not presented.

#### Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

## Motor-driven hoist

(see next page)

Date of issue: 03/05/2023 Page: 46/49



Contract Ref.: 0001011189/22000

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001395 Make: VERLINDE - STAGEMAKER

Client number of the equipment : 473

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001402 Make: VERLINDE - STAGEMAKER Client number of the equipment: 480

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001415 Make: VERLINDE - STAGEMAKER Client number of the equipment: 492

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001419 Make: VERLINDE - STAGEMAKER Client number of the equipment: 496

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1614001421

Make: VERLINDE - STAGEMAKER Client number of the equipment: 498

Type: SR10 1004 M2 A

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

## Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)
Not inspected: not presented.

# Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is required before re-service

- \* Conditions and operation inspection (07.2023)
- \* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting the material

(see next page)

Date of issue: 03/05/2023 Page: 47/49



VINCOTTE

Year of manufacture : 2016 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1614001422 Make: VERLINDE - STAGEMAKER Client number of the equipment: 499

Type: SR10 1004 M2 A Year of manufacture: 2016 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature : MOTOR-DRIVEN HOIST Serial number : 1413002054 Make : VERLINDE - STAGEMAKER

Client number of the equipment : 502 Type : SR10 1004 M2 A Year of manufacture : 2016

Year of manufacture : 20 Maximum load : 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002257 Make: VERLINDE - STAGEMAKER Client number of the equipment: 503

Type: SR10 1004 M2 A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

\* Mechanism and structure inspection (04.2024)

Conclusion

The material can be used, no abnormalities were found when inspecting

the material

Motor-driven hoist

Nature: MOTOR-DRIVEN HOIST Serial number: 1414002258 Make: VERLINDE - STAGEMAKER Client number of the equipment: 504

Type: SR10 1004 M2 A Year of manufacture: 2014 Maximum load: 1000KG

Length: 20M

\* Conditions and operation inspection (07.2023)

Not inspected: not presented.

\* Mechanism and structure inspection (04.2024)

Not inspected: not presented.

Conclusion

The material cannot be used anymore. The material was not available during inspection, or could only be partially inspected, an additional inspection is

required before re-service

# Total of the equipment inspected

89 10396001 Motor-driven hoist

Cond. & Oper.Insp. or Prev.

Date of issue: 03/05/2023 Page: 48/49



Contract Ref.: 0001011189/22000

89 10396002 Motor-driven hoist Mechanism&structure inspection

Total of the equipment not inspected
121 10396001 Motor-driven hoist
121 10396002 Motor-driven hoist Cond. & Oper.Insp. or Prev. Mechanism&structure inspection

Date of issue: Page: 49/49 03/05/2023